



FOREWORD

UPS management and employees contributed to the contents of this book to make it as useful as possible to assist our valued craftsman in their everyday tasks and help them identify hazards on the job. Within it you will find.

- Important Safety Tips
- · Tool Use and Inspection
- · Quality reference and expectations
- Bolt and pipe fitting Charts and Weight References
- Employee Roles & Responsibilities.
- Much more

First and foremost this manual is a reference to assist you in identifying known hazards that exist with tools we have used every day of our professional lives but have not always identified before starting a task. If you truly use the UPS Safety? process of identifying a hazard and eliminating it before starting work. This book will help find hazards that you may have not realized existed or have become complacent to that are associated with a tool you are about to use. Before you begin your work take the time to review those hazards not just in the work area but also with your tools.

You will find inside many reference charts containing information gathered from several different sources that we use daily on the job. Information within has come from many different sources including the Internet, UPS subject matter experts or from our past 30 years of experience collecting useful information to better perform our crafts.

An informed craftsman is a safe craftsman. Please keep this tool handbook as a reference through your entire work day. Refer to it to assist in building a good PHA card, saving steps gathering material, or to answer a simple question about a task.

Your safety is paramount at UPS it is the intent of all our programs to assist you in going home the same way you came to work. This tool manual is one component of that program please read it, use it daily for reference to assist in identifying hazards associated with your job.

TABLE OF CONTENTS

Section 1 : Expectations and	Lockout / Tagout52
Responsibilities	Work Permits53
UPS Leadership Program06	Pneumatic Testing55
Leadership Quotes by	Hydrostatic Testing56
Jocko Willink10	Critical Lift Plan57
Foreman Expectations:	Glove Selection58
Safety ² 11	
Line up List	Section 3 : Tool Use and Inspection
12	Inspection Color Codes60
Quality of Work14	Personal Protective Equipment (PPE) 61
Production 15	HAND TOOLS
Welder Responsibilities	Combination Wrench63
Boiler Maker Expectations	Hammer Wrench64
Crane & Rigging Expectations20	Hand Torque Wrench65
Helper, Fire Watch, Hole Watch	Pipe Wrench66
Expectations23	Hack Saw67
Tool Room Attendant Expectations25	Hand File68
Tower Craft Expectations27	Hammer69
Pipefitter Expectations29	Pry Bar70
	Bull Pin71
Section 2: Important Safety Tips	Socket72
Safey ² Process32	ELECTRIC TOOLS
Stop Work Authority (SWA)	Grinders: Portable Grinders73
Job Safety Analysis (JSA)34	Grinders: Bench Grinders74
Standing JSA35	Saws: Port-a-Band Saw75
UPS Life Saving Rules	Saws: Reciprocating Saw (Sawzall). 76
UPS Safe Work	Saws: Chop Saw77
Commitments37	Saws: Circular Saw78
Fabrication Standing JSA38	Hand Drill79
JSA Acknowledgment Form	Magnetic Drill80
Standing JSA	Pipe Threader81
Example of a JSA Acknowledgment42 The Personal Hazard	Welding Machine82
Assessment (PHA)43	Impact Wrench84
• •	PNEUMATIC AND HYDRAULIC TOOLS
Job-Site Hazards Page45 Hazard Assessment46	Air Torque Wrench85
How to Fill Out a PHA47	Hydraulic Torque Wrench86
Filling Out the UPS Hazard Card49	Air Chisel88
i iiiiig Out tile OF3 Flazaru Caru49	Air Mover89

Jack Stands90	150 lb. Flanges - Inches 138
Cutting Torch 91	300 lb. Flanges - Inches 139
Beveling Machine92	400 lb. Flanges - Inches 140
Port-A-Power94	600 lb. Flanges - Inches14
Come-A-Long and Chain Fall95	900 lb. Flanges - Inches 142
Air Tugger96	1500 lb. Flanges - Inches 143
Section 4 : Quality	150 # English Metric 144
QA/QC Guidelines98	300 # English Metric 145
QA/QC101	400 # English Metric 146
QA/QC: Engineering and	600 # English Metric 147
Construction Codes and Standards 102	900 # English Metric 148
QA/QC: Welding Process Metrology 104	1500 # English Metric 149
Bevel Details	2500 # English Metric 150
Welding Defects	Gaskets: Introduction15
Welder Classification &	Gasket Color Codes: Metallic
Welding Parameters111	Winding Materials 152
Weld Procedure (WPS) Identification . 112	Gasket Assembly, Bolting and
. ,	Compression 154
	Bolt Sequence for Proper Torqueing. 155
Section 5 : Charts and Weight	Section 4 (continued
References	Bolt Torque Data:
Decimal Equivalency Chart114	Torque Table for Class 150 Flange 156
Drill Sizes for Bolt Taps115	Torque Table for Class 300 Flange 157
Drill Sizes for Pipe Taps and	Victor Oxygen & Acetylene Cutting
Thread Length	Pressure & Tip Chart 158
Valve and Fitting Dimensions	ANSI Bolting Chart:
150 # RF Piping Dimensions	<i>V</i> ₂ " – 4"
300 # RF Piping Dimensions119	5" – 24"
600 # RF Piping Dimensions121	Weld-o-Lets
900 # RF Piping Dimensions 123 1500 # RF Piping Dimensions 125	ASTM Material Codes 164
900 # RJT Piping Dimensions 127	
1500 # RJT Piping Dimensions 129	
Screwed Fittings	
Tee's and Reducers 134	

FLANGE CHARTS

OTHER TOOLS

Section 6 : Rigging and Crane
Rigging Signals166
Crane & Rigging Qualifications 168
Rigging Signals: Common Safety for
Crane Operation169
RIGGING INFORMATION
Risk Management 170
Inspection of Slings172
Wire Rope Sling Connections
and Hitches 173
Chain Sling Connections
and Hitches174
Synthetic Sling Connections
and Hitches 175
Center of Gravity, Weights
and Measures 176
Single Angle Information 177
ASME B30.9 Operating Practices
and Load Control178
Block Concepts 179
Working with Blocks180
Rigging Blocks181
Block and Sheave Inspection 182
Block Hook Inspection 183
SCREW PIN SHACKLES
G-209 & S209 Style Screw Pin
Anchor Shackles 184
G-210 & S210 Style Screw Pin
Chain Shackles 185
Bolt Chart Quick Reference Guide187



UPS LEADERSHIP, EXPECTATIONS & RESPONSIBILITIES

Leadership: The most important factor in building, training, and developing high performing teams

Team: A group of individuals working together to accomplish a mission, project, or task

Leader: A Leader develops effective interpersonal relationships that makes others want to follow his or her direction. A leader leads by example

Leadership has nothing to do with seniority, position or hierarchy within a company.
Leadership isn't management. Leaders build relationships and accomplish goals, whereas managers build systems and processes.

At UPS, the only meaningful measure for a leader is whether the team succeeds or fails. For all definitions, descriptions, and characterizations of leaders there are only two that matter: effective or ineffective. The UPS Leadership Program focuses on practices and personal character traits that make effective leaders. The purpose and intent of this program is to develop and improve leadership skills in each of our supervisors and employees to further develop high performing teams within UPS. Leadership applies to everything we do.

The Following are Base Leadership Principles for UPS Leader

- Relationships: The ability to make, build, create or improve relationships is the single most important leadership principle. You cannot lead, influence or inspire anyone that you do not have a relationship with.
- Integrity: Integrity means doing the right thing because it is the right thing to do. The quality of having strong moral principles that you refuse to compromise or change. Integrity is the supreme quality of leadership; without it, no real success is possible.
- Humility: Ego is your opinion of yourself; your feeling about your level of ability, Intelligence and your importance as a person. "Checking

- your ego" demonstrates a leader's ability to take charge of himself: it is managing the negative aspects of your ego.
- Self Assessment: Self-assessments are a continuing process through which leaders evaluate their performance and determine what improvements are required. Ego is the biggest obstacle for a leader in performing self-assessments. A "brutally honest" assessment of your own performance is essential for leadership development and improvement.

Extreme Ownership is the Foundation of the UPS Leadership Doctrine

- You accept responsibility of the mission or job and you are responsible for the performance of your team and the outcome of the mission or job. Blame shifting is not an option.
- You own everything that affects your job: every success, every failure, every problem and every solution. Just by simply saying something is your fault does not mean you have taken ownership of the problem. You must provide a solution to solve the problem.
- Ultimately, Extreme Ownership is about you. You step up and make the change in behavior instead of expecting others to change - you accept that you can do better.
- Extreme Ownership starts with you and it spreads to each team member until Extreme Ownership becomes the new standard or culture within your team.

4-Laws of Combat are the fundamental Principles of the UPS Leadership Doctrine

- Cover and Move: Cover and Move is teamwork. Not just teamwork within your group but establishing teamwork with all groups necessary to complete the mission or job.
- Simple: Keep plans simple, not complex. If you get into a situation where
 things are complex, stop and simplify the plan. It is important that your
 people understand the plan, they know their assignments and understand
 the "why". Once you have communicated the plan, ask your team members
 to explain it back to you.
- Prioritize and Execute: In a turnaround environment, priorities shift and situations develop that can sometimes become overwhelming. As a leader, you need to analyze the situation, respond and move to the next priority. Do not become fixated on one priority (target fixation) and lose the ability to see other developing problems. It is important to remain calm and make good decisions under pressure.
- Decentralized Command: Basically, leaders at all levels (Project Managers down to Foreman) are empowered to lead in key tasks necessary to effectively complete the job. Junior supervision must understand the end goal and the "why" to attain that goal; they also need to know the limits of their authority.

Default Aggressive Mindset

As a leader you must make things happen, you cannot sit on problems or issues and do nothing; all decision making is wasted time if you don't act. An aggressive mindset and the act of moving forward will yield the best result and will often improve your odds for success: it also means you are taking ownership.

Taking Care of your People

- Taking care of your people is about making them better and holding them to high standards.
- Providing them honest assessments and feedback.
- Teach them so they can be more proficient in their jobs.
- Giving them ownership.
- You can't be a friend first and a leader second.
- You can't accept sub-standard performance.
- You must hold your people accountable for their actions.

3-Reasons Why Your Team is Failing

- You have not explained to your team what they need to do, how they need to
 perform and "why" they are doing what you are asking. Many times, this is
 a result of miscommunication or a lack of communication from you. Once
 you have communicated your plan, you should have each team member
 explain it back to you to ensure the plan is understood and the "why" is
 defined.
- You have not provided or there is not adequate support for your team (logistics, tools, materials, procedures, etc.). Support may not always be in your control, but you must look ahead and be diligent to make sure those in control of your support are aware of your needs and the needs of your team.
- You have not held team members accountable or terminated team members for substandard performance. Quite often a leader will add a friend or family member to their team but will not hold those members fully accountable due to the personal relationship they share. A leader cannot make his team better if he does not hold all team members to equivalent standards.

Individual Leadership Development

The leadership principles listed are highlights of the UPS Leadership Program. Now that you have read these where do you go from here?

Build on these principles - become a better leader.

Here are a few suggestions:

- Find a Mentor (all Great Leaders have Mentors).
- Step back and take a "brutally honest" self-assessment. Make a list of areas to improve and start working on them.
- Read, there are many books on leadership that are great reads.

"Don't just read.

Don't just take notes.

Don't just get motivated.

Don't just talk.

The only thing that matters is that you actually do.

So: DO" — Jocko Willink

SECTION 1: EXPEXCIATIONS AND RESPONSIBILITIES

FOREMAN EXPECTATIONS Safety²

- Foremen are responsible for making and keeping safety the number one priority of the job.
- · Stay in constant communication with your crew.
- Make sure to have an accurate head count; you should always know where your employees are in case of emergency.
- Maintain a good attitude and respect everyone. Provide encouragement and positive support.
- Think! Look at the work, the environment and the situation. If a situation doesn't seem safe, stop work and make it safe. There is no substitute for common sense and thinking.
- Use your and employee's Stop Work Authority any time something doesn't seem or feel safe.
- Support an employee's decision to be safe and defend their efforts to be proactive.
- You are accountable for the decisions and actions of your crew. If someone decides to perform an unsafe act or violate any policy, it is a reflection of your priorities and leadership.
- · All foreman and crew must attend daily safety meetings.
- Make sure all employees follow the unit entry and exit procedures, signing in and out as required.
- Review permits with crew and make sure everyone knows what work is authorized under the permit and what PPE is required on the permit.
- · Make sure permits are closed out upon completion.
- The JSA must be reviewed with the entire crew. Make sure no one starts work without
 the JSA and PHA being signed and be sure all JSAs and addendums are completely and
 properly filled out with correct date before signing.
- If the task changes or a new crew member joins the team then the JSA and PHA must be reviewed and updated.
- Foremen are expected to actively and personally participate and promote the Observation process, either UPS Hazard Card or an equivalent client safety audit process.
- Ensure that proper tools are available and used on a job; do not allow any tools to be altered or the guards removed!
- Do not let anyone operate any equipment without having verified their proper training and qualification, license, or certification.
- · Make sure employees on your crew have all the required PPE on them at all times.
- Ensure that housekeeping is an ongoing process. You are expected to keep your work area safe and clean.
- Do not assume Operations has inspected the work area simply because they issued
 a permit. Do not trust a permit merely because it is signed. Make an independent
 assessment of the conditions and the wor and raise issues with Operators.
- MAINTAIN SAFETY AT ALL LEVELS!

FOREMAN EXPECTATIONS Line up List

Foreman instructions on how to line up your crew at the first of the job.

You are responsible for ensuring that work is done right the first time.

- Talk personally to each crew member briefly just to make sure they are ready for a day's
 work and get to know them better as a person. If they have a connection to you, they will
 want to do what makes your team look good and perform well.
- Safety meeting times and that they are not an option and a meeting place to gather each morning afterwards.
- Call in numbers and names of who to contact if they are not going to be in that day, with the expectation if they do not call, we have option to terminate.
- Brief talk about what they were hired for and the quality we expect when completing the
 task of the day. Review what the paperwork is required when we complete a task and
 who it goes too.
- Make sure they understand who they report too and if you move them to another crew have the conversation with the new supervisor and employee.
- Review every day the stop work authority and reinforce it when you are doing your daily
 walk with your team and review their individual PHA cards for quality identification of a
 hazard associated with the task at hand.
- Review and reward those that found and reported a good safety mitigation.
- Explain your expectations for how the job will be carried out that does not include the
 details on how to do the work. Talking only about the work sends a message that only
 the work is important. How the work is performed is the last part of the lineup.
 - Keeping work area clean and orderly materials organized and trash disposed of and someone assigned to keeping the area clean.
 - Explain how the PHA should be filled out and any safety issues that were brought up in the earlier meeting and how those apply to the job they are about to start.
 - Go over quality expectations on how the final bolt up should look or that they should call for a double check before the cut is made, leave a window for inspection to view the root pass before closing, take the time to go over the relevant, direct information in the package they should know...bolt spec, gasket spec, material type and rating. Not trusting they read it on their own
 - Go over a plan on where to meet if there is an evacuation.
 - Expectations for staying on track when you are not there watching.
 - Taking the time to read through a permit with the crew before they start work so they all know what's on it and understand it.
 - Review PPE requirements with the FW/Entry attendant and how you expect that person to look out for your people.
 - Assign each one to a task that involves the team's success, one guy is in charge
 of inspecting the scaffold and making sure its updated, one guy is in charge of
 barricades, another in charge of housekeeping ECT....

FOREMAN EXPECTATIONS Line up List

When bringing in a new crew member onto an in-progress project:

Bringing in a new person to a crew that's in the middle of a job has been a historically hazardous situation. It's very important that each person should get the same instructions no matter when they enter into the job.

- Review the same requirements you went over with your crew with the newly added craftsman.
- Make sure he knows where the permit is and has read it the same as the rest of the crew
- Explain your objectives for his performance while on your crew
- Share the same quality hold points with them as you did the original crew.
- Explain to them who is in charge when you're not at the job and who is the senior member of the crew.

Since our work constantly changes as a day progresses make this situation a good time to pull the entire crew back together and revisit the PHA, Standing JSA and addendum to make sure they are still accurate for where you are now.

SECTION 1: EXPEXCTATIONS AND RESPONSIBILITIES

FOREMAN EXPECTATIONS Quality of Work

High quality work is one of the main reasons UPS Industrial Services continues to keep getting work. The quality of our work has a direct effect on safety and cost to the job. If work isn't done right the first time, we increase the chance of an injury or accident, and certainly increase the cost of the job due to rework.

- · You are responsible for ensuring that work is done right the first time.
- Ensure that you have the right person on each job, with skills, certification, training and experience matched to the task.
- Follow UPS Industrial Services tagging and flange management system and do not remove any spools without having tags on them first.
- · Make sure that all flanges are inspected for defects as soon as flanges are separated.
- Verify proper fit-ups.
- Make sure you have seen the applicable welding procedure before welding on ANYTHING. Ensure that the welder is qualified to weld on what they are about to weld.
- · Make sure welding rod slips are being used on every job.
- Verify that the flanges have the correct bolts and gaskets that meet the specifications required.
- Make sure to use proper torque specs, and verify those specs to your work plan.
- · Ensure that torque tags are hung with all of the required information .
- Make sure that the crew uses the proper handling and bolt up procedures with any
 plastic or fiberglass pipe or cast iron valve body flanges.
- Make sure that items are cleaned out or washed as soon as possible to prevent any damage to equipment or items.
- Ensure that any equipment that is unbolted from its position is properly tagged before going to the wash slab.
- Follow the UPS Industrial Services material management system in the QC Manual.
- Inspect jobs and be sure they are correct and complete before calling for Inspection to QC job.
- TAKE OWNERSHIP OF QUALITY!

SECTION 1: EXPEXCIATIONS AND RESPONSIBILITIES

FOREMAN EXPECTATIONS Production

- Everyone is expected to show up on time and be at work every scheduled workday.
- Make sure every employee sign in and sign out, identifying proper times.
- Ensure your crew knows to call in if they are going to be late or call in prior to start of shift
 if they will not be showing up that day.
- You need to make sure your crew is as efficient and productive as possible.
- You are expected to plan work properly and keep crews working at a steady pace.
- Make sure your crews' transition from the safety meeting to their pre-job processes promptly getting permits, tools. [SA, etc.
- It is an expectation that UPS Industrial Services tools and equipment will be taken care of
 properly. You are expected to take immediate action to prevent or stop misuse of tools.
- All tools will be checked back in at the end of every shift unless approved by supervision.
- Make sure job packages are on site at every job for employees to review including weld procedures.
- Do the job safely and in the most efficient way possible. If you identify a better method
 than the work plan, get management approval (and client if necessary) before starting a
 new plan.
- Ensure your crew knows that they should not take direction from anyone except you, and you should not take direction from anyone except your supervisor.
- Understand and follow the work list or schedule; stay in contact with the coordinators and / or supervision.
- · Update the schedule or work list accurately.
- Foremen are expected to be in the field with their crews at all times.
- Shift roll-overs will be done usually 1 hour before each shift. All Supt., GFs, Foreman, and Safety Leads need to be there, and logbooks updated at shift change.
- · Shift roll-overs between foremen are expected.
- Foremen are expected to fill out delay slips thoroughly and accurately, and to turn the slips in to their GFs at the end of shift.
- · Always conduct yourself as a professional.

WELDERS RESPONSIBILITIES

The following is a list of expectations that are required of each employee that is working as a Welder for UPS Industrial Services.

Wear appropriate safety equipment as requipment as fellow the Safety Mitigation Process Follow the Safety2 process Follow Stop Work Authority Process as necessary as the safety and properly preparative and particular and particular and particular and particular and particular and process as necessary and properly preparative and particular and particular and process as necessary and properly preparative and particular and process as necessary and properly professional Follow appropriate chain of command on sit own your actions good or bad (Extreme Ow Take pride in your work and that of your tear welds may only weld in the process (es) for The first two (2) production butt welds are swelds including socket welds may be subject inspect all welds. Rejected welds will be regular and processary and	ired per tasks
Safety Follow the Safety² process Follow Stop Work Authority Process as nece All heat affected zones to be properly prepare Always use fire blanket and barricades for p Always connect ground to the work piece ye ground needs to be a minimum of 18" Show up to work as scheduled on time event Show up prepared with all your equipment/ Treat others as you expect to be treated (50 Follow appropriate chain of command on sit Own your actions good or bad (Extreme Ow Take pride in your work and that of your test Welders may only weld in the process (es) for The first two (2) production butt welds are s welds including socket welds may be subject inspect all welds. Rejected welds will be reg	
Safety Follow Stop Work Authority Process as nece All heat affected zones to be properly prepare Always use fire blanket and barricades for p Always connect ground to the work piece ye ground needs to be a minimum of 18" Show up to work as scheduled on time event Show up prepared with all your equipment. Treat others as you expect to be treated (Go Follow appropriate chain of command on sit Own your actions good or bad (Extreme Ow Take pride in your work and that of your tear Welders may only weld in the process (es) for The first two (2) production butt welds are s welds including socket welds may be subject inspect all welds. Rejected welds will be reg	
All heat affected zones to be properly preparations and that of your team Always use fire blanket and barricades for p Always connect ground to the work piece your ground needs to be a minimum of 18" Show up to work as scheduled on time every show up prepared with all your equipment. Treat others as you expect to be treated (Go Follow appropriate chain of command on sill that provided in your very more provided in your work and that of your team Welders may only weld in the process (es) for the first two (2) production butt welds are swelds including socket welds may be subject inspect all welds. Rejected welds will be regressed.	
All heat affected zones to be properly preparations of the work piece yield and barricades for particular and particades for particular and particades for particular and p	ssary
Always connect ground to the work piece yr ground needs to be a minimum of 18" Show up to work as scheduled on time every sional Freat others as you expect to be treated (50 Follow appropriate chain of command on sill be provided by the process of the process (es) for the first two (2) production butt welds are simple welds including socket welds may be subject inspect all welds. Rejected welds will be reg	red before welding.
ground needs to be a minimum of 18" Show up to work as scheduled on time every sional Treat others as you expect to be treated (Go Follow appropriate chain of command on sit Own your actions good or bad (Extreme Ow Take pride in your work and that of your tear Welders may only weld in the process (es) for The first two (2) production butt welds are s welds including socket welds may be subject all welds. Rejected welds will be reg	ersonnel and equipment protection.
Professional Show up prepared with all your equipment. Treat others as you expect to be treated (Go Follow appropriate chain of command on sit Own your actions good or bad (Extreme Ow Take pride in your work and that of your tear Welders may only weld in the process (es) for The first two (2) production butt welds are so welds including socket welds may be subject inspect all welds. Rejected welds will be reg	ou are welding to. Near equipment
Show up prepared with all your equipment. Treat others as you expect to be treated (Go Follow appropriate chain of command on si Own your actions good or bad (Extreme Ow Take pride in your work and that of your tear Welders may only weld in the process (es) for The first two (2) production butt welds are s welds including socket welds may be subject inspect all welds. Rejected welds will be rep	/ day
Follow appropriate chain of command on sit Own your actions good or bad (Extreme Ow Take pride in your work and that of your tear Welders may only weld in the process (es) for The first two (2) production butt welds are s welds including socket welds may be subject inspect all welds. Rejected welds will be reg	tools as expected
Leadership Own your actions good or bad (Extreme Own Jake pride in your work and that of your tear Welders may only weld in the process (es) for The first two (2) production butt welds are s welds including socket welds may be subject inspect all welds. Rejected welds will be reg	lden Rule)
Ship Own your actions good or bad (Extreme Ow Take pride in your work and that of your tear Welders may only weld in the process (es) for The first two (2) production butt welds are s welds including socket welds may be subject all welds. Rejected welds will be rep	e and in work area
Welders may only weld in the process (es) for The first two (2) production butt welds are s welds including socket welds may be subject inspect all welds. Rejected welds will be rep	nership)
The first two (2) production butt welds are s welds including socket welds may be subject inspect all welds. Rejected welds will be rep	n
welds including socket welds may be subjectinspect all welds. Rejected welds will be rep	r which he/she is qualified.
All welds are to be stenciled with assigned wel	ct to x-ray. A QC inspector will visually
7 iii Welabare to be sterreiled Will designed Wel	ders stencil in an appropriate visible place.
Fill out Rod Issue Forms correctly with application material annotated	cable approvals and proper filler
Welders need to review and verify the weld the start of welding.	procedure for their specific job, before
All welds will be free of slag, splatter balls, a completion of the weld.	rc strikes and must be brushed at
Quality Excessive weld reinforcement on (ROOT, CA	AP OR CROWN) is unacceptable
There will be no mixing of filler material in co	ontainers or portable rod caddies.
All E70XX, 80XX, and 90XX electrodes w which will be plugged in at all times (NO	
Arc marks and undercut are at zero tolerand 'ringed' with a file or saw blade!	e. (NO EXCEPTIONS). No weld shall be
Completely grind off all fit-up dogs flush wit the surface of the base metal, THIS MEANS I HAMMERS!!! Repairs of base metal defects QA/QC without exceptions.	NO KNOCKING OFF DOGS WITH
No extra work should be performed withou	t propor approval

WELDERS RESPONSIBILITIES

EXPECTATION		
Work Know- ledge	Proper preheat and inter-pass temperatures will be maintained at all times.	
	Socket welds will be a full fillet with a minimum of two (2) passes. Socket welds must have a minimum of $1/16''$ and a maximum of $1/4''$ gap before welding.	
	All 51/2" and under diameter open butt welds will be made using GTAW (UNLESS OTHERWISE NOTED)	
	Stainless steel and E6010 electrodes are not permitted in rod caddies/ovens	
	All welding filler materials, containers, or portable rod caddies will be returned to the rod room at the end of each shift (NOT LEFT IN THE FIELD OR GANG BOX)	
	Welders will use stub buckets for used electrodes, (strictly enforced).	
	All stencil markers, gloves, lenses, temp sticks, etc. furnished by Universal Plant Industrial Services Items will be replaced only with exchange items.	

BOILER MAKER EXPECTATIONS

The following is a list of expectations that are required of each employee that is working as a Boiler Maker for UPS Industrial Services.

	EXPECTATION
Safety	Wear appropriate safety equipment as required per tasks
	Follow the Safety Mitigation Process
	Follow the Safety ² process
	Follow Stop Work Authority Process as necessary
Profes-	Show up to work as scheduled on time every day
	Show up prepared with all your equipment/tools as expected
Sioriai	Treat others as you expect to be treated (Golden Rule)
	Follow appropriate chain of command on site and in work area
Leader-	Own your actions good or bad (Extreme Ownership)
ship	Take pride in your work and that of your team
	No extra work should be performed without proper approval
	Tighten flanges to specifications without having someone come back and tighten loose bolts
	Joint alignment - should have even gap all around no high low
	Joint alignment - bolts should be uniform with bolts having at least 1 thread outside of nuts (site requirements may vary on this ensure you get clear expectation from your supervisor)
	Joint alignment – nuts should have stamped side out
Flange	Joint alignment – all bolts should be tight with no loose nuts
Make- up	If bolts have to be cut, always ensure to cut them from one end and leave stamped end for identification
	Spiral wound and metal gaskets have sharp edges and must be handled with Kevlar gloves
	Removing/Installing – Gaskets/Blinds – only 1 less than half of the bolts need to be removed from pipe flange
	Removing/Installing – Gaskets/Blinds – Inspect all gasket sealing surfaces for damage prior to making back up
	Anti-Seize – ensure that you follow client requirements on application specifications
	Impact Wrench – personally inspect all wrenches
	Impact Wrench – ensure sockets are free of cracking or damage that could cause breakage
	Impact Wrench – ensure correct size retainer rings in place used every time
Tool Use	Face Shields are to be worn and down every time you are using impact or torque wrench
	Clear water from air hoses by blowing them down when connected to a compressor prior to use
	House cleaning - Use proper pins with hoses in use, and roll up hoses when not in use

BOILER MAKER EXPECTATIONS

EXPECTATION		
	Hoses – know the differences, colors, fittings, use and client requirements	
Tool Use	Hoses – Red – air and water – crows foot or cleco (sometimes clients don't allow red for water	
	Hoses – Yellow – nitrogen – Chicago, black – steam hammer union	
	Hoses – Blue – water – crows foot or cleco	
	Harness – If you leave the ground for work have a harness on or with you for easy accessibility.	
	Know the difference between a valve that has flow direction and one that does not (common directional valves include check valve, globe valve and control valve)	
	Installing Flow Directional Valves – ensure that you have checked with your supervisor or operational contact for flow direction of product line	
	Must know the parts to an exchanger (ask your supervisor if you have any questions)	
	Know the difference between removable tube bundle exchangers and fixed straight tube condensers	
	Know the difference between removable straight tube and U-tube bundles	
	Know that unless a client request, bell heads on a straight tube bundle with no split rings do not have to be removed	
	Know how to install gaskets and heads on an exchanger	
	Know that grafoil tape is not necessary for gasket seal	
	Know what tapered plugs are and when to use them	
	Know how to hook up and hydro exchangers and detect leaks (shell and tube side)	
Work Knowl- edge	Know how to hook up, drain, and hydro a test piping system – always open a high point bleed to drain any hydro test	
cugc	Never hydro through a control valve unless client request and signed off on the procedure	
	Know when to remove internals on check valves for hydro and have a check list with the quality department to insure they are reinstalled prior to turning line over to client operations	
	When removing PSVs or control valves, inlet and outlet flanges have to be covered with blinds, plastic, or temporary spool while awaiting reinstall (client requirements vary)	
	Always transport a relief valve in the upright position	
	Never lay a RV on its side	
	You must be fit tested to wear and use fresh air equipment (5 and 30 minute packs)	
	Teflon Tape - Know the proper application to threaded fittings	
	Pipe unions – know that they are flow directional and ensure to have the direction of flow prior to installation.	
	Must understand and be able to use basic rigging hand signals for signaling a crane	
-		

CRANE & RIGGING EXPECTATIONS

The following is a list of expectations that are required of each employee that is working Crane & Rigging for UPS Industrial Services. The mechanical and piping groups do a lot of their own rigging here at UPS IS and we need to help them along the way. Take pride in every lift you make. If you are lifting a load and it takes you 20 times to get it right, then that is what must be done.

	EXPECTATION
	Wear appropriate safety equipment as required per tasks
Safety	Follow the Safety Mitigation Process
	Follow the Safety ² process
	Follow Stop Work Authority Process as necessary
	You must never override or alter any safety device in any crane.
	You must mitigate any equipment issue prior to using it for rigging.
	Documentation from a medical officer or official will be required if you missed for a medical reason.
	Show up to work as scheduled on time every day
	Take Pride in your work, do your job right the first time, when you leave your job site leave it better than you found it.
Profes-	Show up prepared with all your equipment/tools as expected
sional	Treat others as you expect to be treated (Golden Rule)
	Managing your time is key to your success
	You must show up when scheduled to work. You will be terminated if you have 2 unexcused absences or more.
	You will be considered absent if you have 2 late arrivals or 2 early outs.
	Follow appropriate chain of command on site and in work area
	Own your actions good or bad (Extreme Ownership)
	Take pride in your work and that of your team
Leader- ship	It is mandatory to complete an inspection on all equipment that you will be operating on prior to use: cranes, forklifts, aerial lifts, and scissors.
	Document your equipment inspections on an inbound inspection sheet before using the equipment.
	Document your equipment inspections on outbound inspection sheet when returning the equipment to client or rental company once job is complete.
	Turn in inspection sheets to the Safety Department upon job completion
	No extra work should be performed without proper approval
Re- spect	We believe that UPS representatives should always be considerate, respectful and curteous to all persons. This belief applies regardless of what your job title may be. We ask that you treat others the way you would want to be treated.

CRANE & RIGGING EXPECTATIONS

EXPECTATION	
Rela- tion-	A lot of our business comes from the relations we have with our clients. We ask that you maintain a positive attitude. $ \label{eq:positive}$
	Don't burn bridges with pettiness.
ships	Our approach, attitude and performance are trust builders and trust is the number one influencing factor to the success of any relationship
	You must maintain the 3 Ring Binder that was issued to you by Crane & Rigging Manager
Paper- work	The binder will have at a minimum: UPS Crane & Rigging Policy, daily crane inspections, and lift plans. Binder will contain the client Crane & Rigging material if mandated by client, along with their lift plans and documentation that will be required to work at that particular facility
work	Ensure that you conduct a thorough inspection of cranes prior to use and if you find any issues address it immediately at the beginning of the shift
	Red tag cranes that are inoperable until applicable repairs have been completed and verified
Daily	It is a requirement to do a proper inspection at the beginning of each shift. If there is a problem with the equipment, it needs to be addressed immediately.
Inspec- tions	If the equipment needs repair, we will red tag the machine and take it out of service until the equipment is fixed and verified. We will not override the "turn the key" or alter any safety device on any crane at any time.
In-	We will inspect every piece of equipment (cranes, forklifts, Aerial lifts, and scissor lifts) that we receive on every job prior to putting it to use.
bound/ Out- bound	We will document these inspections on an inbound inspection sheet before using it and we will do an outbound inspection when we are returning the equipment to the client or rental company once the job is complete
Inspec- tions	At the end of the job all of this documentation will be turned over to the safety department
	You must use a ratchet strap and or secure every load that you haul
	You must complete an inspection on the forklift prior to use
Fork- lifts	Your forklift will be equipped with a minimum of one $2^{\prime\prime}$ ratchet strap prior to moving any load.
	YOU MUST NEVER USE RIGGING OVER OUR FORKS TO LIFT EQUIPMENT
	If chokers are involved, we will use an engineered lifting device only

CRANE & RIGGING EXPECTATIONS

EXPECTATION		
Com- pensa- tion	Pay rates and classifications vary depending on the contract we are working under. $ \\$	
	It needs to be understood that if you hire in with a ll of the required certifications, but you do not have the experience we are looking for, you may be removed from the project or your wages may change according to your skill set.	
	UPSIS rigging techniques will be utilized at all times	
	You must use Shackles on all chokes	
Rigging	You must use Softeners on all sharp edges	
	You must use steel rigging on beams	
	You must use nylon rigging on all painted surfaces, and steel on any valve over ten inches for example	
	You must use taglines on all single crane picks, barricades with tags are mandatory and will be put up around lift area if spotters are not available	
	You must use the proper rigging for the lift. It must be inspected and in good working condition every time.	
	Anytime there is any doubt we need to stop everything until all concerns are addressed and mitigated properly.	

HELPER, FIRE WATCH, HOLE WATCH EXPECTATIONS

The following is a list of expectations that are required of each employee that is working as a Helper for UPS Industrial Services. Your job as a helper is not only to help in any capacity that you are asked but also to learn each area that you are assigned to. Our expectations of Helpers is that this will only be your first step towards a career with UPS.

EXPECTATION		
	Wear appropriate safety equipment as required per task.	
	Follow the Safety Mitigation Process	
	Follow the Safety ² process	
Safety	Follow Stop Work Authority Process as necessary.	
	You must be able to carry your own assigned tools and fire extinguisher to be assigned as a helper with UPS.	
	You must know what you are required to do with a permit and JSA	
	Show up to work as scheduled on time every day	
	Take Pride in your work, do your job right the first time, when you leave your job site leave it better than you found it.	
	Show up prepared with all your equipment/tools as expected	
Profes-	Treat others as you expect to be treated (Golden Rule)	
sional	Managing your time is key to your success	
Signal.	While assigned on a project it is imperative that you are dependable. Days off are rarely approved while on projects.	
	You must let your foreman know where you are at all times. There will be times when you are asked to help in other areas that you were originally assigned. Ensure you update your foreman when this occurs.	
	Follow appropriate chain of command on site and in work area	
Leader- ship	Own your actions good or bad (Extreme Ownership)	
	Take pride in your work and that of your team	
	No extra work should be performed without proper approval	
Work Knowl- edge	You must have a general knowledge in our craft groups: Piping, Mechanical, and Towers. Ensure you ask your foreman to review these with you.	
	Helpers are expected to be versatile and work as helpers, entry attendants, firewatch, bottle watch, and basically in any capacity that your assigned foreman finds prudent.	
	A main part of your job is to assist with project house cleaning—you must be willing to aid as requested but also do it without being asked.	

HELPER, FIRE WATCH, HOLE WATCH EXPECTATIONS

EXPECTATION		
	Know the procedures to take tools out of service. Ask your foreman if you have any questions.	
	Know how to setup a job using pneumatic tools and not have chords, hoses, or welding leads in walk ways. Attention should be made not to create tripping hazards.	
	A seasoned UPS helper will know how to identify the different types of Flanges.	
Helper	A seasoned UPS helper will know how to identify the different types of Unions.	
Know-	You must have general knowledge on tools that we use in our industry.	
ledge	You must become familiar with UPS tool coloring codes. Ask your foreman to provide.	
	You must inspect your tools at a minimum when you initially check the tool out from the tool room and at the job site prior to tool use.	
	You must know how to determine if an electrical cord or equipment is serviceable.	
	You must be able to read a measuring tape	
Fire- watch Know- ledge	Know how long to stay at your assigned site after cutting/welding has completed	
	Know what to do if the Plant Alarm sounds. Ask your foreman if you are not clear on this.	
	You must know how to monitor a confined space: entry/exit procedures and documentation	

TOOL ROOM ATTENDANT EXPECTATIONS

The following is a list of expectations that are required of each employee that is working as a Tool Room Attendant for UPS Industrial Services. The importance of the tool room position is often underestimated. A good Tool Room Attendant can significantly affect loss prevention, productivity, and profitability of a project if you follow the following.

	EXPECTATION
Safety	Wear appropriate safety equipment as required per tasks
	Follow the Safety Mitigation Process
	Follow the Safety ² process
	Follow Stop Work Authority Process as necessary
	Show up to work as scheduled on time every day
Profes- sional	Treat others as you expect to be treated (Golden Rule)
3101101	Managing your time is key to your success
	Follow appropriate chain of command on site and in work area
Leader-	Own your actions good or bad (Extreme Ownership)
ship	Take pride in your work and that of your team
	No extra work should be performed without proper approval
	You must keep your tool room organized free of any clutter. Dirty tool rooms are a negative reflection to our client and all others who see our tool rooms.
	Maintain adequate inventory of tools and consumables in stock
	Ensure you are communicating to field supervision on the status of missing tools
Tool Room	Loss prevention is a major part of your daily routine and you must make every effort to recover missing tools throughout the day.
	All tools including rental tools should be stored in the tool room (with the exception of tools that are too large). Rental tools are treated as our own and should be signed in/out.
	It is your responsibility to conduct inspections of any UPSIS employee tool box entering and leaving the job site.
	It is your responsibility to ensure that UPSIS Employee's personal tool box do not contain unsafe or homemade tools onto the job site.
	It is your responsibility to inspect personal tool box of personnel that have been released from the job site ensuring that all UPSIS tools and equipment are not present.

TOOL ROOM ATTENDANT EXPECTATIONS

EXPECTATION		
Tool Mainte- nance	Ensure that you conduct daily inspections on tools that enter and come back in to the tool room.	
	Tag and remove tools that are not serviceable and document appropriately.	
	Ensure you follow manufacturer's specific checks of the following: Electrical tools, rigging, fall protection, pneumatic tools, and certain hand tools.	
	Ensure you maintain required color coding of tools, chords, and harnesses.	
Job Close- out	Make sure all non-billables are replaced prior to returning the trailer to the shop.	
	Prepare the Tool Room for return to the shop in the same or better shape than when you were assigned to the tool room.	

TOWER CRAFT EXPECTATIONS

The following is a list of expectations that are required of each employee that is working as a Tower Craft for UPS Industrial Services.

EXPECTATION		
Safety	Wear appropriate safety equipment as required per tasks	
	Follow the Safety Mitigation Process	
	Follow the Safety ² process	
	Follow Stop Work Authority Process as necessary	
	Working in Confined Spaces adds another level of hazards to your work environment. You must keep in mind and apply all Confined Space Safety Practices	
Profes-	Show up to work as scheduled on time every day	
	Take Pride in your work, do your job right the first time, when you leave your job site leave it better than you found it.	
	Show up prepared with all your equipment/tools as expected	
	Treat others as you expect to be treated (Golden Rule)	
	Managing your time is key to your success	
	Follow appropriate chain of command on site and in work area	
Leader-	Own your actions good or bad (Extreme Ownership)	
ship	Take pride in your work and that of your team	
	No extra work should be performed without proper approval	
Quality	Understand the meaning of "clean" and understand the meaning of "complete".	
	You must know how to read tray drawings. Ensure you get with your supervisor if you have any questions.	
	You must know how to identify different tray parts. Ensure you ask your supervisor if have any questions prior to starting any work.	
	You must know the different types of valves on a tray and what type to use on the project you are on.	
Work Knowl-	You must know the importance of down comer clearances and weir heights.	
edge	You must know how to make adjustments on comer clearances and weir heights.	
	You must know the difference between the different types of packing. You must know how to safely remove and replace all types of packing. If you have questions get with your supervisor before you begin.	
	Know the proper way to remove and replace the different types of demister pads.	
	Knowing how to fit up new rings and bars per the client's drawings will positively impact your career	

TOWER CRAFT EXPECTATIONS

EXPECTATION			
Work Knowl- edge	You must know the proper layout of a nozzle. This is critical to the operation and must be verified by inspection prior to cutting the hole or welding.		
	When you are welding to the shell of a vessel you must know the hold points for each step of the processing		
	You must know the alloy of the material you are supposed to have for each component. The material can change from one tray level to another. Always verify type first.		
	When tightening a flange ensure you tighten appropriately so that no one has to come and retighten behind you.		
	Flange joint/alignment should have an even gap all the way around, should have no high/low.		
	Bolts should be uniform with bolts having at least 1 thread outside of nut (client requirements may vary on this ensure you verify prior to work).		

PIPEFITTER EXPECTATIONS

The following is a list of expectations that are required of each employee that is working as a Pipefitter for UPS Industrial Services.

EXPECTATION		
Safety	Wear appropriate safety equipment as required per tasks	
	Follow the Safety Mitigation Process	
	Follow the Safety ² process	
	Follow Stop Work Authority Process as necessary	
Profes-	Show up to work as scheduled on time every day	
	Take Pride in your work, do your job right the first time, when you leave your job site leave it better than you found it.	
sional	Show up prepared with all your equipment/tools as expected	
	Treat others as you expect to be treated (Golden Rule)	
	Managing your time is key to your success	
	Follow appropriate chain of command on site and in work area	
Leader-	Own your actions good or bad (Extreme Ownership)	
ship	Take pride in your work and that of your team	
	No extra work should be performed without proper approval	
	QC is part of your team for success. Involve them before any welding or testing is to start	
	Fit up's IDs are to match with proper transitions & properly cleaned	
0 111	You must properly square and bevel pipe cuts	
Quality	Double check your own work prior to QC inspecting your work	
	Ensure you measure twice cut once to save time and client money	
	Make sure that all piping attaching to a pump is free floating aligned with no strain on the pump case	
	Must know how to read ISO's and & P&ID's, if you have any questions ask someone before you start your task	
Work	Must know how to determine the type of material to determine the type of alloy per drawing and specs: Check the BOM to make sure we have all material	
Knowl-	Must pay attention to leveling pipe & supports	
edge	All fits must be plum & square	
	All Socket welds should have proper gaps	
	Pipe inside fittings should be cut square	

PIPEFITTER EXPECTATIONS

EXPECTATION		
Flange Make- up	Tighten flanges to specifications without having someone come back and tighten loose bolts	
	Joint alignment - should have even gap all around no high low	
	Joint alignment - bolts should be uniform with bolts having at least 1 thread outside of nuts (site requirements may vary on this ensure you get clear expectation from your supervisor)	
Flange Make- up	Joint alignment – nuts should have stamped side out	
	Joint alignment – all bolts should be tight with no loose nuts	
	If bolts have to be cut, always ensure to cut them from one end and leave stamped end for identification	
	Spiral wound and metal gaskets have sharp edges and must be handled with Kevlar gloves	
	Removing/Installing – Gaskets/Blinds – only 1 less than half of the bolts need to be removed from pipe flange	
	Removing/Installing – Gaskets/Blinds – Inspect all gasket sealing surfaces for damage prior to making back up	
	Anti- Seize – ensure that you follow client requirements on application specifications	



SAFETY² PROCESS

Safety² is the foundation of the UPS HSE Program. The Safety² process is a simple method for looking for hazards. The process begins with your mindset.

→ 1: How can I be injured?

Identify the hazards of your activities and your surroundings. Ask the question throughout your day!

The second party of the Safety² process is all about actions:

2: What am I going to do about it?

Take actions needed to mitigate the hazards to prevent injury to yourself or others.

Mitigation of the hazards by either controlling or removing the hazard is the key to preventing injuries or damage.

TAKE ACTION — PREVENT THE INCIDENT

Find the hazard before the hazard finds you!

Eliminate the hazard before the hazard eliminates you!

STOP WORK AUTHORITY (SWA)

It is our duty and expectation to stop work when a new hazard is introduced, or you notice that the potential for someone to be injured or damage to equipment is about to occur.













Prepare to resume—From a Stop Work Authority

If it is determined and agreed that the stop work issue is valid, then every attempt will be made to resolve the issue to affected person's satisfaction prior to resuming work. Notify your Supervisor!

If the stop work issue cannot be resolved immediately work shall be suspended until proper resolution is achieved.

Persons with proper authority (e.g. next level of management, HSE Professional) who are not directly involved with the conflict should be identified to resolve such issues.

INCIDENT REPORTING

Report all incidents to your supervision immediately. Incident must be reported to meet UPS expectations and client requirements. Conducting investigations into incident causes gives us a learning path.

JOB SAFETY ANALYSIS (JSA)

The Job Safety Analysis (JSA) process is about thinking, not about the paperwork. JSA forms are a guide to help you go through the mental process of hazard recognition.

Resolving the hazard:

- Top priority ELIMINATE the hazard.
- Second priority MITIGATE the hazard, by taking steps to control the hazard and make tasks safe to complete.
- If the hazard cannot be eliminated or mitigated, then stop work and NOTIFY your supervisor.

Tips on how to conduct a great JSA:

- Focus on specific hazards in the work area and develop specific ways to resolve the hazards.
- Discuss the work jointly with your crew—work as a team. Make
 it fun—challenge the crew on how many hazards they can
 identify, play the "what if" game, or give recognition to the
 best comment.
- Always include every crew member. Make sure each person in the crew identifies at least one hazard.

STANDING JSA

The Approved Standing JSA addresses the hazards associated with the task. For example, the Standing JSA you are receiving must be reviewed by all crew members and followed. Changes or additions must be covered on the Standing JSA Acknowledgment Form. The expectation is that this form is reviewed with the entire crew and each item that pertains to the actual task is highlighted, underlined, or somehow identified as relevant.

ELIMINATING OR CONTROLLING HAZARDS

Plan A Eliminate the hazard: Get rid of or remove the hazard

Plan B Control the hazard: Take action steps to control hazards that will make tasks safe to complete

Plan C If the hazard cannot be eliminated or controlled, then stop work and notify your supervisor

- Tasks that are not covered on the Standing JSA (or if there is no Standing JSA for the task)
 can be addressed on the Acknowledgment form.
- · Hazards associated with the task, and elimination/control steps must be included.
- All members of the work crew must review the Standing ISA Acknowledgment form.
- The supervisor must review the Standing JSA and Acknowledgment and sign the JSA Acknowledgment form prior to the beginning of the task.

Note: It is very important that the entire crew participates in identifying hazards and elimination or control steps!

UPS LIFE SAVING RULES

United Plant Services Life Saving Rules

I understand that the following Life Saving Rules are in place because failure to follow them could result in serious injury or death to me or someone working around me.

I understand that failure to follow these four lifesaving rules is grounds for disciplinary action, up to and including termination.

1. Never Violate Work Permit Procedures.

- No work without a valid permit on jobs requiring a permit.
- Do not receive a permit without conducting the required job-site verification.
- Do not enter a confined space without a valid permit or a required standby present.
- Do not receive a work permit without a required gas test being conducted.

2. Always Follow Energy Isolation Lockout/Tagout Procedures.

- Do not perform work on equipment without all energy isolated and controlled.
- No unauthorized removal or tampering with a lockout/tagout device.
- No opening process equipment without joint field verification that the equipment has

been properly cleaned, isolated and de-energized or without wearing proper PPE.

- 3. Never bypass or defeat a safety device.
- 4. Never work without Fall Protection when required.

UPS 10 SAFE WORK COMMITMENTS

- 1. I believe that all incidents are preventable.
- 2. I will report all incidents, no matter how minor.
- 3. I am not authorized to perform work where uncontrolled hazards exist. I will eliminate them or control them!
- 4. I will perform Safety² throughout the day, every task, every time.
- 5. I will use Stop Work Authority to intervene and correct at risk behaviors and conditions.
- I will conduct myself in a professional manner at all times no horseplay, harassment or discrimination.
- 7. I will only perform tasks that I am qualified to perform, and, will only operate equipment that I am qualified to operate.
- 8. I will use the best tool for the job, as defined by the JSA or procedure.
- 9. I will always do the job right the first time; safety and quality go hand in hand. No shortcuts!
- 10. I will keep my work area clean, tools and materials organized, and travel paths clear at all times.

FABRICATION STANDING JSA

This Standing JSA must be the approved version that is located in SharePoint. Changes must be approved by Safety and Supervisor.

Task	Associated Hazards	Mitigation/Elimination Steps
Stage Pipe, Iron, or plate using cribbing, Jack- stands, shackles, chokers, and slings	A. Crushing hazards from moving or adjusting large bore pipe, structure, or plate B. Rigging failure from damaged equipment c. Pinch points, pipe shifting or rolling on cribbing or jack stand D. Falling material due to improper jack stand use E. Tripping hazards from lay-down material.	A. Use a tag-line to control load. Maintain communication with rigging department personnel and operator. Ensure NO personnel under load B. Inspect all rigging prior to each use by a certified rigger and ensure proper color code is in place D. Use a 4 leg Jack stand for 8" or larger diameter pipe. Use jack stand(s) only on level solid ground when surface conditions are anything other than concrete. Level, sturdy, and rigid support material must be placed beneath the legs of the jack stands. E. Protruding pipe material will be flagged. Lay-down areas will be barricaded and tagged with a gate for access. Maderial well be stored in a way that does not block access to any other material and will have clear access paths.
2. Prep/cut Pipe, Iron or plate using electric 5" grinder, 7" grinder, die- grinder, bandsaw, Metabo grinder, drill, mag drill, center punch, and cutting torch	A. Electric shock from power tools B. Burns or abrasions from improper tool use C. Cut hazards from saw blades, drill bits or grinding discs D. Trip hazards from electric coxofs E. Furnes / Inhalation hazard from welding F. Flying debris and sparks striking the workers(s) G. Flammable material becoming ignited H. Muscle Strains from lifting mag drill J. Striking hazard while singing hammer J. Wrist snap form drill binding twisting K. Material or clothing getting caught in drill or grinder L. Hot surfaces from fresh cuts	A. Inspect cords that are not normally turned in everyday before use and frequently throughout task to make sure no abrasions, cuts, or wear have occurred. Have 6FC1 at the power source B. Unplug grinder to change disc or adjust guard. Hold tools with both hands on designated factory handles. Never use a grinder without a guard or without a handle. C. Unplug tools to change blade, clist, or bit. Secure any material by device or mechanical means while cutting or grinding, do not attempt to hold material. Keep hands or body parts away from material that is being grinded drilled or cut. Unplug powered tools when not in use. Guard must be placed to protect hand on handle D. Run cords overhead or not in a walkway so a 7 clearance can be maintained in the walkways. Flag cords if less than 7' E. Refer to Addendum for Specific respiratory Protection for Welding F. Anyone using or within 10' of a grinder or torch while in use will utilize same PPE sealed eye wear and a 787-face shield. Maximum speed of Grinder G. Construct spark containment or hooch that is capable of preventing all sparks or slag from leaving the containment or falling below the work area if it is elevated. Remove all flammable or combustible material from the containment or falling below the work area fit is elevated. Remove all flammable or combustible material from the containment prior to task. Utilize a fire-watch with a horn and vest. Fire-watch will stop the work is a fit is elevated. Remove all flammable or combustible material from the containment prior to task. Utilize a fire-watch with a horn and vest. Fire-watch will stop the work is a fit is elevated. Remove fill in the containment of H. Get help moving, lifting and setting mag-drill, and always pick up with legs (NOT-BACK)

FABRICATION STANDING JSA

		I. Never hold any object with your hand, use channel lock or othe tool holding device J. Hold drill with both hands using a firm grip, step up drill size gradually, and use cutting lubricant to reduce binding K. Keep loose clothing tucked in, and/or material secured away from, drill or grinder while in use. Have shirt sleeves buttoned L. Always wear leather gloves when working with cutting torch and watch your hand placement
Weld Pipe, fron rop plate using welding machine, welding leads, argon hose, electric 5" grinder, and argon cylinder	A. Eye burns from arc B. Flammable material becoming ignited C. Hot surfaces from fresh welds or cuts D. Tripping hazards from leads and/or argon hoses E. Fumes / Inhalation hazard when welding F. flying debris while grinding G. Cut hazards from grinding discs	A Utilize welding helmet with #10 through #14 lens filter. Maintain and rylens surface B. Construct a welding enclosure or hooch that is capable of preventing all sparks or slag from leaving the containment or falling below the work area if it is elevated. Remove all flammable or combustible material from the containment prior to task. Utilize a fire-watch with a horn and vest. Fire watch will have a radio. (WHEN REQUIRED BY PERMIT) Fire-watch will stop the work if sparks or slag are flying out of or falling from containment. C. Do not place hands or body parts on hot (fresh) welds /cuts D. Run cords/hoses overhead so a 7' clearance can be maintained in the walkways. Flag hoses/cords if less than 7' E. Refer to Addendum for Specific respiratory protection F. Utilize sealed eyewear and a 287+ face shield will be used. Maximum RPM rating of Grinding Disk must be greater than Maximum speed of Grinder G. Unplug grinder to change disc. Secure any material by device or mechanical means while grinding; do not attempt to hole material. Keep hands or body parts away from material that is being grinded. Unplug powered tools when not in use. Guard must be placed to protect hand on handle
Safety Director/		JSA Subject Matter Expert/Date

JSA ACKNOWLEDGMENT FORM STANDING JSA

- Tasks that are not covered on the Standing JSA (or if there is no Standing JSA for the task) can be addressed on the Acknowledgment form.
- Hazards associated with the task, and elimination/control steps must be included.
- All members of the work crew must review and sign the Standing JSA Acknowledgment.
- The supervisor must review the Standing JSA and Acknowledgment prior to the beginning of the job.



JSA ACKNOWLEDGEMENT

(de of Standing JSA(s):	
OTO Sox &: Snorgy Isolation, zoro onorg	
as this form for any additional tasks or tools to be u	
this form may also be used as your ISA if a Standing II. Task Man	SA does not exist for the task you are performing rands to Consider:
Tool Hazands pinch, cuts, burns, strikes, etc.	# Use of Motorised Equipment? Spotters?
→ Sensitive Equipment in the area?	Flying Debris, Spanks, Airborne Particles Inhalation – Purnes? Respiratory
→ Rigging? Type and Size Determined? Softeners? → Leaka/Solis? Environmental protection Systems in Place **Total Control **Total Control Control Control **Total Control **T	# Heavy Lifting - Machine or Muscle?
→ Electric Shock? LO/TO in Place? Other Protection System	
In place?	Reging?
UST ANY ADDITIONAL TASKS OF TOOLS I HOW CAN YOU	USE NURED? WHAT ARE YOU GOING TO DO ABOUT
TO SE USED FOR TASK.	IT?
Note: It is you	ny improvingat that
Noie. II is ve	ry important that
the entire cre	w participates in
idontifying be	verd climination
<u>laeniliying ne</u>	<u>izara eliminalion</u>
and / or o	control stensi
una / or c	rolliloi siebs:
	, this Acknowledgement, and the Permit and agree to
comply with all safety controls and procedures li	sted to complete my job safely.
ALL WORKERS MUST SI	IGN BEFORE STARTING WORK.
Crew Leader / Foreman: Print Name	Crew Leader / Foreman: Signature
	100,000 to 275,000 to 20,000 to 20,0
	Audio de la circulation de la
Audited / Reviewed by: Print Name	Audited / Reviewed by: Signature

EXAMPLE OF A JSA ACKNOWLEDGMENT



JSA ACKNOWLEDGEMENT

TO Sex A: Snergy Iso	lation, zero energy	voified by:	
e this form for any additional tasks	or tools to be used	for the task.	
is form may also be used as your A			he task you are performing
	Task Hazaro	ds to Consider:	
→ Tool Hassade pinch, cuts, burns, str. → Sandthive Equipment in the area? → Rigging? Type and Size Determine ← Leaks/Spills? Environmental protect → Dectric Shock? LO/TO in Place? On In place?	d? Safteners? ition Systems in Place?		norted Gujorman? Spotman? Int, Spariu, Arbonne Particles Furmet? Registatory Ing-Machine or Muscle? Hassand Watch Required? Undentands Dutles? GCP Path Cleared? Tagʻlines in Pisca? Plan?
ST ANY ADDITIONAL TASKS ON TO OLS DISE USED FOR TASK.	HOW CAN YOUS	(CERUM	WHAT ARE YOU GOING TO GO ABOUT
maye KEAD and UNDERSTAND tr emply with all safety controls ar		-	ment, and the Permit and agree to y job safely.
ALL WO	RKERS MUST SIGI	N BEFORE START	ING WORK
			- -
rew Leader / Foreman: Print Na	me	Crew Leade	r / Foreman: Signature
udited / Reviewed by: Print Nar		Audited / D	eviewed by: Signature

THE PERSONAL HAZARD ASSESSMENT (PHA)

COVER PAGE

- Fill out your name, company # and supervisor
- ··· Read all instructions
- --- Check all that apply

Important: The PHA <u>must always</u> be filled out at the work location in order to effectively address hazards

PHA

Personal Hazard Assessment	
Name	Complete your
Company #	name, Co # &
Supervisor	Supervisor's name
How can I be injured? What am I going to do about it?	
INSTRUCTIONS	
Remember: The PHA Card MUST always be filled out at your work area following the field visit.	
Check All That Apply	L ,
 Walk out your work area − identify wind direction. Identify safety showers and evacuation routes/sites. Have you read and do you understand the Standing JSA? Review and note hazards on Jobsite Hazards List. If a new hazard is identified and not listed, write down the hazard in the OTHER section. Place each hazard number within the circle. Hazards identified in the circle MUST be eliminated or controlled. Circle the hazard # within the circle. Hazards that you cannot immediately eliminate or control MUST be listed individually in the space provided, and in the circle. A discussion MUST occur with your Foreman, Crew Leader, Safety Contact, Permit Issuer, or facility contact to find a way to eliminate or control the hazard before work proceeds. If the scope of work for your job changes or If you move to a different job then a new PHA must be filled out. 	Read each item and Check All that Appl
UNIVERSAL PLANT SERVICES	

	JOB-SITE HAZARDS	
#	HOUSEKEEPING/ TRAVEL PATH HAZARDS	1
Н1	Uneven ground conditions	/
Н2	Slippery Surfaces (algae, ice, sand, water, pellets, etc.)	
нз	Tripping Hazards (rigging, equipment, hoses, temp. piping)	
Н4	Clutter in Work Area (trash, job materials, tools, etc.)	
Н5	Potential Falling Objects	
Н6	Barricade not removed	
Н7	Debris that could become airborne (sandblast grit, insulation, etc.)	\perp
#	FACILITY HAZARDS	~
F1	Cuts/Punctures/Sharps (metal insulation, wire, banding, etc.)	\perp
F2	Hot surfaces	\bot
F3	Head Knockers/Body Knockers (pipe, valve stems)	┸
F4	Open-ended Flanges, Bleed Points, Double-block and Bleeds	\perp
F5	Lighting Inadequate	\perp
F6	Sensitive Equipment (tubing, flow meters, probes, PVC pipe etc.)	\perp
#	JOB PLANNING/SET UP	~
J1	Platform or Scaffold not adequate for job	
J2	Adjacent Work Crews (hazards they may cause in your area)	\perp
13	Mobile Equipment/Traffic (roll over, crushed/struck by)	\perp
J4	Hot Work (Correct Set-up?)	\perp
J5	Overhead Loads/Work Crews (material dropping)	\perp
J6	Process lines not cleaned or cleared	┸
#	PROCEDURES	1
P1	Permit issues	_
P2	LOTO/Energy Isolation	\perp
Р3	Confined space issues (ventilation, no hole watch, gas test)	\perp
#	ENVIRONMENT	✓
E1	Weather (windy, lightening, rain)	
E2	Heat Stress or cold stress	
E3	Excessive Noise	
E4	Insects or animals	\perp
#	TOOLS/EQUIPMENT	1
T1	Electrical Hazards (extension cords frayed, loose wiring)	
T2	Defective tool/Not inspected	
ТЗ	Rigging condition, inspection	
T4	Safety device missing	
T5	Compressed Gas Cylinder storage and use	
oxdot		\bot

Check each hazard that you have found in the area.

SECTION 2: IMPORTANT SAFETY TIPS

HAZARD ASSESSMENT

Write the unit you will be working in and the current date / time. Please use black / blue ink.

Write a brief job scope in the lines provided. If you received a Work Permit for this job, then this job scope should be similar to the one on the permit.

Now (at the job site) begin assessing your hazards by looking around, observing, talking with co-workers, operations and using the HAZARD list. Write the corresponding number of the hazard in the circle.

In this example, there are three (3) hazards that MUST be eliminated or controlled.

As you eliminate or control the hazards circle the numbers.

Unit/Loc:	Date:
Time	Permit Reviewed? Y or N/A
Job 2 (brief job	scope)
-	
	\ -
/ -	
/ (H:	1)
	\ \ \
1	-
1	J1
\	_ ^ " /
	тз)
	/ –
	ZARDS not eliminated or controlled
above and desc	ribe the path forward below.
Hazard #J1_	How Controlled Called Foreman at
7:10 AM; Forema	an called scaffold crew at 7:30 AM
Hazard #	How Controlled
Hazard #	How Controlled
DO IT	Safely or don't do it
	Reviewed By:
	:
Safety:	

List the Unit/Location you are working in.

List the date/time of your job walk.

Did you review the permit for your task?

Provide a brief detailed description of the job scope or task you are performing.

Inside the red circle list the hazards by # (from the Job Site Hazards list) you have found in your work area. Circle those hazards that you or the crew has mitigated; be prepared to answer audit questions about how you mitigated the hazards.

NOTE: If you have more than 5-6 hazards listed, housekeeping is a problem and the area needs to be cleaned or a Stop Work Authority needs to be issued so that the hazards can be eliminated.

Unit/Loc: Date:	
TimePermit Reviewed? Y or N/A	
Job 2 (brief job scope)	
H1 J1	If the hazard cannot be mitigated or properly controlled, then list item in this section.
Discuss the HAZARDS not eliminated or controlled above and describe the path forward below.	Contact your Supervisor.
Hazard #J1 How Controlled_Called Foreman at	Do not proceed with the task or job until all hazards
7:10 AM; Foreman called scaffold crew at 7:30 AM	are controlled or eliminated.
Hazard #How Controlled	Once hazard has been eliminated or controlled
Hazard #How Controlled	then return to the red circle and mark the hazard by circling the number.
DO IT SAFELY OR DON'T DO IT Reviewed By: Supervisor: Safety:	A discussion about the hazards found and the mitigations must take place between crew members and Site Supervision or Safety Professional.

SECTION 2: IMPORTANT SAFETY TIPS

FILLING OUT THE UPS HAZARD CARD

JOBSITE HAZARDS ANALYSIS

Most hazards in the work area should be noted on the following jobsite hazards card.

Use the identified items on the card for your hazard assessment.

Your assessment should include any at risk behaviors as well.

ADDITIONAL METHODS TO INPUT HAZARD OBSERVATIONS, STOP WORK AUTHORITY, NEAR MISSES AND AUDITS.

This is accomplished by the UPS Forms App on phones or iPads and on the Safety main page of the UPS SharePoint site.

All hazards observations, Stop Work Authority, Near Misses, Audits and Incidents must be entered into the Forms App or SharePoint site.

Each Supervisor level employee and HSE Professional must enter a Hazard Observation into the system per day per shift.

	UPS HAZARD CARD	
Obse	erver Name:	
Date	:	
_	4 SSN:	
_		
_	Company #:	_
Facil	ity:	_
Activ	ity Observed:	_
	AT RISK BEHAVIORS	
#	Check behaviors that you observed AND corrected.	
	LINE OF FIRE / PERSONAL INJURY RISK / PPE	ļ
	PPE-Basic (wrong or not using)	4
	PPE-Special (wrong or not using)	4
	Unsafe Body Position	4
	Unsafe Hand Position	4
	Walking/working under a load	+
	Muscle instead of machine (over 50 lbs)	+
_	Not using 3 points of contact climbing/not using handrails	+
_	Crossing barricade	4
_	Climbing/standing on equip. (need scaffold, ladder or stool)	4
_	Walking outside of walk paths	4
L 11	Within 10' of a job without PPE required for that job	_
	WORK PRACTICES	÷
_	Worker not qualified on tool or equipment	4
_	No/wrong barricade	4
	Wearing dark glasses in dark areas or past dusk	4
	Improper ladder use	4
	Poor or improper rigging practices	4
	Not using a spotter for moving equipment	4
_	Swing path not cleared for crane load	4
W 8	Not containing sparks	┙
W 9	Improper use of tool or equipment	⊥
W10	Vehicle or mobile equipment operation	_
W11	Improper use of harness/lanyard	I
_	Standby issues	I
W13	JSA/Addendum/PHA issues (Wrong/incomplete)	I
W14	Poor communication	J
W15	Not folloW ing procedure or no procedure for task	I
W16	Safety ² process not being used	J
	Describe Hazard	
		_
_		
		_
		_

_	JOBSITE HAZARDS	
#	Check jobsite hazards you observed And corrected	
	HOUSEKEEPING/ TRAVEL PATH HAZARDS	
H 1	Uneven ground conditions (holes, rocks, etc.)	Т
Н2	Slippery Surfaces (algae, ice, sand, water, pellets, etc.)	Ť
_	Tripping Hazards (rigging, equipment, hoses, temp.piping)	†
	Clutter in Work Area (trash, job materials, tools, etc.)	+
_	Potential Falling Objects	+
_	Barricade not removed	+
H 7	Debris could become airborne (sandblast grit, insulation, etc.)	+
п/		_
F 4	FACILITY HAZARDS	÷
	Cuts/Punctures/Sharps (metal insulation, wire, banding, etc.)	+
F 2	Hot surfaces	+
	Head Knockers/Body Knockers (pipe, valve stems)	4
F4	Open-ended Flanges, Bleed Points, Double-block and Bleeds	4
_	Lighting Inadequate	4
F6	Sensitive Equipment (tubing, flow meters, probes, etc.)	_
	JOB PLANNING/SET UP	_
J 1	Platform or Scaffold not adequate for job	1
J 2	Adjacent Work Crews (hazards may cause in your area)	1
J 3	Mobile Equipment/Traffic (roll over, crushed/struck by)	1
J 4	Hot Work (Correct Set-up?)	1
J 5	Overhead Loads/Work Crews (material dropping)	4
J 6	Process lines not cleaned or cleared	_
	PROCEDURES	_
	Permit issues	4
-	LOTO/Energy Isolation	4
Р3	Confined space issues (ventilation, no hole watch, gas test)	_
	ENVIRONMENT	
	Weather (Windy, lightening, rain)	1
E 2	Heat Stress or cold stress	1
	Excessive Noise not managed	4
E 4	Insects or animals	_
	TOOLS/EQUIPMENT	
	Electrical Hazards (extension cords frayed, loose wiring)	1
Т2	Defective tool/Not inspected	4
T 2 T 3	Defective tool/Not inspected Rigging condition, inspection	1
T 2 T 3 T 4	Defective tool/Not inspected Rigging condition, inspection Safety device missing	#
T 2 T 3 T 4	Defective tool/Not inspected Rigging condition, inspection Safety device missing Compressed gas cylinder storage and use	
T 2 T 3 T 4	Defective tool/Not inspected Rigging condition, inspection Safety device missing	
T 2 T 3 T 4	Defective tool/Not inspected Rigging condition, inspection Safety device missing Compressed gas cylinder storage and use	
T 2 T 3 T 4	Defective tool/Not inspected Rigging condition, inspection Safety device missing Compressed gas cylinder storage and use	†
T 2 T 3 T 4	Defective tool/Not inspected Rigging condition, inspection Safety device missing Compressed gas cylinder storage and use	
T 2 T 3 T 4	Defective tool/Not inspected Rigging condition, inspection Safety device missing Compressed gas cylinder storage and use	
T 2 T 3 T 4	Defective tool/Not inspected Rigging condition, inspection Safety device missing Compressed gas cylinder storage and use	
T 2 T 3 T 4	Defective tool/Not inspected Rigging condition, inspection Safety device missing Compressed gas cylinder storage and use	
T 2 T 3 T 4	Defective tool/Not inspected Rigging condition, inspection Safety device missing Compressed gas cylinder storage and use	
T 2 T 3 T 4	Defective tool/Not inspected Rigging condition, inspection Safety device missing Compressed gas cylinder storage and use	

LOCKOUT / TAGOUT

Universal Plant Services has an extensive policy regarding energy isolation to protect our coworkers.

Please refer to our policy # S-3310 and your project policies for energy isolation or lockout / tagout. Below are comments from the OSHA website that specifically address this topic. If you have any questions on energy isolation, please contact your site safety and supervisor prior to accepting a safe work permit on a potentially energized system.

Energy sources including electrical, mechanical, hydraulic, pneumatic, chemical, thermal, or other sources in machines and equipment can be hazardous to workers. During the servicing and maintenance of machines and equipment, the unexpected startup or release of stored energy can result in serious injury or death to workers.

- Proper lockout/tagout (LOTO) practices and procedures safeguard workers from the release of hazardous energy. The OSHA standard for The Control of Hazardous Energy (Lockout/ Tagout) (29 CFR 1910.147 [link: http://tinyurl.com/pea65q2]) for general industry, outlines specific action and procedures for addressing and controlling hazardous energy during servicing and maintenance of machines and equipment. Employers are also required to train each worker to ensure that they know, understand, and are able to follow the applicable provisions of the hazardous energy control procedures. Workers must be trained in the purpose and function of the energy control program and have the knowledge and skills required for the safe application, usage and removal of the energy control devices.
- All employees who work in an area where energy control procedure(s) are utilized need to be instructed in the purpose and use of the energy control procedure(s), especially prohibition against attempting to restart or reenergize machines or other equipment that are locked or tagged out.

- All employees who are authorized to lockout machines or equipment and perform the service and maintenance operations need to be trained in recognition of applicable hazardous energy sources in the workplace, the type and magnitude of energy found in the workplace, and the means and methods of isolating and/or controlling the energy.
- Specific procedures and limitations relating to tagout systems where they are allowed.
- Retraining of all employees to maintain proficiency or introduce new or changed control methods.

SECTION 2: IMPORTANT SAFETY TIPS

WORK PERMITS

SCOPE OF WORK (SOW) — Ensure you conduct a job walk with the client to review the SOW prior to permit issue. Ensure that the permit contains a clear description and scope of the work to be performed. Some jobs require multiple tasks to be performed. Each task may have different safety requirements such as inspection, cleaning, line preparation, blinding, etc. Detailing the safety requirements for each task covered in the work permit is important since the exposure and hazards may vary at each stage of the work.

Read and understand the SOW conditions. If the permit is not legible, requires safety precautions that seem too much or too little for the type of work you are doing, or if there is any information missing or confusing to you — DO NOT ACCEPT THE PERMIT. Get clarification, and have the initiator reissue the permit with the additional information.

Do not exceed the SOW that is indicated on the permit. Stop work if the work scope or job conditions change beyond what is specified on the original permit. Contact the permit issuer and get the permit updated in writing. If it is not in writing, DON'T DO IT! Verbal approval is not permitted!

Check the permit for the following:

- The date and time for which the permit is valid. Work must start within one hour after the permit is issued. (Some clients require work to start sooner)
- Unit, area, name and number of equipment and location are clearly identified.
- Equipment isolation (LOTO) and line preparation procedures are specific.
- Atmospheric testing data is complete, and the signature of the individual performing the testing is present.

- SDS is provided for the material that was previously in the line or vessel.
- Respirator selection If respirators are indicated as required on the permit, the type of respirator and/or cartridge must be specified.
- Any special PPE provisions must satisfy the permit requirements, our company policies, and regulatory compliance.
- If the work involves interconnecting units or areas, make sure you have signatures from operators of all affected areas on the permit.

Walk the jobsite to visually inspect, determine equipment needs, coordinate work, and complete the JSA. When working with either a hot or cold work permit, ensure proper barricades are in place between permit areas. Ensure that a safe distance exists between conflicting types of work.

Remember, permit issuers are human and can make mistakes, so it is your responsibility to take your time, read, understand and ask questions. Keep asking questions until you get clarification and are satisfied that you and your crew thoroughly understand the scope, hazards, site conditions, and safety precautions necessary to complete the job safely

WORK PERMITS

STOP AND THINK — A permit doesn't replace common sense.

- What is the most hazardous aspect of the job?
- If performing a procedure, have I talked to the affected people & supervisor prior to beginning?
- · Are process safety hazards considered?
- · Is Lockout/Tagout required?
- Is blinding point(s) and / or piping de-pressured and drained?
- · Do I need a gas test?
- · Am I downwind of any hazard?
- · Is there adequate lighting?
- Is the scaffold adequate, inspected and tagged?
- · Do I need a harness?
- · Do I need a respirator?
- Do I need special gloves?
- · Do I need to wear a face shield?
- Could my actions impact the environment?
- Could my actions impact other units?
 - If yes, have I contacted / discussed with affected personnel?
- · Have I checked for:

- · Possible pinch points
- · Nearest fire extinguisher
- Escape routes
- · Nearest safety shower
- Appropriate PPE
- Slipping hazards
- · Adequate and appropriate tools
- · Proper gasket type
- · Proper blind type
- · Exposed steam tracing

PNEUMATIC TESTING

The pneumatic test may be used, with UPS Engineering approval, in lieu of standard hydrostatic pressure testing of piping systems, valves, vessels and other processing equipment if the system is so designed that:

- The item being tested cannot safely support the weight of water filling.
- The item cannot be adequately drained or dried after hydrostatic testing.
- Liquids would contaminate a process that would be hazardous, corrosive, or become inoperative in the presents of moisture
- Liquids would cause damage internal components.

Safety Precautions

- Before performing any pneumatic test always review the latest UPS Pneumatic Test Procedure.
- Any pneumatic test with pressures greater than 25 psi requires UPS engineering review and written QC manager approval.
- Pneumatic testing involves the hazard of released energy stored in compressed gas. Particular care must be therefore be taken to minimize the chance of brittle fracture during a pneumatic leak test. Test temperature is important in this regard. If the temperature is or is expected to be below 50 deg. F and/ or the material wall thickness is greater than 1/2 inch thick, engineering must be consulted to determine if the conditions will fall below the minimum design metal temperature and create a brittle fracture hazard.
- Reinforcing plates and welds are tested using the threaded weep (telltale) hole in the plate, the test pressure shall not exceed 15 psi unless directed in writing by UPS Engineering.
- This test is not to be used on cast iron pipe, plastic pipe or pipe having soldered joints.

- Rope off the work area for a minimum of 25 feet, barricade with caution tape or signs.
- Compressed gas cylinders will be secured and stored in their upright position.
- All compressed gases will be introduced through a pressure regulator set to the test pressure.
- All pneumatic tests shall have a pressure relief device provided, having a set pressure not higher than the test pressure plus the lesser of 50 psi or 10% of the test pressure.
- Never leave the filling valve unattended while building pressure.
- Face shields and hearing protection will be worn by all personnel inside the pressure test barricade area. High pressure leaks, ruptures gaskets or system failures can result in debris injuries and sudden loud noises.
- A properly sized and calibrated test gauge will be located within view of the filling manifold.

HYDROSTATIC TESTING

Hydrostatic testing is performed on existing, new equipment and pipelines to check for leaks after repair or maintenance. The main hazard during hydrostatic testing is losing control of the high-pressure water flow. A secondary hazard is over-pressurizing the system. Both hazards can damage property and endanger workers' safety. Never start the test if a problem is identified.

HYDROSTATIC TESTING PREPARATION

Hydro-tests will be performed per the UPS Quality Manuals for the items being tested. Before hydro-testing, be sure to verify that:

- A safe work permit has been issued by authorized personnel.
- The test area is isolated and surrounded with safety line. Place appropriate safety signs near the area. If possible, perform the test in a remote area. No one other than workers involved with the hydrotesting shall be in the area.
- All workers are wearing proper personal protective equipment.
- There are specific work and communication plans among everyone involved in, or affected by, the test.
- Any equipment or pipes not included in the hydrostatic test have been isolated.
- Vents are available and installed at high points. Re-check the vent line immediately before testing to make sure it is not blocked
- There is a drain valve at the low point in order to completely empty the system.
- All pipe and vessel supports are in good condition and have been inspected.
- Temporary supports which may be required for systems designed for vapor or gas during the hydrostatic test are approved by the client.

- Water temperature is higher than 60 F.
- All test equipment and tools have been inspected for wear or damage.
- Pressure gauges are installed at a location so that they can be easily read and do not create additional hazards by exposing personnel to leaking hydro-test fluid. The gauges are recommended to have 150% of the maximum allowable working pressure. Pressure gauges must have current calibration inspections.
- Hydro-testing of multi-chamber vessels or heat exchangers have been reviewed with the client to confirm the maximum differential pressure between the chambers or across the tube sheets.
 Ensure that at least two test gauges are used to monitor the differential pressure.
- All the temporary tools (such as valve, fitting, hoses, flanges, blind plate, etc.) are rated more than the maximum hydrostatic pressure.
- Someone is assigned to monitor the pump pressure during operation.
- Dispose of used hydro-test water only in the approved locations.

CRITICAL LIFT PLAN

UPS Industrial Services procedure for critical lifting is as follows:

- Engineering Dept. determines weight and center of gravity of component to be lifted.
- 2. The Competent rigging person sizes rigging hardware and its application, taking into consideration deductions for sling configuration, sling angle, shackle configuration, and the 1:1 ratio of cable choker to pin shackle (1" cable choker requires minimum 1"shackle pin diameter, ¾": ¾", etc.)
- 3. Competent rigging person sizes crane and determines crane configuration, taking into consideration all aspects of the lift, including: tip height, boom angle, boom and jib length and off-set, deductions for erected or stowed jib, deductions for traveling block and parts of line or falls, and deductions for rigging hardware. Remember to check for load and boom clearances, tail swing clearances, overhead power lines or obstructions, soil condition and compaction, matting requirements, underground lines, sewers, recent excavations or voids.
- Measure to confirm actual lifting radius and elevation. Do not rely on crane's computer or other electronic devices.
- If necessary, perform geotechnical survey to determine allowable ground bearing pressures and ensure crane owner provides maximum imposed ground bearing pressures. Engineering Dept. shall calculate appropriate matting arrangement.

- Provide detailed engineer stamped sketch or CAD drawing (plan and elevation view) to client representative for approval.
- Perform pre-lift meeting to establish responsibilities and to assure all parties are aware of the sequence of activities to take place.
- Confirm that all inspections of crane, lift lugs / trunnions, and rigging hardware have been completed.
- Confirm that lift and tail swing radius have been barricaded and all nonessential personnel have been notified and cleared from the lift site.
- Attach the required number and length of tag lines to the load in order to maintain control at all times.
- 11. Be aware of imminent weather conditions and the dynamic effects wind can have on loads and crane components, or the effect that accumulations of snow and rain can have on the weight of items to be lifted.
- 12. Establish a sole crane signal person who is to remain in constant communication with the crane operator. Crane operator should be prepared to acknowledge a "stop signal" from anyone involved in the lift.

GLOVE SELECTION

Employees shall use the proper hand protection when hazards exist from skin absorption of harmful substances, cuts or lacerations, abrasions, punctures, chemical burns, thermal burns and harmful temperature extremes. Hand protection shall be selected on the basis of the task to be performed, conditions present, duration of use and the hazards & potential hazards identified.

PROPER GLOVE FIT

- · Wear only gloves that fit your hands.
- Gloves that are too small can tire your hands.
- Gloves that are too large are awkward to work with.
- Wearing gloves around moving equipment shall be done with great caution. Gloves may get caught and pull your hand into the machinery.

TYPES OF GLOVES

Leather Gloves

- Leather gloves protect against sparks, moderate heat, blows, chips and rough objects.
- Welders gloves (heavy duty) used for handling moderately hot materials.
- Welders gloves (TIG) Smooth finished with cuff.
- Leather gloves (long cuffed) used by riggers and operators.
- Leather gloves (short cuffed) used by various crafts.
- Driver's gloves leather, smooth finish, good general-purpose glove.

Neoprene Gloves

These are black, elbow length gloves used for handling and cleaning with chemicals. Neoprene protects workers from burns, riritation, and dermatitis caused by contact with oils, greases, solvents, hydraulic fluids, gasoline, alcohol's, organic acids and alkalis.

Nitrile Gloves

This glove type should be used for handling Hexane and Hydrocarbons. Stands up to heavy use even after prolonged exposure that causes other gloves to deteriorate.

Keylar Blend Gloves

Kevlar provides a unique combination of toughness, flexibility, cut resistance and exceptional thermal stability. Use these gloves when cutting or when exposed to mild heat. Cut resistance minimum cut level 3 or higher.

Bead Blasting Gloves

Are to be used for bead blasting machines ONLY.

Latex Gloves

- Reduce the risk of exposure to blood and other potentially infectious substances.
- Comfortable to wear and pliability, along with their protective qualities, make them a popular general purpose glove.
- Protects workers' hands from most water solutions of acids, alkalis, and salts.
- Hypoallergenic gloves, glove liners, and powder-less gloves are possible alternatives for those allergic to latex.

Vinyl Gloves

Should only be used for minor tasks such as trash pickup.

NOTE: GLOVES SHOULD NOT BE CONSIDERED TOTAL PROTECTION. ALWAYS BE AWARE OF HAND POSITIONING AND LINE OF FIRE.



TOOL USE AND INSPECTION

INSPECTION COLOR CODES

Quarterly Color Code
Q1 – 1 JAN – 31 MAR – Yellow
Q2 – 1 APR – 30 JUN – Green
Q3 – 1 JUL – 30 SEP – Red
Q4 – 1 OCT – 31 DEC – Orange
Defective Tool
Brown

PERSONAL PROTECTIVE EQUIPMENT (PPE)

	REQUIRED PPE									
EQUIPMENT	Gloves	FRC's	Steel- Toe- Boots	Safety Glasses	Hearing Protection	Face Shield	Hard Hat	Respirator		
HAND TOOLS	HAND TOOLS									
Combination Wrench	•	/ \	L	8	0	()	0			
Hammer Wrench	•	/ \		=	0	()	0			
Hand Torque Wrench	•	/ \hat{\hat{\hat{\hat{\hat{\hat{\hat{	L	=	0	()	0			
Pipe Wrench	•	/ \hat{\hat{\hat{\hat{\hat{\hat{\hat{	R	8	0		0			
Hack Saw	•	/ \hat{\hat{\hat{\hat{\hat{\hat{\hat{	K	€	0		0			
Hand File	•	/ \(\)	L	8	0		0			
Hammer		1		8	0		0			
Pry Bar		/ \		=	0		•			
Bull Pin	•	/ \		8	0		•			
Socket	•	八	L	8	0	()	0			
ELECTRICAL T	OOLS									
Grinders: Portable Grinders		₹	ß	8	0					
Bench Grinders	•	八		8	0	0	•			
Saws: Port-A- Band Saw	•	水	L		0	(D)	0			
Saws: Re- ciprocating Saw (Sawzall)	•	1	R	8	0	<u> </u>	•			
Saws: Chop Saw	•	水	ß	8	0	(F	0			
Saws: Circu- lar Saw	•	/ \	K	8	0	()	0			

PERSONAL PROTECTIVE EQUIPMENT (PPE)

EQUIPMENT	REQUIRED PPE							
	Gloves	FRC's	Steel-Toe- Boots	Safety Glasses	Hearing Protection	Face Shield	Hard Hat	Respirator
ELECTRICAL TOOLS								
Hand Drill	•	/ \hat{\hat{\hat{\hat{\hat{\hat{\hat{		=	0	9	0	
Magnetic Drill	•	/		8	0			
Pipe Threader	•	八	L	8	0		•	
Welding Machine	•	/ \	L	8	0	(F	•	8
Impact Wrench	•	/ \		8	0	(F	•	
PNEUMATIC AND HYDRAULIC TOOLS								
Air Torque Wrench		/ \hat{\hat{\hat{\hat{\hat{\hat{\hat{	L	8	0	(F	0	
Hydraulic Torque Wrench	•	/ \hat{\hat{\hat{\hat{\hat{\hat{\hat{		=	0	()	•	
Air Chisel	•	/ \		=	0	()	•	
Air Mover	•	/ \	L	8	0		0	
OTHER TOOLS								
Jack Stand	•	/ \hat{\hat{\hat{\hat{\hat{\hat{\hat{		8	0		0	
Cutting Torch	•	八		8	0	()	0	8
Beveling Machine	•	/ \hat{\hat{\hat{\hat{\hat{\hat{\hat{	L	=	0	(J)		
Port-A-Power	•	/ \hat{\hat{\hat{\hat{\hat{\hat{\hat{		=	0	(F	•	
Come-A- Long And Chain Fall	•	1	ß	8	0		•	
Air Tugger	•	/		8	0		0	

SECTION 3: TOOL USE AND INSPECTION

Hand Tools COMBINATION WRENCH



A combination wrench is a double-ended wrench where one end is an open-end wrench and the other a box-end wrench or ring spanner. Both ends generally fit the same size bolt. It is used to apply manual torque to turn objects.

IS THIS NOTED IN YOUR ISA/PHA?

Do you have the correct size wrench that fits the job?

Do you have a good grip on the wrench to prevent slipping?

Have you inspected the wrench and nut for damages or wear that may cause slipping?

Have you checked for pinch points or hand injury points should the wrench slip?

Is the area where your are working clear of tripping hazards and well lit?

Do you have all the PPE required for the job?

DO:


- Wear appropriate PPE.
- Always push, never pull any tool towards you.
- Remove your body and that of others from line of fire!
- Inspect the wrench for flaws, damage, or wear prior to use.
- · Return any damaged wrench to tool room.
- Maintain correct balance and footing.
 Ensure the floor is not slippery and wear non-slip shoes.
- Clear area around wrench work to protect against injury if the wrench slips.
- Use the correct jaw to avoid slippage.
 Box wrenches are safer than open-end wrenches since they are less likely to slip.
- Use a split box wrench on flare nuts.
 Grip the wrench so it will not slip.

- Don't attempt to repair a wrench with rounded or damaged points on the box end or worn or spread jaws on the open end.
- Never use fractional wrenches on metric fasteners or vice versa.
- Don't use a shim to make a wrench fit.
- Never overload a wrench by using a pipe extension or cheater bar on the handle.
- Don't strike the handle with a hammer.
 This can weaken the metal of the wrench and cause the tool to break.
- Never use a wrench on moving machinery.
- Don't overreach. Keep proper footing and balance at all times.
- Don't double wrench.

Hand Tools HAMMER WRENCH

A hammer wrench is a specialized, short, stocky wrench with a block end designed to be hit by a hammer. This tool is commonly used with large fasteners, especially a nut and stud which both have index marks. Typically, the nut is hand-tightened first, and then further tightened with the hammer wrench a specific number of index marks, thus giving precise torque (preload). Hammer

wrenches also provide shock and high force for releasing large and / or stuck nuts and bolts including situations where there is not room for a large wrench.



Do you have the correct size hammer wrench for the job?

Have you inspected the wrench and nut for flaws or wear that may cause it to slip?

Do you have enough clearance to hold the wrench and swing the hammer safely?

Do you have a good grip on the wrench to prevent slipping?

If you are working with a partner, do you have line of sight and a plan to prevent someone from being struck?

Is the area where your are working clear of tripping hazards and well lit?

Do you have all the PPE required for the job?

DO:

- Wear appropriate PPE.
- Inspect the wrench for flaws, damage, or wear.
- · Return any damaged wrench.
- Maintain correct balance and footing.
 Ensure the floor is not slippery and wear non-slip shoes.
- Clear area around wrench work to protect against injury if the wrench slips.
- Ensure you have room to swing hammer safely.
- Maintain line of sight and / or have a communication plan with co-workers to make sure no one is struck.
- Must use a holder to secure hammer wrench.
- It is preferred not to be used as a backup, but when you must utilize a tool holder.

- Don't hold it in your hands, while in use.
- Don't attempt to repair a wrench with worn or damaged points.
- Never use fractional wrenches on metric fasteners or vice versa.
- · Don't use a shim to make a wrench fit.
- Never overload a wrench by using a pipe extension or cheater bar on the handle.
- Never use a wrench on moving machinery.
- Don't overreach. Keep proper footing and balance at all times.
- Never swing a hammer before ensuring adequate clearance and the location of co-workers.

Hand Tools HAND TORQUE WRENCH

Hand Torque wrenches primarily are used to measure torque and to apply it on any type of fastener, such as nuts, socket head screws or bolts. Torque wrenches come in many shapes and sizes for use in different situations, but all operate essentially the same.

IS THIS NOTED IN YOUR JSA/PHA?

Do you have the correct size wrench for the job?

Do you have the correct socket and have you verified that it fits properly on the nut or bolt being tightened?

Have you inspected the wrench and nut for flaws or wear that may cause slipping?

Is your balance and footing properly maintained?

Do you have sufficient space and correct body positioning to do the job?

Is the tool on the proper torque setting before use?

Is the grip handle held correctly and in the proper position?

Do you have all the PPE required for the job?

DO:

- Wear appropriate PPE.
- Inspect the wrench for flaws, damage, or wear.
- Return any damaged wrench.
- Maintain correct balance and footing.
 Clear area around wrench work to
- protect against injury if the wrench slips.Verify that torque wrench has been
- Verify that torque wrench has been serviced, calibrated, and maintained by a qualified technician.
- Clean and / or repair the threads that will be tightened. Damaged or dirty threads will result in a misleading torque reading.
- Store torque wrench inside a case in a clean and dry location.
- · Use tool only within rated torque range.
- Inspect before every use.
- Use only sockets with the correct drive and that are rated to at least the torque that will be applied to it.

- Don't use tool if damaged or parts are loose. Return for repairs.
- Never immerse wrench in cleaning solution, as it damages the internal lubrication.
- Don't use a handle extension, hammer or pry bar to increase force.
- Never turn knurled handle below the lowest torque setting.
- · Don't use torque wrench for loosening.
- Never use a wrench on moving machinery.
- Don't overreach. Keep proper footing and balance at all times.
 - Push don't pull. Never pull towards your body.

SECTION 3: TOOL USE AND INSPECTION

Hand Tools PIPE WRENCH





There are three basic types of pipe wrenches — the strap wrench, the chain wrench and the Stillson wrench. They are used to connect or break pipe joints, or to turn cylindrical parts. When using a pipe wrench of any size, maintain a small gap between the shank of the hook jaw and the pipe itself.

IS THIS NOTED IN YOUR ISA/PHA?

Do you have the correct size and type of pipe wrench to do the job?

Have you inspected the pipe wrench for any excessive wear, cracks or damaged parts?

Is there enough clearance for the job to be performed?

Is the work piece secured or clamped to a stable platform? Is your footing properly maintained while using the wrench?

Is your area clean and clear of all possible hazards?

Do you have all the PPE required for the job?

DO:

- Wear appropriate PPE.
- Inspect the wrench for flaws, damage, or wear.
- · Return any damaged wrench.
- · Maintain correct balance and footing.
- Clear area around wrench work to protect against injury if the wrench slips.
- Select a pipe wrench with sufficient capacity and leverage to do the job.
- Adjust the pipe wrench grip to maintain a gap between the back of the hook jaw and the pipe.
- Face wrench forward and turn wrench so pressure is against heel jaw.
- Pull, rather than push, on the pipe wrench handle.
- Inspect pipe wrenches periodically for worn or unsafe parts. Keep pipe wrench teeth clean and sharp.

- Don't use tool if damaged or parts are loose. Return for repairs.
- Never modify or alter a pipe wrench.
- Don't use in conjunction with a power drive, threading machine or any mechanical / hydraulic device to make or break fittings.
- Never use a handle extension, hammer or pry bar to increase force.
- Don't apply a side load to the handle.
- Never use a pipe wrench to bend, raise or lift a pipe.
- · Don't overreach.
- Push don't pull. Never pull towards your body.

SECTION 3: TOOL USE AND INSPECTION

Hand Tools HACK SAW



A hacksaw is comprised of a fine tooth blade under tension in a frame, used for cutting materials such as metal or plastics. Hacksaw blades are available with tooth counts ranging from 14 to 32 teeth per inch. Thin material requires more teeth per inch, while thicker material requires fewer teeth per inch.

IS THIS NOTED IN YOUR JSA/PHA?

Do you have the correct saw blade for the material to be cut? Is the material to be cut secure in a vise or a holding device?

Is the blade correctly tensioned and teeth pointing forward?

Do you have all the PPE required for the job?

DO:

- Wear appropriate PPE.
- Secure the material to be cut in a vise or other holding device to avoid vibration.
- Choose the correct blade for the material being cut.
- Insert the correct blade in the hacksaw frame and adjust wing nut for proper tension.
- Maintain correct balance and footing.
 Use a file to make a notch for guiding the first strokes of the saw.
- Steady the saw by holding the handle with the one hand and the frame with the other.
- Keep your hands and fingers away from the saw blade.
- Hold the blade perpendicular to the material being cut.
- Saw at a rate not to exceed 40 to 50 strokes per minute. Cut harder materials slower than softer materials.
- When done, place saw flat on a work bench or in a spot where teeth cannot be damaged between cuts. Keep saw blade clean, and use light machine oil on the blade to keep it from rusting, overheating and breaking.

- Protect saw blade teeth from coming in contact with metal or other material that may damage them.
- Replace damaged saw handles with new ones immediately when needed.

- Don't use tool if damaged or parts are loose. Return for repairs.
- Never modify or alter a saw.
- · Don't carry a saw by the blade.
- Never force the saw if it binds. Use a wedge to spread the cut..
- Never cut material that isn't secure, and do not hold material you are cutting. Don't overreach.
- Never place your hand on or near the blade during use.

Hand Tools HAND FILE



Metal hand files are used for shaping, cutting and finishing metal, and also for removing excess material or smoothing rough edges. Files come in a variety of materials, sizes, shapes, cuts, and tooth configurations.

IS THIS NOTED IN YOUR JSA/PHA?

Do you have the proper file for the job?

Is your balance and footing properly maintained?

Do you have proper hand protection?

Is the material to be filed secured in a vice or other holding device?

Is your area clean and clear of all possible hazards?

Is the file handle fitted tightly?

Do you have all the PPE required for the job?

DO:

- · Wear appropriate PPE.
- Secure the material being filed in a vice or other holding device.
- · Use an offset handle if available.
- Maintain correct balance and footing.
 Ensure the floor is clear and stable.
- · Inspect file before every use.
- Grasp the file with one hand and guide the point of the file with the thumb and forefinger of the other hand. Always wear proper hand protection.
- Use the lightest amount of pressure to perform the desired job.
- Carry pointed tools with the point facing DOWN.
- Ensure proper handle is installed on the file.
- Ensure that the file is clean and serviceable before and after use.

- · Don't use tool if damaged.
- · Never use a file without a handle.
- Don't use a file to pry or hammer.
- Never hold the file rigid or stationary keep stroking continually.
- Don't overreach. Keep proper footing and balance at all times.

SECTION 3: TOOL USE AND INSPECTION

Hand Tools **HAMMER**





A hammer is a basic construction tool used to deliver an impact to an object. Common uses include driving nails, fitting parts, forging metal and breaking up objects. There are specific hammers designed for particular jobs.

IS THIS NOTED IN YOUR JSA/PHA?

Do you have the proper weight and size hammer for the job?

Have you inspected the hammer for excessive wear, mushrooming, or cracks?

Is the head of the hammer firmly attached to the handle?

Is your balance and footing properly maintained?

Have you warned nearby personnel before using the hammer?

Do you have adequate clearance to swing the hammer safely?

Do you have all the PPE require for the job?

DO:

- · Wear appropriate PPE.
- · Watch the object you are hitting.
- · Keep striking face clear of oil and grease.
- Hold the hammer with your wrist straight and your hand firmly wrapped around the handle.
- Look behind and above you before swinging the hammer.
- Strike a hammer blow squarely with the striking face parallel to the surface being struck. See Fig. 1a
- Avoid glancing blows as well as over and under strikes. See Fig. 1b
- Protect wood handles from extremely wet and dry conditions.
- · Inspect the wood handle prior to use.

- Don't use a hammer with dents, cracks, chips, mushrooming, or excessive wear to the head.
- Never redress, grind, weld or heat-treat a hammer head.
- Don't use a hammer for any purpose other than for which it was designed or intended.
- Don't strike with the side or cheek of the hammer.
- Don't overreach. Keep proper footing and balance at all times.

SECTION 3: TOOL USE AND INSPECTION

Hand Tools **PRY BAR**



A Pry bar (or Crowbar) is commonly used for ripping out, separating or prying apart objects, It also can be used as a lever. Pry bars come in many different sizes and weights. Crow bars have an angled, forked end, typically used for removing nails.

IS THIS NOTED IN YOUR JSA/PHA?

Do you have the proper size and type pry bar for the job?

Is your balance and footing properly maintained?

Do you have the proper hand protection?

Have you inspected the pry bar for wear or cracks?

Is your area clean and clear of all possible hazards?

Do you have all the PPE required for the job?

DO:

- · Wear appropriate PPE.
- · Inspect the bar for burrs and cracks.
- Look behind you before using to make sure the area is clear.
- Be sure to secure the object you are demolishing.
- Have secure footing before applying pressure.
- Find a narrow crack and insert the pry bar into the crack and then apply force slowly.
- Carry pointed tools by your side with the points and heavy end DOWN.

- Don't use a bar that is cracked, bent or has excessive wear.
- Never use a pry bar for any purpose other than for which it was designed or intended.
- · Don't strike a bar with another tool.
- Never apply force quickly to an object you are prying apart.
- Don't overreach. Keep proper footing and balance at all times.
- Push don't pull. Never pull towards your body.

Hand Tools **BULL PIN**



A bull pin or drift pin is used as an aid in aligning bolt or rivet holes prior to inserting a fastener. They are often made from round steel stock. It is important to discard any drift pin that is not straight or has excessive wear.

IS THIS NOTED IN YOUR JSA/PHA?

Is your balance and footing properly maintained?

Do you have the proper hand and eye protection?

Have you inspected the bull pin for cracks, chips, mushrooming or excessive wear?

Do you have all the PPE required for the job?

DO:

- Return any drift pin if it is bent or either end shows dents, cracks, chips, mushrooming or excessive wear.
- Look behind and above you before striking the bull pin.
- Maintain correct balance and footing.
 Ensure the floor is not slippery and wear non-slip shoes.
- Barricade the area, when possible.
- Watch the bull pin as you are striking it.
 Be careful for sudden release of stored energy of the pin.
- · Strike the head squarely with a hammer.
- · Use a tool holder, if possible.

- Don't use a bull pin with dents, cracks, chips, mushrooming, or excessive wear.
- Never use a bull pin for any purpose other than for which it was designed or intended.
- Don't hold the bull pin while someone else is striking the head with the hammer, and vice versa.
- · Never use a drift pin as a punch.
- · Don't ever weld to a bull pin.

Hand Tools HAND SOCKET





A socket is a cup shaped fitting with a recess that grips the head of a bolt or nut. Sockets are attached to various types of socket wrenches, including hand held, powered and torque wrenches.

IS THIS NOTED IN YOUR JSA/PHA?

Do you have the correct size and type of socket to do the job?

Is the socket secured with a socket retaining pin?

Have you inspected the socket for any cracks or damage?

Is your area clean and clear of all possible hazards?

Do you have all the PPE required for the job?

DO:

- Wear appropriate PPE.
- · Regularly inspect sockets and drive tools.
- Replace sockets if corners are worn or cracked.
- Select the correct size and type of socket for the job. Match the socket to the drive tool / wrench.
- Use an approved retaining pin to hold socket to drive tool.
- Use the shortest and simplest connection to the drive tool. Avoid extension bars and adapters if possible.
- · Maintain correct balance and footing.

- · Don't use damaged or worn sockets.
- Never use hand sockets on power or impact tools.
- Don't strike an impact socket with a hammer or other tool.
- Never hold a socket, universal joint, or any other attachment while the power tool is running.
- Don't continue to operate an impact tool once the fastener is tight.
- Never modify a socket to accomplish a task for which it was not intended.
- Don't use shims to get a socket to fit. Use the correct size socket.
- Don't ever attempt to repair a damaged socket (do not weld).

Electrical Tools GRINDERS: PORTABLE GRINDERS



Hazards with the use of portable grinders include the disc either contacting the operator's body, or shattering and throwing off fragments at high speed. Operators must be trained in selecting, inspecting, fitting, maintaining, removing, and carefully using portable grinders. Always check the max RPM of the grinder before mounting a wheel, to ensure that it doesn't exceed the maximum operating speed marked on the wheel.

IS THIS NOTED IN YOUR JSA/PHA?

Is the guard present and firmly attached?

Is the wheel free from cracks, chips, gouges, or other damage?

Is the rated wheel speed greater or equal to that of the grinder, and is the correct wheel size used?

Are the flange nuts and flanges in good condition and appropriate for the wheel?

Have you inspected the new abrasive wheels before they are mounted?

Is the wheel being used correct for the application, and correctly mounted and tightened before use?

Is the electrical cord or air hose damaged or showing excessive wear?

Are there any worn or damaged mounting accessories?

Do you have all the PPE required for the job?

DO:

- Wear appropriate PPE.
- Use clamps or other safe ways to secure and support the work piece to a stable platform.
- Be sure ON/OFF switch is non-locking type. And inspect for proper function.
- Remove adjusting keys or wrenches before turning on the tool.
- Disconnect the plug from the power source before making any adjustments, changing accessories, or storing the too.
- changing accessories, or storing the tool.

 Always use a side handle, in order to
- maintain control of the tool.
 Wear FRC clothing and proper gloves when grinding with the portable disc
- grinder to protect hands and forearms.
 Require same PPE for people within 10' of grinding activities.
- Always operate the grinder with two (2) hands.
- Check the safe operating speed of grinding disks and rocks before use.

- Never reach underneath the work. The quard cannot protect you below the work.
- Never overreach; keep proper footing and balance at all times.
- Don't use damaged cutting disc, wheel or rock
- Never abuse the cord. Never use the cord to carry the tools or pull the plug from an outlet.
- Don't place the cord near heat, oil, sharp edges or moving parts. Remove damaged cords immediately.
- Never override the ON/OFF switch or secure it in the ON position.
- Don't work on unsecure materials.
- Don't sharpen tungsten with the grinder.

Electrical Tools GRINDERS: BENCH GRINDERS



There are four basic safety elements to the bench grinder that serve as guards or shields. (1) The flange and spindle guard protect you from the spinning wheel. (2) The eye shield protects your eyes. (3) The adjustable tongue guard helps stop flying debris and sparks. It should be no more than 1/4-inch from the wheel. (4) The work rest is the point of operation and ensures safe operation if located properly. The rest should be 1/8-inch from the wheel. You should position the work piece on the rest so it touches the wheel from the front or edge.

IS THIS NOTED IN YOUR JSA/PHA?

Do side guards cover the spindle, nut and flange and 75% of the wheel diameter?

Is the eye shield secure, clear and free of cracks?

Is the adjustable tongue guard on the top of the grinder within 1/4" of the wheel?

Is the work rest in place and adjusted to within 1/8" of the wheel?

Is the maximum RPM rating of each abrasive wheel compatible with the RPM rating of the grinder motor?

Before a new abrasive wheel is mounted, is it visually inspected and ring tested? Make sure the grinder is unplugged prior to removing / installing wheels.

Is the grinding surface completely square with no grooves? (if no, dress wheel prior to use)

Is the bench grinder securely mounted?

Is the arinder effectively arounded?

Does the grinder have an individual ON/OFF switch?

Do you have all the PPE required for the job?

DO:

- Wear appropriate PPE.
- Dress wheel prior to use if disk surface is irregular in any way.
- Bring the object into contact with the grinding wheel slowly and smoothly, avoiding impact motions.
- Keep bystanders a safe distance away from the work area.
- Move object being ground back and forth across the face of the wheel to avoid forming grooves.
- Keep proper footing and balance at all times.

- Don't use a bench grinder if it is not firmly fastened to a work bench or rigid frame.
- Never grind on the side; grind only on the face of the grinding wheel.
- Never use tool if switch does not turn it on or off. Any tool that cannot be controlled with the switch is dangerous and must be repaired.
- Don't force tool. Use the correct tool for your job.
- Never grind or sharpen anything that cannot be adequately supported by the tool rest.
- Don't stick an object into the wheel to slow or stop it, and always wait until the grinder stops completely before leaving.

Electrical Tools SAWS: PORT-A-BAND SAW



Few tools can make a job of cutting metallic tubing or other stock easier than a bandsaw. On those occasions when the stock cannot be brought to the machine, portable bandsaws offer the option of taking the machine to the work.

IS THIS NOTED IN YOUR ISA/PHA?

Is the object being cut secured?

Are GFI's installed, labeled, and operating correctly?

Is the blade correct for the application and has it been correctly mounted and tightened before use?

Is the electrical cord damaged or showing signs of excessive wear?

Does the START / STOP control function properly?

Are there any worn or damaged mounting accessories?

Are stops in place and in good condition?

Do you have all the PPE required for the job?

DO:

- Wear appropriate PPE.
- Use clamps or other safe ways to secure and support the work piece on a stable platform.
- Avoid accidental starting. Be sure the switch is OFF before plugging in.
- Make sure the portable band saw is clean before using.
- Remove adjusting keys or wrenches before turning the tool on.
- Wait until the motor has reached full speed before starting a cut.
- Support both pieces before cutting. Do not let large pieces free fall.
- Keep hands away from cutting area and blade.
- Check for misalignment or binding of moving parts, breakage of parts, or any other condition that may affect the tools operation.
- Utilize fence when cutting.
- Keep hands on handles during cutting operations.
- Disconnect plug from power source before making any adjustments, changing accessories, or storing the tool.
- Keep cord away from heat, oil, sharp edges or moving parts.

- · Use an approved outdoor extension cord.
- Maintain tools with care. Keep cutting tools sharp and clean.
- Always operate the port-a-band saw with two (2) hands.

- Never remove the grounding prong or modify the plug in any way. Do not use any adapter plugs.
- Don't force tool. Use the correct tool for your job.
- Never expose electric power to rain or wet conditions.
- Don't abuse the cord. Never use the cord to carry the tool or pull the plug from an outlet.
- Never overreach. Keep proper footing and balance at all times.
- Don't use tool if START / STOP switch does not work.
- Never modify and/or use this tool for any application other than for which it was designed.
- Don't work on unsecured materials.

Electrical Tools SAWS: RECIPROCATING SAW (SAWZALL)



A reciprocating saw is a type of saw in which the cutting action utilizes a push and pull reciprocating motion of the blade. Reciprocating saws are most useful for making quick, crude cuts.

IS THIS NOTED IN YOUR ISA/PHA?

Are guards present and firmly attached?

Is the saw housing in good condition?

Is the work area clean and are cords routed in a manner not to create tripping hazards?

Does the blade show signs of excessive wear or missing teeth?

Is the electrical cord damaged or showing signs of excessive wear?

Is the saw effectively grounded?

Are there any worn or damaged mounting accessories?

Do you have all the PPE required for the job?

DO:

- · Wear appropriate PPE.
- Use an approved outdoor extension cord.
- Avoid accidental starting. Be sure switch is OFF before plugging in.
- Use clamps or other safe ways to secure and support the work piece on a stable platform.
- Disconnect the plug from power source before making adjustments, changing accessories, or storing tool.
- Maintain tools with care. Keep cutting tools sharp and clean.
- Check for misalignment or binding of moving parts, breakage of parts, and any other condition that may affect the tool's operation.

- Don't remove the grounding prong or modify the plug in any way.
- Never force tool. Use the correct tool for your job.
- Don't expose power tools to rain or wet conditions.
- Never abuse the cord. Never use the cord to carry the tool or pull the plug from an outlet.
- Don't overreach. Keep proper footing and balance at all times.
- Never use tool if ON/OFF switch does not work properly.
- Don't operate this tool it if becomes too hot to touch with bare hand.

Electrical Tools SAWS: CHOP SAW

A chop (or miter) saw is used to make accurate cross cuts in wood, plastic, and light metals. It has a fixed blade attached to a moving arm which spins over a small worktable. The operator lines up the piece to be cut and lowers the saw blade.



IS THIS NOTED IN YOUR JSA/PHA?

Are the guards in position and in good working condition before operating?

Does the swing arm and movable saw parts function properly?

Is work area clean and are cords routed in a manner not to create tripping hazards?

Is the cutting blade in good working order and properly aligned?

Is the electrical cord damaged, show signs of excessive wear or damage to prongs?

Do you have all the PPE required for the job?

DO:

- · Wear appropriate PPE.
- Use an approved outdoor extension cord.
- Avoid accidental starting. Be sure switch is OFF before plugging in.
- Use clamps or other safe ways to secure and support the work piece on a stable platform.
- Disconnect the plug from power source before making adjustments, changing accessories, or storing tool.
- Maintain tools with care. Keep cutting tools sharp and clean.
- Check for misalignment or binding of moving parts, breakage of parts, and any other condition that may affect the tool's operation.

DON'T:

- Don't remove the grounding prong or modify the plug in any way. Do not use any adapter plugs.
- Never force tool. Use the correct tool for your job.
- Don't expose power tools to rain or wet conditions
- Never abuse the cord. Never use the cord to carry the tool or pull the plug from an outlet
- Don't overreach. Keep proper footing and balance at all times.
- Never use tool if ON/OFF switch does not work properly.
- Don't reach into the cutting area until the blade comes to a full stop.
- Never reach underneath the work. The guard cannot protect you from the blade below the work.
- · Don't use damaged blades.
- Never use circular saw blades or any other toothed blades with an abrasive cutoff saw.

(NOTE: THERE ARE METAL CUTTING SAWS THAT USE TOOTHED BLADES. THEY ARE PURPOSE BUILT AND MATCHED TO THEIR COMPONENTS. PLEASE VERIFY WITH APPROPRIATE PERSONNEL PRIOR TO USE IF UNSURE).

Electrical Tools SAWS: CIRCULAR SAW

DEWALT DATES

A circular saw is handheld electrical power saw with a rotating saw blade.

IS THIS NOTED IN YOUR JSA/PHA?

Is the retracting lower blade guard in good condition and moves freely?

Is the saw blade mounted for proper rotation?

Is the blade locked in at a depth so that the lowest tooth does not extend more than about $0.3 \, \text{cm}$ or 1/8" beneath the wood.

Are extension cords properly sized for electrical load? (15AMP)

Are all cords in good condition (no frays, splits or tears)?

Are work platforms stable, level and free from clutter?

Is there adequate ventilation in the work area?

Do you have all the PPE required for the job?

DO:

- Wear appropriate PPE.
- Keep cord away from heat, oil, sharp edges, and moving parts.
- Use an approved outdoor extension cord.
 Avoid accidental starting. Be sure switch
- Avoid accidental starting. Be sure switc is OFF before plugging in.
- Use clamps or other safe ways to secure and support the work piece on a stable platform.
- Disconnect the plug from power source before making adjustments, changing accessories, or storing tool.
- Maintain tools with care. Keep cutting tools sharp and clean.
- Check for misalignment or binding of moving parts, breakage of parts, and any other condition that may affect the tool's operation.
- Check lower guard for proper closing before each use.
- Check operation and condition of the lower guard spring.
- Use blades with correct size and shape arbor holes (diamond vs. round).
- Use extra caution when making a "pocket cut" into existing walls or other blind areas.

- Don't remove the grounding prong or modify the plug in any way. Do not use any adapter plugs.
- Never force tool. Use the correct tool for your job.
- Don't expose power tools to rain or wet conditions.
- Never abuse the cord. Never use the cord to carry the tool or pull the plug from an outlet.
- Don't overreach. Keep proper footing and balance at all times.
- Never use tool if ON/OFF switch does not work properly.
- Don't operate saw if lower guard does not move freely and close instantly.
 Never clamp or tie the lower guard into the open position.
 - Never use dull or damaged blades.
- Don't use damaged or incorrect blade washers or bolts.
- Never reach into the cutting area until the blade comes to a full stop.
- Don't reach underneath the work. The guard cannot protect you from the blade below the work.
- Never hold piece being cut in your hands or across your legs.

Electrical Tools HAND DRILL



Hand drills are used for boring holes in wood, concrete, steel or other construction materials. Here are two types of hand drills: Manual and power drills (corded, pneumatic or battery powered).

IS THIS NOTED IN YOUR ISA/PHA?

Is the drill housing in good condition?

Does the bit show signs of excessive wear?

Is the hand drill the right tool for the job?

Is the size and capacity of the tool adequate for the work being performed?

For pneumatic drills: Is air hose in good condition and properly secured?

Is the electrical cord damaged or showing signs of excessive wear?

Is each electrically operated hand drill effectively grounded?

Is the chuck in good working order?

Do you have all the PPE required for the job?

DO:

- Wear appropriate PPE.
- Keep cord/ hose away from heat, oil, sharp edges, and moving parts.
- Use an approved outdoor extension cord.
 Use clamps or other safe ways to secure
- Use clamps or other safe ways to secure and support the work piece on a stable platform.
- Disconnect the plug / hose from power source before making adjustments, changing accessories, or storing tool.
- Maintain tools with care. Keep bits sharp and clean.
- Check for misalignment or binding of moving parts, breakage of parts, and any other condition that may affect the tool's operation.
- Remove adjusting / chuck key before turning the tool on.
- Be aware that drill bits can "grab" during the cut. Use body and hand positions that will prevent the drill from running into something. Always use the side handle.
- Keep handle dry, clean, and free from oil or grease to ensure control of the tool.
- Hold tool by insulated gripping surface to ensure personal safety.

- Be aware of the drill bit binding by maintaining a firm grip on the tool.
- Pneumatic power tools shall be secured to the hose or whip by some positive means to prevent the tool from becoming accidentally disconnected.

- Don't remove the grounding prong or modify the plug in any way.
- Never force tool. Use the correct tool for your job.
- Don't expose power tools to rain or wet conditions.
- Never abuse the cord. Never use the cord to carry the tool or pull the plug from an outlet.
- Don't overreach. Keep proper footing and balance at all times.
- Never use tool if ON/OFF switch does not work properly.
- Don't operate drill if it becomes too hot to touch with bare hand.

Electrical Tools MAGNETIC DRILL

Magnetic base drills are a specialized type of drill primarily for drilling metal. The magnetic base secures firmly to the metal to be cut, ensuring that the drill can accurately bore through the metal.

IS THIS NOTED IN YOUR JSA/PHA?

Are the guards in position and in good working condition before operating?

Is the drill base and hardware in good repair?

Is the work area clean and are cords routed in a manner not to create tripping hazards?

Is the tool secured in the event of power loss and the power cord tagged or clearly identified?

Is the drill bit size less than or equal to the rated capacity of the magnetic drill?

Is the magnetic drill set up as to avoid awkward operations and hand positions?

Is the size and capacity of the tool adequate for the work being performed?

Is the electrical cord damaged or showing signs of excessive wear?

Is each electrically operated magnetic drill effectively grounded?

Is there enough room around the machine to do the job safely?

DO:

- Wear appropriate PPE.
- Keep cord away from heat, oil, sharp edges, and moving parts.
- · Use an approved extension cord.
- Use clamps or other safe ways to secure and support the work piece on a stable platform.
- Place the unit on a surface that is clear of shavings, chips or dirt to allow for optimum magnetic hold.
- Be sure that the drill press is plugged into the correct voltage system and is grounded correctly and a safety chain is attached.
- Remove adjusting / chuck key before turning the tool on.
- Be aware that drill bits can "grab" during the cut.
- Disconnect the plug from power source before making adjustments, changing accessories, or storing tool.
- Check for misalignment or binding of moving parts, breakage of parts, and any other condition that may affect the tool's operation.

- Maintain tools with care. Keep bits sharp and clean.
- Use only accessories recommended by the manufacturer.
- Attach safety chain to magnetic drill when you are using them in elevation.

- Don't remove the grounding prong or modify the plug in any way.
- Never force tool. Use the correct tool for your job.
- Don't expose power tools to rain or wet conditions.
- Never abuse the cord. Never use the cord to carry the tool or pull the plug from an outlet.
- Don't overreach. Keep proper footing and balance at all times.
 - Never use tool if ON/OFF switch does not work properly.

Electrical Tools PIPE THREADER

Pipe Threading machines thread and cut pipe, as well as bar stock and power roll grooving equipment. Follow instructions on proper use of threading machines.



IS THIS NOTED IN YOUR ISA/PHA?

Is the foot switch present and does it turn the machine off when released?

Are all electrical connections dry and off the ground?

Is the work area clean and are cords routed in a manner not to create tripping hazards?

Are the cutting dies in good working order and properly installed?

Is the threading machine barricaded when material extends past the machine?

Is the size and capacity of the tool adequate for the work being performed?

Is the proper cutting oil or lubricant for the job available and being used?

Is the electrical cord damaged or worn excessively?

Are you familiar with the safe operation of the threading machine you are using?

Is there enough room around the machine to do the job safely?

Do you have all the PPE required for the job?

DO:

- Wear appropriate PPE.
- Keep cord away from heat, oil, sharp edges, and moving parts.
- Replace damaged cords immediately.
- · Secure machine to bench or stand.
- Keep floors dry and free of slippery materials such as oil.
- Guard or barricade the area when work piece extends beyond machine.
 Avoid accidental starting. Be sure switch is OFF
- Avoid accidental starting. Be sure switch is OFI before plugging in.
- Tighten chuck handwheel and engage rear centering device on the pipe before turning on the machine.
- Operate machine from side with REV/OFF/FOR switch.
- Use proper lubricating fluid to extend the life of the cutting dies.
- Keep hands away from rotating pipe and fittings.
- Stop the machine before wiping pipe threads or screwing on fittings. Allow the machine to stop completely before touching the pipe or machine chucks.
- Disconnect the plug from power source before making adjustments, changing accessories, or storing tool.
- Maintain tools with care. Keep cutting tools sharp and clean.

- Check for misalignment or binding of moving parts, breakage of parts, and any other condition that may affect the tool's operation.
- · Lock foot switch when machine is not in use.
- Use only accessories that are approved for the specific machine you are using.

- Don't remove the grounding prong or modify the plug in any way.
- Never force tool. Use the correct tool for your job.
- Don't expose power tools to rain or wet conditions.
- Never abuse the cord. Never pull the plug from an outlet
- Don't overreach. Keep proper footing and balance at all times.
 - Never use tool if ON/OFF switch does not work properly.
- Don't operate the machine with covers removed.
 Exposure to moving parts may result in entanglement and serious injury.
- Never use this machine to make or break fittings.
- Don't use this machine if the foot switch is broken or missing.

Electrical Tools WELDING MACHINE

Welding machines are the primary tool in fabrication, providing the source of electrical spark to create the arc between the gas, filler material and material being welded. Effective grounding of the machine is critical, as is properly securing the gas tanks and cylinders.

IS THIS NOTED IN YOUR JSA/PHA?

Are all the connections tight, including the earth ground?

Are the electrode holder and welding cable free of defects or repairs?

Is the work area clean and are cords routed in a manner not to create tripping hazards?

Is the original enclosure and fan guarding in place?

Are the cables the right size for your job? Be sure any damaged cable insulation is replaced.

Are the leads spread out and run neatly to prevent overheating?

Is there enough dry insulation between your body and the work piece?

Is there adequate ventilation in your work area?

Is the work stable and easy to reach from where you are standing?

Are the work area conditions such that normal safety precautions can be observed?

Do you have all the PPE required for the job?

CONTINUED ON PAGE 57

Electrical Tools WELDING MACHINE

CONTINUED

DO:


- Wear appropriate PPE.
- Use only grounded or double insulated equipment.
- Verify that welding machine has functioning GFCI in place for power supply.
- Verify the supply ground. Connect equipment grounding terminal to a proper earth ground.
- Use only well maintained and properly operating equipment.
- Keep all doors, panels, covers, and guards closed and securely in place.
- Turn off or unplug all electrical equipment connected to generator power receptacles before starting or stopping the engine.
- Use protective screens or barriers to protect others from flash and glare; warn others not to watch the arc.
- Ensure gas tanks / cylinders are properly chained to the machine or on a tank cart.
- Verify that cables are not pinched under forklifts, hand trucks or other moving equipment.
- Keep away from moving parts such as fans, belts, and rotors.
- Follow hex chrome procedures when welding an alloy metal.
- Insulate yourself from work and ground using dry insulating mats or covers big enough to prevent any physical contact with the work or ground.
- Work in a confined space only if it is well ventilated, or while wearing an airsupplied respirator.
- Clamp work cable with good metal to metal contact to work piece or work table as near the weld as practical.
- Insulate work clamp when not connected to work piece to prevent contact with any metal object.
- Disconnect both welding cables to prevent live electrode from causing electric shock and fire hazards if using generator power only and not welding.



- Watch for fire, and keep a fire extinguisher nearby.
- Disconnect input power or stop engine before inspecting, servicing or reconnecting welding machine.
- Inspect electrical cables and power cables regularly for fraying or other problems.
 Replace cord immediately if damaged.
- · Turn off all equipment when not in use.

- Don't operate the machine if the ON / OFF switch does not work properly.
- Never use worn, damaged, undersized, or poorly spliced cables.
- Don't connect to any electrical distribution system normally supplied by utility power unless a proper transfer switch and grounding procedure are employed.
- Never use AC output in damp areas, if movement is confined, or if there is a danger of falling.
- · Don't drape cables over your body.
- Never touch electrode if you are in contact with the work, ground, or another electrode from a different machine.
- Don't touch live electrical parts.
- Never touch the torch or electrode clamp simultaneously with the earth clamp.
- Don't point gun (MIG) toward any part of your body, other people, or any metal when threading welding wire.
- Never add fuel near an open flame or welding arc or when the engine is running.
- Do not attempt to move a welding machine trailer from the side with a forklift.

Electrical Tools IMPACT WRENCH



IS THIS NOTED IN YOUR JSA/PHA?

Have you checked the hose for wear, and made sure that all connections are secure?

Is the work area clean and are hoses routed in a manner not to create tripping hazards?

Has the impact wrench been calibrated and inspected prior to use?

Is the size and capacity of the tool adequate for the work being performed?

Is the trigger in the "OFF" position before connecting to the air supply?

Is the retaining ring properly installed if required?

Is the impact socket specifically designed for the particular impact wrench?

Do you have all the PPE required for the job?

DO:

- · Wear appropriate PPE.
- Keep hoses away from heat, oil, sharp edges, and moving parts.
- Ensure wrench air valve (or trigger) is in the "off" position before connecting to the air supply.
- Disconnect tool from power source before making adjustments, changing accessories, or storing tool.
- · Maintain tool with care.
- Check for misalignment or binding of moving parts, breakage of parts, and any other condition that may affect the tool's operation.
- Maintain correct balance and footing.
- Check air hose for wear before use and ensure that all connections are secure.
- · Check for correct air pressure.
- Drain the compressor air tank daily. Water in the air line will damage the wrench.
- Always use appropriate retaining rings if required.

- Never use tool if ON / OFF switch does not work properly.
- Don't use wrench if damaged or thought to be faulty.
- Never use worn, or damaged sockets.
- Don't use without an approved socket retainer; do not use improvised retainers.
- Never carry wrench with your hand on the trigger to prevent unintentional starting.
- Don't carry the wrench by the air hose, or yank the hose from the air supply.
- Never overreach. Keep proper footing and balance at all times.
- Don't direct air from the air hose at yourself or others.
- Don't use an Impact Wrench as a hammer or hit it with a hammer.

Pneumatic and Hydraulic Tools AIR TORQUE WRENCH

This high speed tool puts out more torque then a regular pneumatic impact wrench. Several size drives are common

in our workplace, including %", 1" and $1 \frac{1}{2}$ " drives. It is important to review the air pressure chart supplied by the manufacturer to ensure you have selected the correct tool for the job.

IS THIS NOTED IN YOUR JSA/PHA?

Have you checked the hose for wear, and made sure that all connections are secure?

Is the work area clean and are hoses routed in a manner not to create tripping hazards?

Has the wrench been calibrated and well maintained prior to used?

Is the size and capacity of the tool adequate for the work being performed?

Is the trigger in the "OFF" position before connecting to the air supply?

Is the socket designed for the specific wrench?

Have you verified the charts for the wrench to ensure proper pressure settings?

Do you have all the PPE required for the job?

DO:

- Wear appropriate PPE.
- Keep hoses away from heat, oil, sharp edges, and moving parts.
- Ensure wrench air valve (or trigger) is in the "off" position before connecting to the air supply.
- Disconnect tool from power source before making adjustments, changing accessories, or storing tool.
- · Maintain tool with care.
 - Check for misalignment or binding of moving parts, breakage of parts, and any other condition that may affect the tool's operation.
- Maintain correct balance and footing. Ensure the floor is not slippery and wear non-slip shoes.
- Check air hose for wear before use and ensure that all connections are secure.
- Drain the compressor air tank daily. Water in the air line will damage the wrench.
- Make sure oil lubricator has correct oil levels before using tool.
- Make sure reaction arm is sitting properly against flange.
- Make sure wrench has pressure charts to set air pressure to proper torque.
- Pneumatic power tools shall be secured to the hose or whip by some positive means to prevent the tool from becoming accidentally disconnected.
- · Check calibration date prior to use.

- Never use tool if ON/OFF switch does not work properly.
- Don't use wrench if damaged or thought to be faulty.
- Never use worn, or damaged sockets.
- Don't use without an approved socket retainer; do not use improvised retainers.
- Never carry wrench with your hand on the trigger to prevent unintentional starting.
- Don't carry the wrench by the air hose, or yank the hose from the air supply.
- Never overreach. Keep proper footing and balance at all times.
- Don't direct air from the air hose at yourself or others.
- · Never use if hoses are leaking air.
- Never use if direct torque cannot be regulated.
 Don't operate if tool doesn't have a place to rest
- Don't operate if tool doesn't have a place to res reaction arm.

Pneumatic and Hydraulic Tools HYDRAULIC TORQUE WRENCH



A hydraulic torque wrench uses hydraulics to exert torque on a fastener to achieve proper tightening or loosening of a connection. Hydraulic torque wrenches typically offer a high degree of accuracy and repeatability. A good and solid support is the first requirement for safe use.

IS THIS NOTED IN YOUR ISA/PHA?

Do you have all the proper tools for the job?

Have all users been trained in Torque Training?

Have you inspected all hydraulic hoses, quick connects, pump, impact sockets and accessories for damages prior to use?

Is the work area clean and are hoses routed in a manner not to create tripping hazards?

Is the proper size socket being used?

Is there enough clearance for the job to be performed?

Do you have all the PPE required for the job?

CONTINUED ON PAGE 61

Pneumatic and Hydraulic Tools HYDRAULIC TORQUE WRENCH

CONTINUED

DO:

- · Wear appropriate PPE.
- Keep hoses away from heat, oil, sharp edges, and moving parts.
- Ensure trigger is in the "off" position before connecting to the pump.
- Disconnect tool from power source before making adjustments, changing accessories, or storing tool.
- · Maintain tool with care.
- Check for misalignment or binding of moving parts, breakage of parts, and any other condition that may affect the tool's operation.
- Maintain correct balance and footing.
- Check hoses for wear before use and ensure that all connections are secure
- Avoid sharp bends and kinks that will cause back-up pressure in hoses or lead to premature hose failure.
- Only use impact sockets designed for use with the specific wrench.
- Use proper mechanical support and correct reaction arm positioning to control forces.
- Keep hands away from the boot and reaction bar.
- Use the quick connect system to attach the hoses to the tool and pump.
- Use proper hand signals as your primary method of communication. If hand signals are not applicable, voice command should be "STROKE" to activate and "RETRACT" to deactivate.
- Inspect sight glass of pump to make sure oil levels are adequate.
- Use compressed air only Never use combustible gases or steam as a power source.
- Pneumatic power tools shall be secured to the hose or whip by some positive means to prevent the tool from becoming accidentally disconnected.



- Never use tool if ON / OFF switch does not work properly.
- Don't use wrench or sockets if damaged, worn, or thought to be faulty.
- Never carry the wrench by the hose, or yank the hose from the pump.
- Don't overreach. Keep proper footing and balance at all times.
- Never use damaged, frayed or deteriorated hoses and fittings.
- · Don't place hands near reaction arm.
- Never position the reaction arm so that it tilts the tool off axis of the bolt.
- Never use the uni-swivel coupling as a reaction point.

Pneumatic and Hydraulic Tools **AIR CHISEL**



An air chisel is a cutting and driving tool powered by compressed air that can be used to break or cut metal objects. It is also used for smoothing metal that has been roughed, shaped or formed.

IS THIS NOTED IN YOUR JSA/PHA?

Is the air supply clean and under 125 psi?

Is the trigger in the "OFF" position before connecting to the air supply?

Does the tool have an inline oiler?

Have you checked the hose for wear, and made sure that all connections are secure?

Is the work area clean and are hoses routed in a manner not to create tripping hazards?

Is the size and capacity of the tool adequate for the work being performed?

Do you have all the PPE required for the job?

DO:

- Wear appropriate PPE.
- Keep hoses away from heat, oil, sharp edges, and moving parts.
- Ensure trigger is in the "off" position before connecting to the air supply.
- Disconnect tool from power source before making adjustments, changing accessories, or storing tool.
- · Maintain tool with care.
- Check for misalignment or binding of moving parts, breakage of parts, and any other condition that may affect the tool's operation.
- Maintain correct balance and footing.
- Check air hose for wear before use and ensure that all connections are secure.
- Check correct air pressure is maintained and not exceeded.
- Inspect air hose for wear before each use and ensure that all connections are secure.
- Keep the handle clean, dry, and free from oil and grease at all times.
- Be sure the trigger is not depressed when carrying the Air Chisel to avoid unintentional starting.

- Use compressed air only Never use combustible gases or steam as a power source.
- Never use tool if ON / OFF switch does not work properly.
- Don't use chisel if damaged or thought to be faulty.
- Pneumatic power tools shall be secured to the hose or whip by some positive means to prevent the tool from becoming accidentally disconnected.

- Never carry chisel with your hand on the trigger to prevent unintentional starting.
- Don't carry the chisel by the air hose, or yank the hose from the air supply.
- Never overreach. Keep proper footing and balance at all times.
- Don't direct air from the air hose at yourself or others.
- Never use if hoses are leaking air.
- Don't allow air chisel to free run as this will reduce bearing life.

Pneumatic and Hydraulic Tools **AIR MOVER**

Air movers (or "blowers") are used to disperse hazardous fumes, move air into a confined space, cool individuals in high temperature conditions, and / or ventilate equipment and machinery.

IS THIS NOTED IN YOUR ISA/PHA?

Have you visually inspected the air mover for damaged, worn, or broken parts?

Have you checked the air hoses for wear, and made sure that all connections are secure?

Is the air supply clean and under 125 psi?

Is the work area clean and are hoses routed in a manner not to create tripping hazards?

Is the air blower properly mounted and secured?

Is the air flow in the proper direction? (out of the vessel)

Do you have all the PPE required for the job?

DO:

- Wear appropriate PPE.
- Keep hoses away from heat, oil, sharp edges, and moving parts.
- Keep the blower clean and properly serviced.
- Inspect the blower before use for damaged, worn, loose and / or broken parts.
- Check air hose for wear before use and ensure that all connections are secure.
- Check that the correct air pressure is maintained and not exceeded.
- · Secure the device while in use.
- Use proper lifting techniques when moving or carrying blower.
- Use compressed air only Never use combustible, inert gases or steam as a power source.
- Disconnect the blower from the air supply before attempting to service or move the blower.
- Disconnect blower from power source before making adjustments, changing accessories, or storing.

- Don't direct air from the air hose towards yourself or others.
- Never use if hoses are leaking air.
- Don't operate the blower without the inlet and outlet screens properly secured and in place.
- Don't stand directly in front of and / or face the blower outlet.
- Never hook Air Mover up to anything other than an air source.
- · Don't use without proper grounding.

Other Tools JACK STAND

Jack stands support material such as pipe. The standard unit has a steel V-head on a threaded shaft for fine adjustment. Special application heads include bar stick roller head, dual wheel roller head. or ball caster transfer head.



IS THIS NOTED IN YOUR JSA/PHA?

Are all of the components present and operating properly?

Is the jack stand set up on a flat, stable surface?

Is the jack stand rated for the load weight?

Is the jack stand head sufficient to safely hold the pipe's diameter?

Do you have a sufficient number of jack stands to support the load?

Is the height of the jack stand at the center of travel?

Do you have all the PPE required for the job?

DO:

- · Wear appropriate PPE.
- · Inspect jack stand before use.
- · Set up jack stand on flat, stable surface.
- Use plywood or planks to ensure a good working surface.
- Use T-Handle to raise and lower jack stand.
- Verify that the load washer and locking mechanism are in place and secure.
- Confirm the head is appropriate for the application.
- Verify the pipe load weight before setting on jack stand, and ensure there are enough stands to safely support the load
- When using multiple stands, confirm that all are adjusted to the same height.
- Check your weight the 3 leg stands are rated for up to 2500#'s while the 4 leg can handle up to 6000#'s.

- Don't use a jack stand for any purpose other than for which it was designed.
- Never roll pipe on a jack stand unless jack stand has roller head.
- Don't stack multiple jack stands on top of each other.
- Never release a load with the locking washer; use the screw adjustment on the head.
- · Don't overload your stands.
- · Never modify a jackstand.
- Don't place pipe larger than 8" in diameter on the jack stand.
- Don't use a 4 leg jack stand for anything other than pipe.

Other Tools CUTTING TORCH



IS THIS NOTED IN YOUR ISA/PHA?

Are all users trained in the safe operation of the cutting torch?

Do you have all the proper tools for the job?

Do you have a fire extinguisher readily available?

Have you inspected the oxygen tank, the acetylene tank and the hoses for damage or wear?

Are the acetylene and oxygen bottles secure and stored in an upright position?

Have you secured the material to be cut to an adequate support at a comfortable working height?

Have you referred the torch tip chart and selected the proper tip for the material (page 138)?

Have you reviewed the torch tip chart for the proper gas pressures for the tip selected?

Are you wearing tinted torch goggles and/or a face shield?

Do you have the proper gloves?

Is your area clean and well lit?

Do you have all the PPE required for the job?

DO:

- Wear appropriate PPE.
- · Secure cylinders to a cart, wall, or post to prevent them from falling. All cylinders should be used and stored in an upright position.
- Ensure the torch is well maintained and serviced.
- Check for loose gas connections, hose leaks, damage, or any other condition that may impair the cutting torch operation.
- · Use clamps or other safe ways to secure and support the work piece to a stable platform.
- · Point the cutting tip away from yourself and others when lighting. Avoid exposure to fumes and gases, by
- keeping your head out of the fumes.
- Have a fire extinguisher of the proper size and type in the work area.

- Don't use a torch for any purpose other than for which it was designed.
- Never operate an acetylene cutting torch in explosive atmospheres, such as in the presence of flammable liquids, gases, or dust.
- Don't use the cutting torch if the tool or the hoses are worn, damaged or not properly functioning.
- Never touch the tip or weld until cool.
- Don't adjust acetylene pressure above 15 psi.
- Never use oil or grease on connections.
- Don't use a torch as a hammer

Other Tools **BEVELING MACHINE**



Beveling machines deliver accurate and swift pipe cutting and beveling, saving weld prep time compared to hand beveling. Made of hard-anodized aluminum, these machines are both lightweight and durable.

IS THIS NOTED IN YOUR JSA/PHA?

Are users trained in the safe operation of the beveling machine?

Do you have all the proper tools for the job?

Do you have the proper type and size fire extinguisher available in case of a fire?

Is the pipe to be cut secured to a table or pipe stand prior to starting?

Have you checked for loose gas connections, hose leaks, or any other condition that may affect the machine's operation?

Is your area clean and clear of all possible tripping hazards?

Do you have the proper hand protection to proceed with the job?

Do you have all the PPE required for the job?

CONTINUED ON PAGE 67

Other Tools **BEVELING MACHINE**

CONTINUED



- · Wear appropriate PPE.
- Secure cylinders to a cart, wall, or post to prevent them from falling. All cylinders should be used and stored in an upright position.
- Ensure the torch is well maintained and serviced.
- Check for loose gas connections, hose leaks and damage, any other condition that may affect the beveling machine operation. If damaged, have it serviced before using.
- Use heat-resistant shields to protect nearby walls from sparks and hot material.
- Adequately ventilate area to prevent the concentration of dangerous fumes.
- Ensure pipe is firmly secured to a table, pipe stand, or other device prior to starting.
- Point the cutting tip away from yourself and others when lighting.
- Rotate Torch one full turn around the pipe to be sure torch tip will not contact the pipe.
- Avoid exposure to fumes and gases, by keeping your head out of the fumes.
- Keep hands and feet as far from the path of the beveling machine as possible.
- Inspect the general area for flame or smoldering materials when work has been completed.
- Have a fire extinguisher of the proper size and type in the work area.



- Don't use the machine for any purpose other than for which it was designed.
- Never operate a beveling machine in an explosive atmosphere, such as in the presence of flammable liquids, gases, or dust.
- Don't use the tool if it, or the hoses, are worn, damaged or not properly functioning.
- Never direct flame or debris associated with cutting process toward the oxygen or fuel gas cylinders.
- Don't lubricate the beveling machine or use oil or grease on connections.
- Never attempt to remove metal slag from cutting area while machine is in operation.

Other Tools PORT-A-POWER

Port-a-Power tools provide hydraulic power in a portable format for situations where material needs in place modifications. They can be used to deliver hydraulic power in order to straighten, bend, lift, or modify metal material.



IS THIS NOTED IN YOUR JSA/PHA?

Is the hydraulic Port-a-Power set on a hard and level surface?

Have you inspected the Port-a-Power for damage before use?

Is the load centrally located to attachment or ram saddle, and secure?

Have you purged the air from the Port-a-Power by pumping the handle a few strokes before use?

Is the size and capacity of the tool adequate for the work being performed?

Is there enough clearance for the job to be performed?

Do you have all the PPE required for the job?

DO:

- · Wear appropriate PPE.
- Locate machine only on a hard, level surface capable of sustaining rated capacity loads.
- · Keep ram clean at all times.
- · Use only approved grade hydraulic oil.
- Use only approved accessories.
- Use shims, friction material or constraints to prevent slippage of the base or load.
- Ensure object is securely and safely located in ram saddle.
- · Monitor pressure and load at all times.
- Avoid pinch points or crush points created by the load or parts of ram.
- Keep the piston(s) fully retracted when the ram is not is use.

- Don't use the machine for any purpose other than for which it was designed.
- Don't modify this device.
- Never use the tool, rams or hoses if they are worn, damaged or not properly functioning.
- Never attach an accessory not authorized by manufacturer.
- Don't exceed the rated capacity of the ram.
- Never use tool as a vehicle lifting device or vehicle support.
 - Don't locate loads off-center on the ram.
- Never allow personnel to work on, under or around a load before it is properly supported by appropriate mechanical means.
- Don't allow the hose to kink, twist, curl, crush, cut or bend so that the fluid flow within the hose is blocked or reduced.
- Never place hands under suspended loads.
- Don't open oil filler screw unless ram is fully retracted.
- Never attempt to grasp a leaking pressurized hose with your hands.
- Don't disassemble a hydraulic cylinder.

Other Tools COME-A-LONG AND CHAIN FALL



A Ratchet Lever Hoist or "Come-A-Long" is used for lifting or lowering a load by means of a drum or lift-wheel around which rope or chain wraps. A Chain fall is used for the same purpose, and consists of a lift chain, pinion, sheaves and hook.

IS THIS NOTED IN YOUR JSA/PHA?

Do you have all the proper tools for the job?

Is the Come-A-Long or hoist properly installed to a fixed point?

Is the fixed point rated for the load being lifted?

Have you inspected Come-A-Long or chain fall for any evidence of worn, corroded, cracked, or distorted parts such as suspension housing, chain attachments, yokes suspension bolts, shafts, gears, bearings, pins, rollers and locking and clamping devices?

Are the load slings or other approved single attachments properly sized, rigged, and seated in the hook saddle?

Have you checked that the fixed suspension point rests on the center of the hook's saddle and that the hook's latch is engaged?

Have you verified that the load chain is not twisted and tangled prior to operating the hoist.

Is the load clear of any obstruction?

Have you barricaded the area below the lift point and warned nearby personnel before lifting or moving a load?

Do you have all the PPE required for the job?

DO:

- · Wear appropriate PPE.
- Inspect the come-a-long and area prior to use and return damaged or worn devices.
- Inspect chain falls regularly, paying particular attention to possible distortion and wear especially to the ratchet, pawl, chain and hook.
- If the secure latch and hook are not touching remove the come-a-long from service.
- Ensure adequate space to permit the operator and other persons to stand clear of the load and adjacent structures.
- Check the load before raising or pulling to see that it is held securely in the hook or sling.
- Be sure there are no twists in the load chain.
- Ensure everyone is clear of the chain when under a load.
- Keep constant communication during lift.
- Check for card inspection prior to use.

- Don't operate a hoist which has been modified or is damaged.
- Never operate hoist from an unsecured or off balance position.
- Don't lift more than rated load for the hoist or
- operate beyond the limits of the load chain travel.

 Never lengthen the load chain or repair a
- damaged load chain or hand chain.

 Don't use tool in a way that causes either hook to
- be side loaded, and never side load the hoist.
 Never apply the load to the tip of the hook or to
- the hook latch.
 Don't wrap the load chain around a load. Use a sling.
- Don't wrap the load chain around a load. Ose a sing.
- Never use hoist if hook latch is missing or malfunctioning.
- Don't use a handle extender (cheater bar).
- Never swing the load or hook.
- Don't use the hoist to lift, support, or transport people.
- Never lift loads over people.
- Don't leave load supported by the hoist unattended unless specific precautions have been taken.
- Don't use hook for anything other than rigging.

Other Tools AIR TUGGER



Air tuggers are used primarily for moving and lifting heavy objects. It essentially is a portable winch in a lighter weight compact configuration.

IS THIS NOTED IN YOUR ISA/PHA?

Have you inspected the cable and air hoses?

Have you inspected the snatch block?

Have you made sure the in line oiler has oil and is at proper level?

Is the tugger located on a level, stable surface?

Do you have all the PPE required for the job?

DO:

- Wear appropriate PPE.
- Position machine only on a hard, level surface capable of sustaining rated capacity loads.
- Securely attach the machine with anchor bolts or rigging
- · Make sure the load is properly secured.
- Ensure everyone is clear of the cable when under a load.
- Keep constant communication between air tugger operator and rigging attendant.
- Always barricade the area and communicate with all affected employees in the area.

- Don't use the machine for any purpose other than for which it was designed.
 Don't modify this device.
- Never use the tool, or hoses, if they are worn, damaged or not properly functioning.
- Never attach an accessory not authorized by manufacturer.
- Don't exceed the rated capacity of the tugger.
- Never use tugger as a vehicle lifting device or vehicle support.
- · Don't use for overhead lifting.
- Never hold the cable within 10 ft. of the drum.



SECTION 4: QUALITY

QA/QC Guidelines

One of the major causes of poor work quality in the shop and field is poor communication and planning between inspection and supervision/management. What you say, how you say it, and your attitude have a tremendous effect on you and the people you encounter.

An "Us versus Them" environment will not serve the interest of either departments or the company owners, and it has proven to be the downfall of many turnarounds and projects. We are all working towards the same goal.

All of UPS's procedures and quality systems depend entirely on good communication between all office and field personnel. If they know where they're going, it can take a lot of unnecessary running around out of the daily activities.

UPS's Supervision, Inspection, and Safety should be in Lock-Step with each other to develop and promote Team Work.

The following steps are what we've found to be the best method of planning, communicating and meeting the QA/QC requirements for most jobs. While all of these steps may not apply to every job, they are items that need to be considered for every job.

Before Leaving For Job Site

- Call the project Manager and request a date for you to be on site, and then relay that information to the Quality Manager.
- Establish what training is required to gain site access and complete training before departure as required.
- Discuss the project with your Quality Manager, Get contact phone numbers for the Project Manager, Lead Piping Inspector, and Field Accountant.
- Establish the need for Laptop/Air Card/ Printer/Cell Phone for yourself and if you

- will need identical items for a mechanical lead (if applicable)
- Ensure required programs (C-spec, Weld Log, Flange Log) and all required forms are loaded onto laptop(s)
- Ensure inspectors coming onto the field have ASNT Level II, Flange Assembly, Flange Torquing certifications are up to date.

CONTINUED

SECTION 4: QUALITY

QA/QC Guidelines

Arriving at Job Site

- If you are the lead inspector make contact with the Project Manager.
- If you are a Project inspector make contact with the Lead Piping Inspector and request to meet the Project Manager.
- Sit down and discuss the project variables and the role you will play.
- Ask questions, take notes, clarify any topics you may not completely understand.
- Ask for a copy of the job scope/ project plan and any additional information you may need to set-up your job packages.
- Obtain copy of plant pipe specifications and engineering requirements.
- Make sure you completely understand how the above individuals want the job set- up and your responsibilities.

- ASK, If you're not sure, then you don't know.
- Determine which WPS's / PQR's will be used on this project and obtain copies from SharePoint. Contact the Quality Manager for assistance if new WPS's and PQR's are needed. Note: Be sure to inform the client and project manager of any associated cost.
- Get plant approval on proposed WPS's and PQR's
- Ensure you have copies of each welder's WPQ, and that welder continuity is up to date. Maintain the tip of the filler rod within the gas shroud during welding to avoid contamination.

Meet With Plant Inspection Group

- Find out who will be our contacts in plant inspection group and who will be the third party contact if applicable.
- Determine Package turnover and document control procedures/ requirements.
- Identify Code work and determine if a UPS Code stamp will be required.
- Contact the AI, if required or find out who is the plant or subcontracted API 510.
- Find out if a subcontractor or combination will be used for API 510
- Find out who is performing NDE, (self-performed, subcontractor or combination)

- Find out who will contact NDE company
- Get a list of approved subcontractors if required.
- Ask for team effort in developing a plan to sell final packages, document and distribute to all concerned parties to ensure agreement.
- Ask for this plan to be distributed to all day and night shifts for review and document agreement.
- Document the above information and ensure project manager has a copy, and is completely aware of plant requirements AI, NDE, and selling final packages.

CONTINUED

QA/QC Guidelines

Contact Plant Designated Contact for CODE Work

- Get approval for repair/scope plan and establish Hold Points, this includes contacting the Al for approval of repair/ scope plan prior to starting work.
- Establish NDE requirements per CODE package
- · Discuss the project inspection

- Manpower needs with the Project Manager.
- Don't let them overload your group, request the manpower you need
- Make sure that you have copies of the certifications for inspectors (PT, VT, Vision exams)

Requesting Inspectors to the Job Site

After studying the scope of work with the Project Manager, determine the quantity of Piping and Mechanical inspectors you will need for the project.

NOTE: The solicitation of any inspectors to job sites by any site personnel or Project Manager is prohibited. You may make a request to the Area Quality Systems Managers that certain individuals be sent to your job site. But this is a request only. Quality Managers will dispatch all inspectors to job sites, no exceptions are allowed. This policy is strictly enforced.

Contact Quality Manager by phone and e-mail and request inspection manpower, be sure to include arrival dates, safety council training requirements, laptop/air card /cell phone needs.

Additional Duties and Activities

- Divide inspection work and assign inspectors to foremen whenever possible. This keeps supervision and inspection working hand-in-hand or try to assign an inspector to an area.
- Lead inspector are to meet with supervision and document the meeting on the daily log.
- All inspectors are to meet with their assigned foremen at the beginning of each shift and stay in contact throughout the shift while developing a turnover report for their area.
- Turnover reports must be given to the lead inspector and updated (twice daily at a minimum) or as schedule requires. Individual inspector turnover reports are to be reviewed by the lead inspector each shift.

- Lead inspector must audit his own people daily.
- Build punch list from your inspectors turnover reports and distribute to operations.
- Communicate daily to operations QA/ QC priorities and document operations priorities to area inspectors.
- Stay in close contact with the Quality Manager; check in at least once every week.
- Let the Quality Manager know as soon as possible if additional inspectors are required on site.
- Maintaining contact will keep everyone informed of the project status and prevent inspection from falling behind.

SECTION 4: QUALITY

QA/QC

NDT TECHNIQUE	MATERIALS APPLICABLE	DETECTION CAPABILITY	DEPTH SIZING	ORIENTATION EVALUATION	ACCESS PROBLEM	REMOTE DETECTION	AUTOMATED DETECTION
Liquid penetrant	All	Surface	No	No	Yes	No	No
Ultrasonic	All	Volumetric	Yes	Yes	Limited	Yes	Yes
Radio- graphy	All	Volumetric	Yes	Yes	Yes	No	Yes
Magnetic Particle	Magnetic	Surface, near- surface	No	No	Yes	No	No
Magnetic Flux- leakage	Magnetic	Surface, near- surface	Yes	Yes	No	Yes	Yes
Eddy current	Conducting	Surface, near- surface	Yes	Yes	Yes	Yes	Yes
Acoustic Emission	All	Volumetric	Yes	No	No	Yes	Yes
Thermo- graphy	All	Surface, near- surface	No	Yes	No	Yes	Yes
Visual	AII	Surface	No	No	Limited	Yes	Yes
XRD	Conducting	Surface Stresses	Yes	No	Yes	No	No
Potential drop	Conducting	Surface	Yes	No	Yes	No	Yes

QA/QC

Engineering and Construction Codes and Standards

ASME IX - American Society of Mechanical Engineers PIPING ASME IX - B 31.3 PROCESS ASME IX - B 31.1 POWER PIPING

Material (P numbers) will assist the Welding Engineer to complete the Welding Procedure Specification prior to the mechanical testing of the Procedure Qualification Report.

P-Numbers	Material Composition
1	Carbon Steel
3	Carbon, 1/2 Mo
4	1.25 Cr.
5A	2.25 Cr
5B	5 Cr. & 9Cr.
6	Martensitic Stainless Steel, (410)
7	Ferritic Stainless Steel (410SS)
8	Austenitic Stainless Steel
10H	Duplex Stainless Steel
11	Low Alloy Steel, Quenched and Tempered to 95ksi+
15E	P91, 9Cr1Mo-V
21	1.2% Mg or Mn alloy Aluminum
22	1.2% Mn, 2.5% Mg, 0.25% Cu Aluminum
23	1.3% Mg, 0.7% Si, 0.25% Cr Aluminum
25	1.5% Mg, 0.8% Mn, 0.15 Cr Aluminum
31	Copper
32	Admirally, Naval, Aluminum Brass, Muntz Metals
33	Cu-Si Alloys
34	Cu-Ni Alloys
41	Nickel
42	Monel (400)
43	Inconel 600 series, Hastelloy 276
44	Hastelloy
45	Inconel 800 Series
51	Titanium
61	Zirconium

QA/QC

Approvals required prior to the commencement of welding operations.

- Welding Procedure Specifications.
- Procedure Qualification Reports.
 Welder Certification Certificates.
 Welding Consumables.
- · NDT Company.
- · NDT Operators.

- · NDT Procedures.
- · Radiation Safety.
- Post Weld Heat Treatment Company.
 Post Weld Heat Treatment Procedure.
- · Welding Inspection Personnel.
- · Welding Repair Procedure.

Welding Defects Defined		
DEFECT	CAUSE	
Pipe off set mismatch	Pipe misalignment	
Lack of root penetration	Welding technique	
Insufficient root fill	Welding technique	
Excessive penetration	Welding technique	
External undercut	Excessive amps/volts	
Internal undercut	Excessive amps/volts	
Internal concavity	Welding technique	
Root burn through	Welding technique	
Lack of root penetration	Weld joint set up	
Interpass slag inclusions	Weld technique, grinding, cleaning	
Elongated slag inclusions	Weld technique, grinding, cleaning	
Lack of side wall fusion	Weld technique, amps/volts to low	
Interpass cold lap	Weld technique	
Scattered porosity	Weld technique	
Cluster porosity	Weld technique, insufficient wind cover	
Root pass aligned porosity	Weld technique, insufficient wind cover	
Transverse crack	Insufficient wind cover, lack of pre-heating & post weld heat treatment of weld joint. Material problem.	
Longitudinal crack	Insufficient wind cover, lack of pre-heating & post weld heat treatment of weld joint. Material problem.	
Longitudinal root crack	Insufficient wind cover, lack of pre-heating & post weld heat treatment of weld joint. Material problem.	
Tungsten inclusions	Weld technique	

QA/QC Welding Process Metrology

Welding Procedures to avoid hydrogen induced cracking.

To control cracking when completing the welding procedure the following factors must be considered.

Combined thickness of the material to be welded	Hydrogen scales Welding arc energy
Carbon equivalent values	

Codes and Standards That are most Commonly Used on Construction Projects

 $Codes\ and\ Standards\ That\ are\ most\ Commonly\ Used\ on\ Construction\ Projects$


ASME Boiler and Pressure Vessel Code

Clause	Section
Clause Power boilers	1
Pressure vessels	VIII, DIVISION 1
Pressure vessels	VIII, DIVISION 2
Heating Boilers	IV
Nondestructive Ex	V
Welding & brazing qualifications	IX


American Pipeline Institute		
API	1104	Welding Pipelines & related facilities
API	650	Welded Steel Tanks for Oil Storage
AWS	D1.1	American Welding Society
ANSI		American National Standards Institute

B31.1 Power Piping B31.2 Industrial Gas & Air Piping B31.3 Petroleum Refinery Piping B31.4 Oil Transportation Piping	B31.5 Refrigeration Piping	
	B31.6 Chemical Industrial Piping	
	B31.7 Nuclear Power Piping B31.8 Gas Transmission & Distribution	


BEVEL DETAILS




WELDING DEFECTS



Cold Lap is a condition where the weld filler metal does not properly fuse with the base metal or the previous weld pass material (interpass cold lap). The arc does not melt the base metal sufficiently and causes the slightly molten puddle to flow into the base material without bonding.



Porosity is the result of "gas entrapment" in the solidifying metal. Porosity can take many shapes on a radiograph but often appears as dark round or irregular spots or specks appearing singularly, in clusters, or in rows. Sometimes, porosity is elongated and may appear to have a tail. This is the result of gas attempting to escape while the metal is still in a liquid state and is called "wormhole porosity" All porosity is a void in the material and it will have a higher radiographic



density than the surrounding area.


Cluster Porosity is caused when flux coated electrodes are contaminated with moisture. The moisture turns into gas when heated and be-comes trapped in the weld during the welding process. Cluster porosity appears just like regular



porosity in the radiograph but the indications will be grouped close together.



Slag inclusions are non metallic solid material entrapped in weld metal or between weld and base metal. In a radiograph, dark, jagged asymmetrical shapes within the weld or along the weld joints areas are indicative of slag inclusions.




Incomplete Penetration (IP) or lack of penetration (LOP) occurs when the weld metal fails to penetrate the joint. It is one of the most objectionable weld discontinuities. Lack of penetration allows a natural stress riser from which a crack may propagate. The appearance on a radiograph is a dark area with well defined, straight edges that follows the land or root face down the center of the weldment.







Incomplete fusion is a condition where the weld filler metal does not properly fuse with the base metal. Appearance on radiograph is usually appears as a dark line or lines oriented in the direction of the weld seam along the weld preparation or joining area.




Internal concavity or suck back is a condition where the weld metal has contracted as it cools and has been drawn up into the root of the weld. On a radiograph it looks similar to a lack of penetration but the line has irregular edges and it is often quite wide in the center of the weld image.




Internal or Root Undercut is an erosion of the base metal next to the root of the weld. In the radiographic image it appears as a dark irregular line offset from the centerline of ht weldment. Undercutting is not as straight edged as LOP because it does not follow a ground edge.




External or Crown Undercut is an erosion of the base metal next to the crown on the weld. In the radiograph, it appears as a dark irregular line along the outside edge of the weld area.




Offset or Mismatch are terms associated with a condition where two pieces being welded together are not properly aligned. The radiographic image shows a noticeable difference in density between the two pieces. The difference in density is caused by the difference in material thickness. The dark, straight line is caused by the failure of the weld metal to fuse with the land area.




Inadequate Weld Reinforcement is an area of a weld where the thickness of weld metal deposited is less than the thickness of the base metal. It is very easy to determine by radiograph if the weld has inadequate reinforcement, because the image density in the area of suspected inadequacy will be higher (darker) than the image density of the surrounding base material.



Excess Weld Reinforcement is an area of a weld that has a weld metal added in excess of that specified by engineering drawings and codes. The appearance on a radiograph is a localized, lighter area in the weld. A visual inspection will easily determine if the weld reinforcement is in excess of that specified by the engineering requirements.



Cracks can be detected in a radiograph only when they are propagating in a direction that produces a change in thickness that is parallel to the x-ray beam. Cracks can appear as jagged and often very faint irregular lines. Cracks can sometimes appear as "tails" on inclusions or porosity.




Tungsten inclusion: Tungsten is a brittle and inherently dense material used in the electrode in tungsten inert gas welding. If improper welding procedures are used, tungsten may be entrapped in the weld. Radiographically, tungsten is more dense than aluminum or steel, therefore it shows up as a lighter area with a distinct outline on the radiograph.



Oxide Inclusions are usually visible on the surface of material being welded (especially aluminum). Oxide inclusions are less dense than the surrounding material, and, therefore appear as dark irregularly shaped discontinuities in the radiograph.

Discontinuities in TIG Welds

Whiskers are short lengths of weld electrode wire, visible on the top or bottom surface of the weld or contained within the weld. On a radiograph they appear as light, "wire like" indications.



Burn Through results when too much heat causes excessive weld metal to penetrate the weld zone. Often lumps of metal sag through the weld, creating a thick globular condition on the back of the weld. These globs of metal are referred to as icicles. On the radiograph, burn through appears as dark sports, which are often surrounded by light globular areas (icicles).

WELDER CLASSIFICATIONS AND WELDING PARAMETERS

PIPE TESTS

UPS-GT-1

GTAW process using ER70S-2 filler metal, SA106 Gr. B Pipe 2.875'' O.D. $\times .625''$ T (Magnum Coupon), 6G position.

UPS-GT/SM-1

GTAW & SMAW Process using ER70S-2, E7018 Filler Metal, SA106 Gr. B pipe 2.750" O.D. X .625" (Magnum Coupon) 6G position (.125" GTAW & .500 SMAW).

UPS-GT-1/45

GTAW process using ERNiCr-3 (Inco-82) filler metal, SA 106 Gr. B pipe 2.375 O.D. $\times .436$ " (XXH), 6G position.

TOWER TESTS

UPS-SM-1

SMAW process using E7018, SA 106 Gr. B pipe 6.625" O.D. x .432" (S80)

6G position with backing ring.

UPS-SM-8

SMAW process using E309 filler metal, SA 106 Gr. B pipe 6.625" O.D. X .432" (\$80),6G position with backing ring.

WELD PROCEDURE (WPS) IDENTIFICATION

[UPS]-[SM]-[8]

First section — company name [UPS].

Second section --> welding process,

GT = GTAW (Gas Tungsten Arc Welding) or tig

SM = SMAW or stick,

GM = GMAW (Gas Metal Arc Welding),

FC = FCAW (Flux Core Arc Welding)

SA= SAW (Sub Arc Welding

Third section Type of base metal, 1 = carbon, 8 = stainless &, or filler metal.



SECTION 5: CHARTS AND WEIGHT REFERENCES

DECIMAL EQUIVALENCY CHART

Decimal Equivalent Chart

32nd	16th	8th	4th	Decimal	Millimeters
1/32"				0.03125	0.79375
2/32"	1/16"			0.0625	1.5875
3/32"				0.09375	2.38125
4/32"	2/16"	1/8"		0.125	3.175
5/32"				0.15625	3.96875
6/32"	3/16"			0.1875	4.7625
7/32"				0.21875	5.55625
8/32"	4/16"	2/8"	1/4"	0.25	6.35
9/32"				0.28125	7.14375
10/32"	5/16"			0.3125	7.9375
11/32"				0.34375	8.73125
12/32"	6/16"	3/8"		0.375	9.525
13/32"				0.40625	10.31875
14/32"	7/16"			0.4375	11.1125
15/32"				0.46875	11.90625
16/32"	8/16"	4/8"	1/2"	0.5	12.7
17/32"				0.53125	13.49375
18/32"	9/16"			0.5625	14.2875
19/32"				0.59375	15.08125
20/32"	10/16"	5/8"		0.625	15.875
21/32"				0.65625	16.66875
22/32"	11/16"			0.6875	17.4625
23/32"				0.71875	18.25625
24/32"	12/16"	6/8"	3/4"	0.75	19.05
25/32"				0.78125	19.84375
26/32"	13/16"			0.8125	20.6375
27/32"				0.84375	21.43125
28/32"	14/16"	7/8"		0.875	22.225
29/32"				0.90625	23.01875
30/32"	15/16"			0.9375	23.8125
31/32"				0.96875	24.60625
32/32"				1	25.4

To convert Millimeters to Inches divide by 25.4 Ex. 19mm / 25.4 = 0.748031 inches

To convert Inches to Millimeters multiply by $25.4 \, \text{Ex.} .75 \, \text{Inches} / 25.4 = 19.05 \, \text{mm}$


DECIMAL EQUIVALENCY CHART

Drill Sizes for Bolt Taps

Size of Tap	Threads per Inch	Diameter of Drill
1/4"	20	7
5/16"	18	F
3/8"	16	5/16"
7/16"	14	U
1/2"	13	27/64"
5/8"	11	17/32"
3/4"	10	21/32"
7/8"	9	49/64"
1"	8	7/8"
1 1/8"	7	63/64"
11/4"	7	1 7/64"
13/8"	6	113/64"
11/2"	6	111/32"
13/4"	5	1 11/16"
2"	41/2	1 25/32"

Drill Sizes for Pipe Taps and Thread Length

Pipe Size	Threads per Inch	Diameter of Drill	Male Thread Length	Depth Screwed into Joint
1/8"	27	11/32"	7/16"	5/16"
1/4"	18	7/16"	5/8"	7/16"
3/8"	18	37/64"	5/8"	7/16"
1/2"	14	23/32"	13/16"	9/16"
3/4"	14	59/64"	13/16"	9/16"
1"	11 1/2	15/32"	1"	11/16"
1 1/4"	11 1/2	11/2"	1"	11/16"
11/2"	11 1/2	1 49/64"	1 1/32"	11/16"
2"	8	2 3/16"	1 1/16"	3/4"
21/2"	8	29/16"	1 9/16"	1 1/16"
3"	8	3 3/16"	15/8"	11/8"
3 1/2"	8	3 11/16"	15/8"	1 1/8"
4"	8	4 3/16"	13/4"	2 3/16"



22 24 Σ 0 4 9 ∞ 8 27 ω ω 6 GATEVALVE 153/4 161/2 203/4 25 3/4 351/4 521/2 601/2 701/4 793/4 97 1/4 1123/4 44 83 01/2 71/2 13 7 2 9 8 20 ¥ / ω 6 7 183/16 WNFLG 45 ELL & 3 9/16 31/16 163/4 203/4 37/8 43/4 71/4 01/4 133/4 6 15 7 TEE & WN 411/16 20 11/16 311/16 121/2 141/2 24 1/4 61/8 71/8 91/8 53/4 FIG 23 I 2 9 9 LR ELL & WN 311/16 411/16 35 11/16 43 3/4 22 1/2 321/2 61/2 121/2 71/4 FIG 42 G 6 9 9 56 29 01/2 101/2 21/2 31/2 61/2 11/2 1/2 11/2 1/2 CAP ш 2 4 9 / ω 6 5 RE-DUCER 31/2 51/2 2 15 20 20 24 ш 2 m 4 9 / ω 4 33/8 5 5/8 131/2 191/2 21/2 41/8 81/2 1/2 21/4 ۵ m 7 2 Ξ 7 15 7 13/4 33/4 83/4 111/4 121/2 45 ELL 11/8 3/8 21/2 61/4 71/2 2/8 2 15 91 U 2 2 ODFLG 271/2 341/4 41/4 131/2 B 2 9 ^ 6 = 9 6 7 25 32 23 27/16 23/16 511/16 WNFLG 21/2 23/4 23/4 31/2 41/2 51/2 43/4 ⋖ m 2 2 9 4 4 PIPE O.D. 5/16 123/4 103/4 17/8 23/8 27/8 31/2 41/2 65/8 8 5/8 ω 20 26 4 9 24 "2/11 2 1/2 SIZE 5 3. 4 <u>.</u> 12" 74" .9 18 20" 24" 26" .9 <u>.</u>

50 # RF Piping Dimensions

(1) POSI-SEAL BUTTERFLY VALVES

223/16 28 7/16

25 7/16

46 15/16

101/2 101/2 01/2

24 24 24 24

201/2 261/2

36 1/2 3/4

415/16 91/89

28 30 36 42

28" 30" 36" 42"

22 30

38

53/8

22 1/4 17 1/4 181/2

> 46 53

26

63/4

23 7/8

27 3/8

503/8 91/8 09

32 11/16

323/4

363/4

693/4

2

CALC. BOX

(4) LENGTH DOES NOT INCLUDE CROWNS (2) CRANE DUO-CHEK II (3) TK BALL VALVES

			_		_	_		_	_		_	_		_			_	_		_		_
STUD BOLT SIZE	LENG (4)	тн	23/4	е	31/4	31/2	3 3/4	3 3/4	4	41/4	43/4	43/4	51/4	5 1/2	9	61/4	7	7 1/4	7 1/4	71/2	8 1/2	6
STUD BO	DIAN		1/2	1/2	2/8	2/8	2/8	8/9	3/4	3/4	8//	8//	-	ı	11/8	11/8	11/4	11/4	11/4	11/4	11/2	11/2
NC). BOLTS	,	4	4	4	4	4	8	8	œ	12	12	12	16	16	20	20	24	28	28	32	36
SI	ZE		٦,,	11/2"	2″	21/5"	3,"	4"	9	œ″	10″	12″	14″	.91	18″	20″	24"	.92	28″	30″	36″	42″
	LEVER LEN- GTH (FB)	Z	6	15	23		33	44														
	HWOD (FB)	٨					171/8	17 1/8	24	24	301/4	301/4	301/4	39	301/4	39	39	301/4	301/4	301/4	301/4	
E (3)	HWPROJ (FB)	×					101/16	101/16	111/2	111/2	18 15/16	1815/16	18 15/16	1815/16	2/11/2	2/11/2	2/11/2	313/8	313/8	313/8	37 1/4	
BALL VALVE (3)	HW OFF- SET (FB)	M					31/8	31/8	5	2	311/16	311/16	311/16	311/16	4 7/8	4 7/8	4 7/8	5 3/4	5 3/4	5 3/4	16	
	VALVE TO HW (FB)	^			43/4		71/16	80	1013/16	12 5/8	15 5/8	173/8	18 7/16	20 1/8	2413/16	25 3/8	30 3/8	341/4	351/8	371/8	42 7/8	
	RED. PORT	n			7		8	6	101/2	18	21	24	27	30		36	42					
	FULL	L	2	61/2	7		80	6	151/2	18	21	24	27	30	34	36	42	45	49	51	09	
WA CH VAL\	ECK	S			23/8	2 5/8	27/8	27/8	3 7/8	2	5 3/4	71/8	71/4	71/2	80	8 2/8	8 3/4	14	12	12	141/2	17
	ERFLY VE (1)	~					17/8	21/8	21/4	21/2	213/16	3 3/16	3 5/8	4	41/2	5	91/19			61/4	7	6
		σ			ω	80	6	91	12	91												
	GLOBE VALVE	Ь			13 3/4	141/2	161/2	19 3/4	24 1/2	26												
- 6	5	0			80	81/2	91/2	11 1/2	91	191/2												
CHECK	VALVE	z			80	81/2	91/2	11 1/2	14	191/2	241/2	271/2	35	39								

300 # RF Piping Dimensions

VALVE AND FITTING DIMENSIONS

Σ 2 4 9 20 20 27 27 30 36 36 ω ω ω 6 GATE VALVE 1201/2 993/4 63/4 231/4 28 1/4 381/2 561/2 641/4 75 1/4 911/2 ω 6 47 8 57/8 1/2 93/4 71/2 81/2 91/2 111/8 2 ω 30 33 36 39 45 ¥ 313/16 263/4 45 ELL & 125/8 WN FLG 35/16 107/8 143/8 53/4 171/2 187/8 215/8 231/4 3/4 33 7/8 43/4 51/8 57/8 75/8 93/8 25 3 TEE & WN 235/8 315/16 415/16 13 1/8 151/8 165/8 173/4 193/4 213/8 263/4 28 1/4 301/4 113/8 37 7/8 51/4 61/2 5 36 I 9 LR ELL & WN 29 3/4 363/8 315/16 415/16 265/8 631/2 127/8 163/8 8/56 231/8 331/4 42 5/8 461/4 493/4 531/4 707/8 53/4 63/4 7 5/8 93/8 FIG Ö 01/2 01/2 101/2 101/2 01/2 11/2 11/2 11/2 11/2 21/2 31/2 61/2 SAP ш 2 4 5 9 ω 6 7 RE-DUCER 21/2 31/2 31/2 51/2 $\underline{\circ}$ 4 5 20 24 24 24 24 24 2 m 4 9 7 ω CALC. BOX 261/2 5 5/8 131/2 91/2 201/2 21/2 33/8 1//2 2 22 30 ۵ m / = 2 15 7 22 1/4 11/4 121/2 171/4 181/2 13/8 21/2 33/4 71/2 83/4 45 ELL 11/8 13/4 61/4 2/8 2 15 9 26 2 2 403/4 503/4 21/2 201/2 251/2 301/2 OD FLG 38 1/4 47/8 61/8 71/2 81/4 2 15 23 28 36 43 20 B 211/16 WN FLG 27/16 23/4 37/8 45/8 77/8 33/8 43/8 51/8 5 5/8 53/4 61/4 63/8 65/8 73/4 81/4 ⋖ m PIPEO.D. 5/16 123/4 103/4 17/8 23/8 27/8 31/2 41/2 65/8 8 5/8 91 42 4 ω 20 24 26 30 36 11/2" 21/2 SIZE 20 24" 28" 30" 36" 42" L 2 <u>-</u> 4 .9 . . 0 2 4 .9 <u>_</u> 26

119

(4) LENGTH DOES NOT INCLUDE CROWNS

(1) POSI-SEAL BUTTERFLY VALVES

(2) CRANE DUO-CHEK II

(3) TK BALL VALVES

STUD BOLT SIZE	LENG (4)	тн	31/4	33/4	31/2	4	41/4	41/2	5	51/2	61/4	63/4	7	71/2	73/4	81/4	91/4	101/4	10 3/4	111/2	13	14
STUD BC	DIA METI		2/8	3/4	2/8	3/4	3/4	3/4	3/4	8//	١	11/8	11/8	11/4	11/4	11/4	11/2	15/8	15/8	13/4	2	2
NC	D. BOLTS	5	4	4	∞	∞	80	œ	12	12	91	16	20	20	24	24	24	28	28	28	32	36
SI	ZE		ا″	11/2"	2″	21/2"	3″	4"	9	<u>*</u>	"OL	12″	14"	91	18″	20″	24"	26″	28″	30″	36″	42"
	LEVER LEN- GTH (FB)	Z			23		33	44														
	HW OD (FB)	٨					17 1/8	17 1/8	24	24	301/4	301/4	301/4	39	39	39	39	301/4	301/4	301/4	301/4	
E (3)	HW PROJ (FB)	×					101/16	10	11 1/2	11 1/2	18 15/16	18 15/16	18 15/16	18 15/16	21 1/2	2/1 1/2	21 1/2	31 3/8	31 3/8	31 3/8	37 1/4	
BALL VALVE (3)	HWOFF- SET (FB)	M					31/8	31/8	5	5	311/16	311/16	311/16	311/16	4 7/8	4 7/8	4 7/8	5 3/4	5 3/4	5 3/4	16	
	VALVE TO HW (FB)	>			41/16		71/16	œ	1013/16	121/2	15 5/8	1613/16	18 7/16	201/8	2413/16	161/2	29 5/16	341/4	35 1/8	371/8	40 7/8	
	RED. PORT	D			81/2		111/8	12	15 7/8	19 3/4	223/8	25 1/2	30	33		39	45					
	FULL	F	2/19	71/2	81/2		11 1/8	12	15 7/8	19 3/4	223/8	251/2	30	33	36	39	45	49	53	22	89	
CH	FER ECK VE (2)	S			23/8	25/8	27/8	27/8	3 7/8	2	53/4	71/8	8 3/4	91/8	10 3/8	11 1/2	121/2	14		141/2	19	22 3/8
	ERFLY VE (1)	~					17/8	21/8	25/16	27/8	3 5/16	3 5/8	4 5/8	51/4	2 7/8	61/4	7			91/2	10 3/4	
		σ			6	10	10	7	18	24												
	GLOBEVALVE	Ь			17 3/4	19	201/2	243/4	293/4	361/2												
	019	0			101/2	11 1/2	12 1/2	7	17 1/2	22												
HE CK	/ALVE	z			01/2	11/2	21/2	7	71/2	21	41/2	28										

G H 43/16 3	43/16 43/16		51/4 51/4 41/8	61/8 55/8 41/2 111/2 181/4 8	. 71/8 63/8 51/8 13 221/4 9	8 67/8 51/2 14 253/4 10	: 101/4 83/8 63/4 17 311/2 14	: 13 7/8 10 1/2 8 5/8 22 42 3/4 20	171/2 121/2 101/2 26 521/4 24	21 1/4 14 3/4 12 1/2 31 62 1/4 27	243/8 163/8 137/8 33 70 27	: 273/4 173/4 151/2 35 771/4 30	311/4 191/4 171/4 39 833/4 30	341/2 21 183/4 43 933/4 36	37 3/4 22 3/4 20 1/4 47 104 1/2 36	2 441/4 251/4 231/4 55 126 42	
	ш	11/2 4	11/2	11/2 6	11/2	2	21/2	31/2	4 17	5 2	6 2	61/2 2:	7 3	8	9 3.	101/2 4	
DOCER	D E	11/2 2	21/4 21/2	21/2 3	3 31/2	33/8 31/2	4 1/8 4	55/8 51/2	9 2	8 1/2 7	10 8	11 13	12 14	131/2	15 20	17 20	CALC. BOX
	U	8/2	11/8	13/8	13/4	2	2/12	3 3/4	5	61/4	71/2	8 3/4	10	11 1/4	12 1/2	15	Ü
OD FLG	В	4 7/8	8/19	61/2	71/2	81/4	10 3/4	14	161/2	20	22	23 3/4	27	291/4	32	37	
WN FLG	∢	2 11/16	м	31/8	33/8	31/2	41/4	4 7/8	51/2	61/4	8/8 9	63/4	71/4	71/2	7 3/4	8 1/4	
PIPEO.D.		15/16	17/8	23/8	2 7/8	31/2	41/2	6 5/8	8/58	10 3/4	12 3/4	14	16	18	20	24	
SIZE			1/2″	2"	21/2"	3.	4"	9	 	10"	12"	14"	.91	18"	20"	24"	

600 # RF Piping Dimensions

(2) CRANE DUO-CHEKII
(3) TK BALL VALVES
(4) LENGTH DOES NOT INCLUDE CROWNS (1) POSI-SEAL BUTTERFLY VALVES

STUD BOLT SIZE	LENG (4)		3 3/4	41/4	41/4	43/4	2	5 3/4	63/4	7 3/4	81/2	8 3/4	91/4	10	10 3/4	11 1/2	13
STUD BO	DIA METI		2/8	3/4	2/8	3/4	3/4	8//	٦	11/8	11/4	11/4	13/8	11/2	15/8	15/8	17/8
NC). BOLTS	5	4	4	8	8	80	œ	12	12	16	20	20	20	20	24	24
SI	ZE		1"	11/2"	2″	21/2"	3″	.4	9	°e	,01	12″	14"	.91	18″	20″	24"
	LEVER LEN- GTH (FB)	Z	6	15	23		33	44									
	HWOD (FB)	۲					17 1/8	17 1/8	24	301/4	301/4	301/4	39	39	301/4	301/4	301/4
E (3)	HW PROJ (FB)	×					10 1/16	10 5/8	11 1/2	18 15/16	18 15/16	18 15/16	2/1 1/2	2/1 1/2	28	28	30
BALL VALVE (3)	HWOFF- SET (FB)	×					31/8	31/8	5	311/16	311/16	311/16	4 7/8	4 7/8	7 3/4	7 3/4	9 3/4
	VALVETO HW(FB)	>	31/8	43/4	5 13/16		71/16	œ	10 13/16	14	151/2	91/271	2/11/2	20 1/16	25 5/8	27 3/8	313/8
	RED. PORT	n			11 1/2		41	17	22	26	31	33	35	39	43	47	55
	FULL	H	81/2	91/2	11 1/2		14	17	22	26	31	33	35	39	43	47	55
WA CH VAL	FER ECK /E (2)	s			2 3/8	2 5/8	27/8	31/8	5 3/8	61/2	8/8	6	103/4	12	14 1/4	141/2	17 1/4
	ERFLY VE (1)	~					113/16	2 3/8	2 7/8	31/2	41/2	51/2	61/4	7	7 3/4	6	6
		σ			10	12	12	18	24								
	GLOBE VALVE	۵			61	21 1/4	23 1/2	271/2	32								
		0			1) 1/2	13	14	17	22								
CHECK	VALVE	z		91/2	11 1/2	13	14	17	22	26	31	33					

	M					12	77	20	24	27	30	30	36				
GATEVALVE	L					27 1/4	31 1/2	42 3/4	52 1/2	62 1/4	73 1/2	77 1/4	85 3/4				
	К					15	18	24	29	33	38	40 1/2	44 1/2				
45 ELL & WN FLG	J	4	4 5/8	5 5/8	61/8	61/4	71/4	91/2	115/8	13 3/4	15 5/8	173/8	18 3/4	20 1/2	22 1/2	26 3/4	
TEE & WN FLG	Н	4 5/8	5 3/4	63/4	7 3/8	7 5/8	87/8	11 3/8	13 5/8	16	18 1/8	19 5/8	203/4	223/4	25	283/4	
LR ELL & WN FLG	G	4 5/8	5 3/4	71/4	81/8	8 3/4	10 3/4	14 3/4	18 5/8	22 1/2	26 1/8	29 5/8	32 3/4	361/4	40	47 3/4	
CAP	F	11/2	11/2	11/2	11/2	2	21/2	31/2	4	5	9	61/2	7	80	6	10 1/2	
RE- DUCER	E	2	2/12	8	31/2	31/2	4	51/2	9	7	∞	13	14	15	20	20	
39 L	D	11/2	21/4	21/2	е	3 3/8	41/8	5 5/8	7	81/2	10	ιι	12	13 1/2	15	11	CALC. BOX
45ELL	С	8/2	11/8	13/8	13/4	2	21/2	3 3/4	2	61/4	71/2	8 3/4	10	111/4	12 1/2	15	
ODFLG	В	2 7/8	7	81/2	8/56	91/2	11 1/2	15	181/2	2/1 1/2	24	25 1/4	27 3/4	31	33 3/4	41	
WN FLG	А	31/8	31/2	41/4	43/8	41/4	43/4	5 3/4	6 5/8	71/2	8/18	8 2/8	8 3/4	91/4	10	11 3/4	
PIPE O.D.		91/51	17/8	2 3/8	27/8	31/2	41/2	8/59	8 2/8	10 3/4	12 3/4	14	91	81	20	24	
SIZE		1	11/2"	2"	21/2"	3"	4	9	 	10"	12"	14"	16"	18"	20"	24"	

(2) CRANE DUO-CHEKII
(3) TK BALL VALVES
(4) LENGTH DOES NOT INCLUDE CROWNS (1) POSI-SEAL BUTTERFLY VALVES

		_		_	_	_	_	_	_	_	_	_	_	_		_	
STUD BOLT SIZE	LENG (4)		2	51/2	5 3/4	61/4	5 3/4	63/4	7 3/4	8 3/4	91/4	01	10 3/4	11 1/4	12 3/4	13 1/2	17 1/4
STUD B(DIA METI		8/2	_	8/2	_	8/2	11/8	11/8	13/8	13/8	13/8	11/2	15/8	17/8	2	21/2
NO	. BOLTS	5	4	4	8	ω	8	œ	12	12	16	20	20	20	20	20	20
SI	ZE		٦,,	11/2"	2″	21/2"	3″	.4	.9	, w	,01	12″	14"	.91	18″	20″	24"
	LEVER LEN- GTH (FB)	Z	6	15	33		33	44									
	HWOD (FB)	٨					171/8	24	24	30 1/4	30 1/4	30 1/4	39	39	30 1/4	30 1/4	30 1/4
E (3)	HW PROJ (FB)	×					101/16	11 1/2	11 1/2	18 15/16	18 15/16	18 15/16	2/1 1/2	2/1 1/2	29	313/8	313/8
BALL VALVE (3)	HW OFF- SET (FB)	Μ					31/8	2	2	311/16	311/16	311/16	4 7/8	4 7/8	9 3/4	5 3/4	5 3/4
	VALVE TO HW (FB)	^					71/16	91/66	1013/16	16	15 5/8	18 3/8	2/1 1/2	20 1/16	25 13/16	28 7/8	30 15/16
	RED. PORT	n			14 1/2 14 1/2		15	18	24	29	33	38	40 1/2	44 1/2		52	61
	FULL	L	10	12	14 1/2		15	18	24	29	33	38	40 1/2	44 1/2	48	52	19
WA CHI VALV	ECK	S			23/4	31/4	31/4	4	61/4	8/18	91/2	11 1/2	14	151//8	17 3/4	17 3/4	191/2
BUTT VAL\	ERFLY /E (1)	~			23/4	31/4	31/4	4	61/4	81/8	91/2	11/2	4	15 1//8	17 3/4	17 3/4	191/2
		ø					12	20	27								
	JBE VALVE	Ь					24	29 1/2	37 3/4								
		0					15	18	24								
CHECK	VALVE	z					15	18	24	29							

	W	8	6	10	12	4	16	24	27								
GATE VALVE	7	91	20	22 1/8	26 3/8	28	33	47	55								
	К	10	12	141/2	161/2	181/2	2/1 1/2	27 3/4	32/34								
45 ELL & WN FLG	_	4	4 5/8	5 5/8	61/8	8/29	7 5/8	10 3/4	13 5/8	161/2	18 7/8	20 3/4	221/2	24 3/8	26 3/4	31 1/4	
TEE & WN FLG	I	4 5/8	53/4	63/4	7 3/8	81/4	91/4	12 5/8	15 5/8	18 3/4	21 3/8	23	24 1/2	26 5/8	29 1/4	33 1/4	
IR ELL & WN FLG	g	4 5/8	5 3/4	71/4	8/18	93/8	11 1/8	16	20 5/8	25 1/4	29 3/8	33	361/2	40 1/8	441/4	52 1/4	
CAP	ц	11/2	11/2	11/2	11/2	2	2/12	31/2	4	2	9	61/2	7	80	6	101/2	
RE- DUCER	Е	2	21/2	ю	31/2	31/2	4	51/2	9	7	œ	13	14	15	20	20	
TEE	D	11/2	21/4	2/12	е	3 3/8	41/8	5 5/8	7	81/2	10	ιι	12	13 1/2	15	17	CALC. BOX
45 ELL	O	8//	11/8	13/8	13/4	2	21/2	3 3/4	5	61/4	71/2	8 3/4	10	11 1/4	12 1/2	15	
ODFLG	В	2 7/8	7	81/2	8/96	101/2	12 1/4	151/2	19	23	26 1/2	29 1/2	32 1/2	36	38 3/4	46	
WN FLG	٧	31/8	31/2	41/4	43/8	4 7/8	51/8	7	8 2/8	101/4	11 3/8	12	12 1/2	13 1/8	14 1/4	161/4	
PIPE O.D.		15/16	17/8	23/8	27/8	31/2	41/2	6 5/8	8 2/8	10 3/4	12 3/4	14	16	18	20	24	
SIZE		1	11/2"	2"	21/2"	3"	4	.9	 80	10"	12"	14"	16"	18"	20"	24"	

1500 # RF Piping Dimensions

(1)
(2) CRANE DUO-CHEKII
(3) TK BALL VALVES
(4) LENGTH DOES NOT INCLUDE CROWNS

125

IZE	LENG		2	51/2	3/4	61/4	7	7 3/4	10 1/4	2/111	13 1/4	14 3/4	91	17 1/2	19 1/2	2/1 1/2	241/2
SOLTS	(4)		4,	51	53	61	_	7.3				14.	·	_	-	21.	-
STUD BOLT SIZE	DIA METI		8//	-	2/8	-	11/8	11/4	13/8	15/8	17/8	2	21/4	21/2	23/4	3	31/2
NC	D. BOLTS	5	4	4	œ	œ	∞	∞	12	12	12	16	16	16	16	16	91
SI	ZE		١,,	11/2"	2″	21/2"	3"	.,4	9	, %	.01	12″	14″	16″	18″	20″	24"
	LEVER LEN- GTH (FB)	Z	6	15	33		33	44									
	HWOD (FB)	\					17 1/8	24	30 1/4	301/4	39	39	39	301/4	301/4	301/4	301/4
(3)	HW PROJ (FB)	×					10 1/4	11 1/2	1815/16	1815/16	2/1 1/2	2/1 1/2	29	29	313/8	313/8	37 1/4
BALL VALVE (3)	HW OFF- SET (FB)	W					31/8	5	2	311/16	4 7/8	4 7/8	93/4	93/4	5 3/4	5 3/4	16
	VALVE TO HW (FB)	^	31/8	513/32	61/2		7 3/8	91/66	12 9/16	141/2	18 7/8	21 11/16	23 3/4	253/4	301/2	31 1/4	37 7/8
	RED. PORT	n			141/2		181/2	2/1 1/2	27 3/4	32 3/4	39	44 1/2	491/2	541/2		651/2	76 1/2
	FULL	L	10	12	141/2		181/2	2/1 1/2	27 3/4	32 3/4	39	44 1/2	491/2	541/2	601/2	651/2	761/2
WA CH VAL	AFER ECK VE (2)	S			2 3/4	31/4	31/4	4	61/4	8/18	93/4	12	14	15 1/8	18 7/16	21	22
	ERFLY VE (1)	~															
		σ			4	8	24										
	GLOBE VALVE	Ь			25 1/8	28 1/8	33 1/2										
	019	0			141/2	161/2	181/2										
CHECK	VALVE	z		12	141/2	161/2	181/2	2/1 1/2	273/4	323/4							

	W					12	14	20	24	27	30	30	36				
GATE VALVE	7					27 1/4	31 1/2	42 3/4	52 1/2	62 1/4	731/2	77 1/4	85 3/4				
J	X					151/8	18 1/8	241/8	29 1/8	331/8	38 1/8	40 5/8	44 5/8				
45 ELL & WN FLG	_	4	4 5/8	511/16	63/16	6 5/16	7 5/16	91/66	91/11 11	13 13/16	1511/16	179/16	18 15/16	20 3/4	22 3/4	27 1/8	
TEE & WN FLG	Ξ	4 5/8	53/4	91/219	77/16	711/16	8 15/16	91/211	13 11/16	161/16	18 3/16	1913/16	20 15/16	23	25 1/4	29 1/8	
LR ELL & WN FLG	g	4 5/8	5 3/4	7 5/16	83/16	813/16	10 13/16	14 13/16	1811/16	22 9/16	26 3/16	29 13/16	32 15/16	361/2	401/4	48 1/8	
CAP	ц	11/2	11/2	11/2	11/2	2	21/2	31/2	4	2	9	61/2	7	80	6	101/2	
RE- DUCER	Е	2	21/2	3	31/2	31/2	4	51/2	9	7	∞	13	4	15	20	20	
TEE	D	11/2	21/4	2/12	е	3 3/8	41/8	2 5/8	7	81/2	10	ш	12	13 1/2	15	17	CALC. BOX
45 ELL	C	8/2	11/8	13/8	13/4	2	21/2	3 3/4	5	61/4	71/2	8 3/4	10	11 1/4	12 1/2	15	
OD FLG	В	5 7/8	7	81/2	8/96	91/2	111/2	15	181/2	2/1 1/2	24	25 1/4	27 3/4		33 3/4	14	
WN FLG	A	31/8	31/2	45/16	47/16	45/16	413/16	513/16	91/119	91/67	8 3/16	8 13/16	8 15/16		101/4	12 1/8	
PIPE O.D.		15/16	17/8	23/8	27/8	31/2	41/2	8/59	8/58	10 3/4	12 3/4	41	16	18	20	24	
SIZE		1	11/2"	2"	21/2"	3"	"4	9	- - - -	10"	12"	14.	16"	18.	20"	24"	

(1)
(2)
(3) TK BALL VALVES
(4) LENGTH DOES NOT INCLUDE CROWNS

127

RING INFO.	GA	Р	5/32	5/32	1/8	1/8	5/32	5/32	5/32	5/32	5/32	5/32	5/32	5/32	3/16	3/16	7/32
RING	RING	NO.	R-16	R-20	R-24	R-27	R-31	R-37	R-45	R-49	R-53	R-57	R-62	R-66	R-70	R-74	R-78
STUD BOLT SIZE	LENG (4)		2	51/2	53/4	61/4	9	7	73/4	6	91/2	101/4	11 1/4	11 3/4	131/2	14 1/4	17 3/4
STUD BC	DIA		8//	1	2/8	1	2/8	11/8	11/8	13/8	13/8	13/8	11/2	15/8	17/8	2	21/2
NC	D. BOLTS	5	4	4	80	ω	8	œ	12	12	16	20	20	20	20	20	20
SI	ZE			11/2"	2″	2	3"	.4	9	, 0	.01	12″	14″	.91	18″	20″	24"
	LEVER LEN- GTH (FB)	Z	6	15	33		33	44									
	HW OD (FB)	٨					8/1 /1	24	24	30 1/4	30 1/4	30 1/4	39	68	30 1/4	30 1/4	30 1/4
(3)	HWPROJ (FB)	×					101/16	11 1/2	111/2	18 15/16	18 15/16	1815/16	2/1 1/2	21 1/2	29	31 3/8	313/8
BALL VALVE (3)	HW OFF. SET (FB)	Α					31/8	22	5	311/16	311/16	311/16	4 7/8	4 7/8	9 3/4	5 3/4	5 3/4
	VALVE TO HW (FB)	>					71/16	91/66	10 13/16	16	15 5/8	18 3/8	2/11/2	20 1/16	2513/16	28 7/8	3015/16
	RED. PORT	D			14 5/8		151/8	18 1/8	241/8	29 1/8	33 1/8	38 1/8	40 7/8	441/2		521/2	61 3/4
	FULL	_	9	12	14 5/8		151/8	18 1/8	241/8	29 1/8	33 1/8	38 1/8	40 7/8	441/2	481/2	52 1/2	61 3/4
ļ	ų.	σ			13 3/4	151/2	12	20	27								
	GLOBE VALVE	۵			23	241/2	24	291/2	37 3/4								
		0			141/2	161/2	15 1/8	181/8	24								
CHECK	VALVE	z			14 5/8	16 5/8	151/8	181/8	241/8	29 1/8							

1500 # RJT Piping Dimensions


VALVE AND FITTING DIMENSIONS


	M	8	6	10	12	4	16	24	27								
GATE VALVE	L	16	20	22 1/8	26 3/8	28	33	47	55								
	К	10 1/8	12 1/8	14 5/8	16 5/8	18 5/8	21 5/8	27 7/8	32 7/8								
45 ELL & WN FLG	J	4	4 5/8	511/16	63/16	615/16	711/16	10 7/8	13 13/16	1611/16	193/16	211/8	22 15/16	24 13/16	27 3/16	31 13/16	
TEE & WN FLG	Н	4 5/8	5 3/4	613/16	77/16	8 5/16	9 5/16	12 3/4	15 13/16	18 15/16	21 11/16	23 3/8	24 15/16	27 1/16	2911/16	33 13/16	
LR ELL & WN FLG	G	4 5/8	5 3/4	7 5/16	8 3/16	91//6	11 3/16	161/8	20 13/16	25 7/16	2911/16	33 3/8	36 15/16	409/16	44 11/16	52 13/16	
CAP	F	11/2	11/2	11/2	11/2	2	21/2	31/2	4	2	9	61/2	7	18	6	101/2	
RE- DUCER	E	2	21/2	3	31/2	31/2	4	51/2	9	7	œ	13	4	15	20	20	
TEE	D	11/2	21/4	21/2	е	3 3/8	41/8	5 5/8	7	81/2	10	F	12	13 1/2	15	17	CALC. BOX
45 ELL	С	8//	11/8	13/8	13/4	2	21/2	3 3/4	5	61/4	71/2	8 3/4	10	11 1/4	12 1/2	15	0
OD FLG	В	5 7/8	7	81/2	8/96	101/2	121/4	151/2	19	23	261/2	291/2	32 1/2	36	38 3/4	46	
WN FLG	А	31/8	31/2	4 5/16	47/16	415/16	5 3/16	21/8	8 13/16	10 7/16	11 11/16	12 3/8	12 15/16	139/16	14 11/16	91/8191	
PIPE O.D.		15/16	17/8	2 3/8	27/8	31/2	41/2	8/59	8 2/8	10 3/4	12 3/4	4	16	18	20	24	
SIZE		1	11/2"	2"	21/2"	 	-4"	9	 	10"	12"	14"	16"	18.	20"	24"	

(1)
(2) CRANE DUO-CHEKII
(3) TK BALL VALVES
(4) LENGTH DOES NOT INCLUDE CROWNS

RING INFO.	GA	Р	5/32	5/32	1/8	1/8	1/8	1/8	1/8	5/32	5/32	3/16	7/32	5/16	5/16	3/8	2/16
RING	RING	NO.	R-16	R-20	R-24	R-27	R-35	R-39	R-46	R-50	R-54	R-58	R-63	R-67	R-71	R-75	R-79
STUD BOLT SIZE	LENG (4)		5	51/2	5 3/4	61/4	7	7 3/4	101/2	12	13 3/4	151/2	17	181/2	201/2	22 1/2	25 3/4
STUD BO	DIA METI		2/8	-	8/2	-	11/8	11/4	13/8	15/8	1 7/8	2	21/4	21/2	23/4	т	31/2
NC). BOLTS	5	4	4	8	8	8	8	12	12	12	16	16	16	16	16	91
SI	ZE		1,,	11/2"	2″	21/2"	3″	4″	9	<u>*</u> 8	10″	12″	14"	.91	18″	20″	24"
	LEVER LEN- GTH (FB)	Z	6	15	33		33	44									
	HW OD (FB)	٨					17 1/8	24	30 1/4	30 1/4	39	39	39	30 1/4	30 1/4	30 1/4	30 1/4
(3)	HWPROJ (FB)	×					101/4	11 1/2	18 15/16	18 15/16	2/11/2	2/1 1/2	29	29	313/8	31 3/8	37 1/4
BALL VALVE (3)	HW OFF. SET (FB)	Μ					31/8	22	5	311/16	47/8	4 7/8	93/4	93/4	53/4	53/4	16
	VALVE TO HW (FB)	^	31/8	513/32	61/2		73/8	91/66	129/16	141/2	18 7/8	21 11/16	23 3/4	25 3/4	301/2	31 1/4	37 7/8
	RED. PORT	n			14 5/8		18 5/8	21 5/8	28	33 1/8	393/8	45 1/8	501/4	553/8		8/8 99	77 5/8
	FULL	L	10	12	14 5/8		18 5/8		28	33 1/8	39 3/8	45 1/8	50 1/4	55 3/8	613/8	8/8 99	77 5/8
	ш	σ			14	18	24										
	GLOBE VALVE	Ь			251/8	28 1/8	331/2										
	9	0			141/2	161/2	181/2										
CHECK	VALVE	z		12	14 5/8	16 5/8	18 5/8	21 5/8	28	327/8							

SCREWED FITTINGS











					3000#					
SIZE	Α	В	С	D	Е	F	G	H*	J*	K*
1/2	1 5/16	11/2	1	2 1/8	2 3/16	1 7/8	1 1/8	1/2	1/2	1/2
3/4	11/2	1 13/16	1 1/8	2 5/16	2 9/16	2	13/8	9/16	9/16	9/16
1	13/4	2 3/16	1 5/16	21/2	2 15/16	2 3/8	13/4	11/16	11/16	11/16
11/2	2 3/8	3	1 11/16	3 1/8	3 11/16	3 1/8	2 1/2	11/16	11/16	11/16
2	21/2	3 5/16	13/4	3 1/2	4 9/16	3 3/8	3	3/4	3/4	3/4
21/2	3 1/4	4	2 1/16	4 5/8	5 1/4	3 5/8	3 5/8	15/16	15/16	15/16

				(6000#					
SIZE	Α	В	С	D	Е	F	G	H*	J*	K*
1/2	11/2	113/16	1 1/8	2 7/8	2 13/16	1 7/8	11/2	1/2	1/2	1/2
3/4	13/4	2 3/16	1 5/16	3 3/8	3 1/8	2	13/4	9/16	9/16	9/16
1	2	2 7/16	13/8	3 5/8	3 13/16	2 3/8	2 1/4	11/16	11/16	11/16
11/2	21/2	3 5/16	13/4	4 3/16	4 3/4	3 1/8	3	11/16	11/16	11/16
2	3 1/4	4	2 1/16	4 5/8	5 1/4	3 3/8	3 5/8	3/4	3/4	3/4
21/2	3 3/4	4 3/4	2 1/2	_	_	3 5/8	4 1/4	15/16	15/16	15/16

ELL'S













,														
NOM.						WAL	WALLTHICKNESS INCHES	ESS INCH	ES					
PIPE SIZE	PIPE O.D.	LIGHT	SCH. 20	SCH. 30	SCH. STD.	SCH.	SCH. 60	SCH. X-STG.	SCH. 80	SCH. 100	SCH. 120	SCH. 140	SCH. 160	SCH.
1/2	0.840	0.083			601.0	0.109		0.147	0.147				0.188	0.294
3/4	1.050	0.083			0.113	0.113		0.154	0.154				0.219	0.308
-	1.315	0.109			0.133	0.133		0.179	0.179				0.250	0.358
11/4	1.660	0.109			0.140	0.140		0.191	0.191				0.250	0.382
11/2	1.900	0.109			0.145	0.145		0.200	0.200				0.281	0.400
2	2.375	0.109			0.154	0.154		0.218	0.218				0.344	0.436
21/2	2.875	0.120			0.203	0.203		0.276	0.276				0.375	0.552
3	3.500				0.216	0.216		0.300	0.300				0.438	0.600
31/2	4.000				0.226	0.226		0.318	0.318					0.636
4	4.500				0.237	0.237		0.337	0.337		0.438		0.531	0.674
5	5.563				0.258	0.258		0.375	0.375		0.500		0.625	0.750
9	6.625				0.280	0.280		0.432	0.432		0.562		0.719	0.864
8	8.625		0.250	0.277	0.322	0.322	0.406	0.500	0.500	0.594	0.719	0.812	0.906	0.875
10	10.750		0.250	0.307	0.365	0.365	0.500	0.500	0.594	0.719	0.844	1.000	1.125	1.000
12	12.750		0.250	0.330	0.375	0.406	0.562	0.500	0.688	0.844	1.000	1.125	1.312	1.000
14	14.000		0.312	0.375	0.375	0.438	0.594	0.500	0.750	0.938	1.094	1.250	1.406	
16	16.000		0.312	0.375	0.375	0.500	0.656	0.500	0.844	1.031	1.219	1.438	1.594	
18	18.000		0.312	0.438	0.375	0.562	0.750	0.500	0.938	1.156	1.375	1.562	1.781	
20	20.000		0.375	0.500	0.375	0.594	0.812	0.500	1.031	1.281	1.500	1.750	1.969	
24	24.000		0.375	0.562	0.375	0.688	0.969	0.500	1.219	1.531	1.812	2.062	2.344	
30	30.000		0.500	0.625	0.375			0.500						
36	36.000		0.500	0.625	0.375	0.750		0.500						
42	42.000				0.375			0.500						
48	48.000				0.375			0.500						

English Units

SECTION 5: CHARTS AND WEIGHT REFERENCES

ELL'S





45 L.R. ELL.












NOM. PIPE	A	В	К	D	٧	E		F :HES	G
SIZE	IN	IN	IN	IN	IN	IN	ASA	MSS	IN
1/2	11/2	5/8	1 7/8			1	3	2	13/8
3/4	1 1/8	7/16	1 11/16			1	3	2	1 11/16
1	11/2	7/8	2 3/16	1	15/8	11/2	4	2	2
11/4	1 7/8	1	2 3/4	11/4	2 1/16	11/2	4	2	21/2
11/2	2 1/4	1 1/8	3 1/4	11/2	2 7/16	11/2	4	2	2 7/8
2	3	13/8	4 3/16	2	3 3/16	11/2	6	2 1/2	3 5/8
21/2	3 3/4	13/4	5 3/16	21/2	3 15/16	11/2	6	2 1/2	41/8
3	41/2	2	6 1/4	3	4 3/4	2	6	2 1/2	5
3 1/2	5 1/4	2 1/4	7 1/4	3 1/2	5 1/2	21/2	6	3	51/2
4	6	21/2	8 1/4	4	6 1/4	21/2	6	3	6 3/16
5	71/2	3 1/8	10 5/16	5	7 3/4	3	8	3	7 5/16
6	9	3 3/4	12 5/16	6	9 5/16	31/2	8	3 1/2	8 1/2
8	12	5	16 5/16	8	12 5/16	4	8	4	10 5/8
10	15	6 1/4	20 3/8	10	15 3/8	5	10	5	12 3/4
12	18	7 1/2	24 3/8	12	18 3/8	6	10	6	15
14	21	8 3/4	28	14	21	61/2	12		16 1/4
16	24	10	32	16	24	7	12		18 1/2
18	27	11 1/4	36	18	27	8	12		21
20	30	12 1/2	40	20	30	9	12		23
24	36	15	48	24	36	10 1/2	12		27 1/4
30	45	18 1/2	60	30	45	10 1/2			
36	54	22 1/4		36	54	10 1/2			
42	63	26		42		12			
48	72	29 3/4		48		13 1/2			




NOM. PIPE	OUTLET IN	C IN	M IN	H IN
3/4	3/4	1 1/8		
3/4	1/2	1 1/8	1 1/8	11/2
1	1	11/2		
1	3/4	11/2	1 1/2	2
1	1/2	11/2	11/2	2
1 1/4	1 1/4	1 7/8		
I	1	1 7/8	1 7/8	2
I	3/4	1 7/8	1 7/8	2
1 1/4	1/2	1 7/8	1 7/8	2
11/2	11/2	2 1/4		
	11/4	2 1/4	2 1/4	2 1/2
	1	2 1/4	2 1/4	2 1/2
	3/4	2 1/4	2 1/4	2 1/2
11/2	1/2	21/4	2 1/4	21/2
2	2	2 1/2		
I	1 1/2	2 1/2	2 3/8	3
I	1 1/4	2 1/2	2 1/4	3
I	1	2 1/2	2	3
2	3/4	2 1/2	1 3/4	3
21/2	21/2	3		
I	2	3	2 3/4	3 1/2
I	1 1/2	3	2 5/8	3 1/2
I	11/4	3	21/2	3 1/2
21/2	1	3	2 1/4	3 1/2
3	3	3 3/8		
	21/2	3 3/8	3 1/4	3 1/2
	2	3 3/8	3	3 1/2
	1 1/2	3 3/8	2 7/8	3 1/2
3	1 1/4	3 3/8	2 3/4	3 1/2




NOM. PIPE	OUTLET IN	c	М	н
NOM. PIPE	OUTLET IN	IN	IN	IN
3 1/2	3 1/2	3 3/4		
	3	3 3/4	3 5/8	4
	21/2	3 3/4	3 1/2	4
	2	3 3/4	3 1/4	4
3 1/2	11/2	3 3/4	3 1/8	4
4	4	4 1/8		
	3 1/2	4 1/8	4	4
	3	4 1/8	3 7/8	4
	21/2	4 1/8	3 3/4	4
	2	4 1/8	3 1/2	4
4	11/2	4 1/8	3 3/8	4
5	5	4 7/8		
1	4	4 7/8	4 5/8	5
1	3 1/2	4 7/8	41/2	5
	3	4 7/8	4 3/8	5
	21/2	4 7/8	4 1/4	5
5	2	4 7/8	4 1/8	5
6	6	5 5/8		
I	5	5 5/8	5 3/8	5 1/2
I	4	5 5/8	5 1/8	5 1/2
I	3 1/2	5 5/8	5	5 1/2
I	3	5 5/8	4 7/8	5 1/2
6	21/2	5 5/8	4 3/4	5 1/2
8	8	7		
	6	7	6 5/8	6
	5	7	6 3/8	6
	4	7	6 1/8	6
8	3 1/2	7	6	6




NOM. PIPE	OUTLET IN	C IN	M IN	H IN
10	10	8 1/2		
	8	8 1/2	8	7
	6	8 1/2	7 5/8	7
	5	8 1/2	71/2	7
10	4	8 1/2	7 1/4	7
12	12	10		
	10	10	9 1/2	8
	8	10	9	8
	6	10	8 5/8	8
12	5	10	8 1/2	8
14	14	11		
	12	11	10 5/8	13
	10	11	10 1/8	13
1	8	11	9 3/4	13
14	6	11	9 3/8	13
16	16	12		
1	14	12	12	14
1	12	12	11 5/8	14
1	10	12	11 1/8	14
1	8	12	10 3/4	14
16	6	12	10 3/8	14
18	18	13 1/2		
	16	13 1/2	13	15
	14	13 1/2	13	15
	12	13 1/2	12 5/8	15
	10	13 1/2	12 1/8	15
18	8	13 1/2	11 3/4	15




NOM. PIPE	OUTLET IN	C IN	M IN	H IN
20	20	15		
	18	15	14 1/2	20
	16	15	14	20
	14	15	14	20
	12	15	13 5/8	20
	10	15	13 1/8	20
20	8	15	12 3/4	20
24	24	17		
	20	17	17	20
	18	17	16 1/2	20
	16	17	16	20
	14	17	16	20
	12	17	15 5/8	20
24	10	17	15 1/8	20
30	30	22		
	24	22	21	24
	20	22	20	24
	18	22	19 1/2	24
	16	22	19	24
30	14	22	19	24
36	36	26 1/2		
	30	26 1/2	25	24
	24	26 1/2	24	24
	20	26 1/2	23	24
	18	26 1/2	22 1/2	24
36	16	26 1/2	22	24
42	42	30	28	
	36	30	28	24
	30	30	28	24
	24	30	26	24
42	20	30	26	24
48	48	35	33	
	42	35	32	28
	36	35	31	28
48	30	35	30	28



			150 LB.	FLANGES -	INCHES		
NOM. PIPE		С		١	′		NO. & SIZE
SIZE	INCHES	INCHES	WELD NECK	SLIPONTHRD.	LAPJOINT	BOLT CIRCLE	OF HOLES
1/2	3 1/2	7/16	1 7/8	5/8	5/8	2 3/8	4 - 5/8
3/4	3 7/8	1/2	2 1/16	5/8	5/8	23/4	4 - 5/8
1	41/4	9/16	2 3/16	11/16	11/16	3 1/8	4 - 5/8
11/4	4 5/8	5/8	2 1/4	13/16	13/16	3 1/2	4 - 5/8
11/2	5	11/16	2 7/16	7/8	7/8	3 7/8	4 - 5/8
2	6	3/4	2 1/2	1	1	4 3/4	4 3/4
21/2	7	7/8	2 3/4	11/8	11/8	5 1/2	4-3/4
3	7 1/2	15/16	2 3/4	1 3/16	1 3/16	6	4-3/4
3 1/2	8 1/2	15/16	2 13/16	11/4	1 1/4	7	8-3/4
4	9	15/16	3	1 5/16	1 5/16	7 1/2	8-3/4
5	10	15/16	3 1/2	1 7/16	1 7/16	8 1/2	8-7/8
6	11	1	3 1/2	19/16	19/16	9 1/2	8-7/8
8	13 1/2	11/8	4	13/4	1 3/4	11 3/4	8-7/8
10	16	1 3/16	4	1 15/16	1 15/16	14 1/4	12-1
12	19	11/4	41/2	2 3/16	2 3/16	17	12-1
14	21	13/8	5	2 1/4	3 1/8	18 3/4	12-1 1/8
16	23 1/2	1 7/16	5	2 1/2	3 7/16	21 1/4	16-1 1/8
18	25	19/16	5 1/2	2 11/16	3 13/16	22 3/4	16-1 1/4
20	27 1/2	1 11/16	5 11/16	2 7/8	4 1/16	25	20-1 1/4
24	32	17/8	6	3 1/4	4 3/8	29 1/2	20-1 3/8




	300 LB. FLANGES - INCHES						
NOM. PIPE	0	C INCHES	Υ				NO. & SIZE
SIZE	INCHES		WELD NECK	SLIPONTHRD.	LAPJOINT	BOLT CIRCLE	OF HOLES
1/2	3 3/4	9/16	2 1/16	7/8	7/8	25/8	4 - 5/8
3/4	4 5/8	5/8	2 1/4	1	1	3 1/4	4 - 3/4
1	4 7/8	11/16	2 7/16	1 1/16	1 1/16	3 1/2	4 - 3/4
11/4	5 1/4	3/4	29/16	1 1/16	1 1/16	3 7/8	4 - 3/4
11/2	61/8	13/16	2 11/16	1 3/16	1 3/16	41/2	4 -7/8
2	6 1/2	7/8	2 3/4	1 5/16	1 5/16	5	8-3/4
21/2	7 1/2	1	3	11/2	11/2	5 7/8	8-7/8
3	8 1/4	11/8	3 1/8	1 11/16	1 11/16	6 5/8	8-7/8
3 1/2	9	1 3/16	3 3/16	13/4	13/4	7 1/4	8-7/8
4	10	1 1/4	3 3/8	17/8	17/8	7 7/8	8-7/8
5	11	13/8	3 7/8	2	2	9 1/4	8-7/8
6	12 1/2	1 7/16	3 7/8	2 1/16	2 1/16	10 5/8	12-7/8
8	15	15/8	4 3/8	2 7/16	2 7/16	13	12-1
10	17 1/2	1 7/8	4 5/8	25/8	3 3/4	15 1/4	16-1 1/8
12	20 1/2	2	5 1/8	2 7/8	4	17 3/4	16-1 1/4
14	23	2 1/8	5 5/8	3	4 3/8	20 1/4	20-1 1/4
16	25 1/2	2 1/4	5 3/4	3 1/4	43/4	22 1/2	20-1 3/8
18	28	2 3/8	61/4	3 1/2	5 1/8	24 3/4	24-1 3/8
20	30 1/2	2 1/2	6 3/8	3 3/4	5 1/2	27	24-1 3/8
24	36	2 3/4	6 5/8	4 3/16	6	32	24-1 5/8




** THE 1/4" RAISED FACE IS NOT INCLUDED IN THE THICKNESS "Y" OR "C"

	400 LB. FLANGES - INCHES							
NOM. PIPE	О	С	Y** (See Note Above)				NO. & SIZE	
SIZE	INCHES	INCHES	WELD NECK	SLIPONTHRD.	LAPJOINT	BOLT CIRCLE	OF HOLES	
1/2	3 3/4	9/16	2 1/16	7/8	7/8	25/8	4-5/8	
3/4	4 5/8	5/8	2 1/4	1	1	3 1/4	4 - 3/4	
1	4 7/8	11/16	2 7/16	11/16	1 1/16	3 1/2	4 - 3/4	
11/4	5 1/4	13/16	2 5/8	11/8	11/8	3 7/8	4 - 3/4	
11/2	61/8	7/8	2 3/4	11/4	1 1/4	41/2	4 -7/8	
2	61/2	1	2 7/8	1 7/16	1 7/16	5	8-3/4	
21/2	7 1/2	11/8	3 1/8	15/8	15/8	5 7/8	8-7/8	
3	8 1/4	1 1/4	3 1/4	1 13/16	1 13/16	6 5/8	8-7/8	
3 1/2	9	13/8	3 5/8	1 15/16	1 15/16	7 1/4	8-1	
4	10	13/8	3 1/2	2	2	7 7/8	8-1	
5	11	11/2	4	21/8	21/8	9 1/4	8-1	
6	12 1/2	15/8	41/16	2 1/4	2 1/4	10 5/8	12-1	
8	15	1 7/8	4 5/8	2 11/16	2 11/16	13	12-1 1/8	
10	17 1/2	2 1/8	4 7/8	2 7/8	4	15 1/4	16-1 1/4	
12	20 1/2	2 1/4	5 3/8	3 1/8	41/4	17 3/4	16-1 3/8	
14	23	2 3/8	5 7/8	3 5/16	4 5/8	20 1/4	20-1 3/8	
16	25 1/2	21/2	6	3 11/16	5	22 1/2	20-11/2	
18	28	25/8	61/2	3 7/8	5 3/8	24 3/4	24-1 1/2	
20	30 1/2	2 3/4	6 5/8	4	5 3/4	27	24-15/8	
24	36	3	6 7/8	41/2	6 1/4	32	24-1 7/8	




** THE 1/4" RAISED FACE IS NOT INCLUDED IN THE THICKNESS "Y" OR "C"

	600 LB. FLANGES - INCHES							
NOM. PIPE	О	С	Y** (See Note Above)				NO. & SIZE	
SIZE	INCHES	INCHES	WELD NECK	SLIPONTHRD.	LAPJOINT	BOLT CIRCLE	OF HOLES	
1/2	3 3/4	9/16	2 1/16	7/8	7/8	25/8	4 - 5/8	
3/4	4 5/8	5/8	2 1/4	1	1	61/4	4 - 3/4	
1	4 7/8	11/16	2 7/16	1 1/16	1 1/16	3 1/2	4 - 3/4	
11/4	5 1/4	13/16	2 5/8	11/8	11/8	3 7/8	4 - 3/4	
11/2	61/8	7/8	2 3/4	11/4	1 1/4	4 1/2	4 -7/8	
2	6 1/2	1	2 7/8	1 7/16	1 7/16	5	8-3/4	
21/2	7 1/2	11/8	3 1/8	15/8	15/8	5 7/8	8-7/8	
3	8 1/4	1 1/4	3 1/4	1 13/16	1 13/16	6 5/8	8-7/8	
3 1/2	9	13/8	3 3/8	1 15/16	1 15/16	7 1/4	8-1	
4	10 3/4	11/2	4	2 1/8	2 1/8	8 1/2	8-1	
5	13	13/4	41/2	2 3/8	2 3/8	10 1/2	8-1 1/8	
6	14	17/8	4 5/8	2 5/8	2 5/8	11 1/2	12-1 1/8	
8	16 1/2	2 3/16	5 1/4	3	3	13 3/4	12-1 1/4	
10	20	2 1/2	6	3 3/8	43/8	17	16-1 3/8	
12	22	2 5/8	61/8	3 5/8	4 5/8	19 1/4	20-1 3/8	
14	23 3/4	2 3/4	6 1/2	3 11/16	5	20 3/4	20-1 1/2	
16	27	3	7	4 3/16	5 1/2	23 3/4	20-1 5/8	
18	29 1/4	3 1/4	7 1/4	4 5/8	6	25 3/4	20-1 3/4	
20	32	3 1/2	7 1/2	5	6 1/2	28 1/2	24-1 3/4	
24	37	4	8	5 1/2	7 1/4	33	24-2	



** THE 1/4" RAISED FACE IS NOT INCLUDED IN THE THICKNESS "Y" OR "C"

	900 LB. FLANGES - INCHES						
NOM. PIPE	O INCHES	C INCHES	Y** (See Note Above)				NO. & SIZE
SIZE			WELD NECK	SLIPONTHRD.	LAPJOINT	BOLT CIRCLE	OF HOLES
1/2	4 3/4	7/8	2 3/8	11/4	1 1/4	3 1/4	4 - 7/8
3/4	5 1/8	1	2 3/4	13/8	13/8	3 1/2	4 - 7/8
1	5 7/8	11/8	2 7/8	15/8	15/8	4	4-1
1 1/4	61/4	11/8	2 7/8	15/8	15/8	4 3/8	4-1
11/2	7	1 1/4	3 1/4	13/4	1 3/4	4 7/8	4-11/8
2	8 1/2	11/2	4	2 1/4	2 1/4	6 1/2	8-1
2 1/2	9 5/8	15/8	41/8	2 1/2	2 1/2	7 1/2	8-1 1/8
3	9 1/2	11/2	4	21/8	2 1/8	7 1/2	8-1
3 1/2							
4	11 1/2	1 3/4	41/2	2 3/4	2 3/4	9 1/4	8-1 1/4
5	13 3/4	2	5	3 1/8	3 1/8	11	8-1 3/8
6	15	2 3/16	5 1/2	3 3/8	3 3/8	12 1/2	12-1 1/4
8	18 1/2	2 1/2	6 3/8	4	41/2	15 1/2	12-1 1/2
10	21 1/2	2 3/4	7 1/4	41/4	5	18 1/2	16-1 1/2
12	24	3 1/8	7 7/8	4 5/8	5 5/8	21	20-1 1/2
14	25 1/4	3 3/8	8 3/8	5 1/8	61/8	22	20-1 5/8
16	27 3/4	3 1/2	8 1/2	5 1/4	6 1/2	241/4	20-1 3/4
18	31	4	9	6	7 1/2	27	20-2
20	33 3/4	41/4	9 3/4	61/4	8 1/4	29 1/2	24-21/8
24	41	5 1/2	11 1/2	8	10 1/2	35 1/2	24-2 5/8



** THE 1/4" RAISED FACE IS NOT INCLUDED IN THE THICKNESS "Y" OR "C"

			1500 LB.	. FLANGES	- INCHES		
NOM. PIPE	О	С		Y** (See N	lote Above)		NO. & SIZE
SIZE	INCHES	INCHES	WELD NECK	SLIPONTHRD.	LAPJOINT	BOLT CIRCLE	OF HOLES
1/2	4 3/4	7/8	2 3/8	11/4	1 1/4	3 1/4	4 - 7/8
3/4	5 1/8	1	2 3/4	13/8	13/8	3 1/2	4 - 7/8
1	5 7/8	11/8	2 7/8	15/8	15/8	4	4-1
11/4	61/4	11/8	2 7/8	15/8	15/8	4 3/8	4-1
11/2	7	1 1/4	3 1/4	13/4	1 3/4	4 7/8	4 -1 1/8
2	8 1/2	11/2	4	2 1/4	2 1/4	6 1/2	8-1
21/2	9 5/8	15/8	41/8	2 1/2	2 1/2	7 1/2	8-1 1/8
3	10 1/2	1 7/8	4 5/8	2 7/8	2 7/8	8	8-1 1/4
3 1/2							
4	12 1/4	2 1/8	4 7/8	3 9/16	3 9/16	9 1/2	8-1 3/8
5	14 3/4	2 7/8	61/8	41/8	41/8	11 1/2	8-1 5/8
6	15 1/2	3 1/4	6 3/4	4 11/16	4 11/16	12 1/2	12-1 1/2
8	19	3 5/8	8 3/8	5 5/8	5 5/8	15 1/2	12-1 3/4
10	23	41/4	10	61/4	7	19	12-2
12	26 1/2	4 7/8	11 1/8	7 1/8	8 5/8	22 1/2	16-2 1/8
14	29 1/2	5 1/4	11 3/4	9 1/2	25	16-2 3/8	
16	32 1/2	5 3/4	12 1/4	10 1/4	27 3/4	16 - 25/8	
18	36	6 3/8	12 7/8	10 7/8	301/2	16-27/8	
20	38 3/4	7	14	11 1/2	32 3/4	16-3 1/8	
24	46	8	16	13	39	16-3 5/8	

	150# Blind-FLG. WT. KG	6.0	0.9	6.0	1.4	1.4	1.8	3.2	4.1	5.9	7.7	9.1	12.2	21.3	30.4	46.3	63.0	84.8	98.4	128.4	188.2
	150# Lap-FLG. WT. KG	0.5	0.7	6.0	1.1	1.4	2.3	3.6	4.1	5.0	5.4	5.9	8.2	12.7	16.3	27.2	34.9	47.2	66.2	72.1	88.5
SIC.	150# Thrd-FLG. WT. KG	0.5	0.7	6.0	1.1	1.4	2.3	3.6	4.5	5.4	5.9	6.8	8.8	13.6	18.6	29.5	38.6	42.2	54.4	70.3	95.3
METRIC	150# SO-FLG. WT. KG	0.5	0.7	6.0	1.1	1.4	2.3	3.6	4.1	5.0	5.9	8.9	7.7	12.7	18.1	27.7	37.6	48.1	49.4	67.1	92.5
	150# WNFLG. WT. KG	6.0	6.0	1.1	1.1	1.8	2.7	4.5	5.2	5.4	7.5	9.5	11.8	19.1	24.5	39.9	51.7	64.4	74.8	89.4	121.6
	NOM. PIPE SIZE MM	12.70	19.05	25.40	31.75	38.10	63.50	63.50	76.20	88.90	101.60	152.40	152.40	203.20	254.00	304.80	406.40	406.40	457.20	508.00	09.609
	150# Blind-FLG. WT. LBS.	7	2	2	е	е	4	7	6	13	17	20	27	47	29	102	139	187	217	283	415
	150# Lap-FLG. WT. LBS.	_	1.5	2	2.5	3	5	8	6	п	12	13	18	28	36	09	77	104	146	159	195
ENGLISH	150# Thrd-FLG. WT. LBS.	_	1.5	2	2.5	3	5	8	10	12	13	15	19.5	30	41	65	85	93	120	155	210
ENG	150# SO-FLG. WT. LBS.	-	1.5	2	2.5	3	5	8	6	11	13	15	17	28	40	19	83	106	601	148	204
	150# WNFLG. WR WT. LBS.	2	2	2.5	2.5	4	9	10	11.5	12	16.5	21	26	42	54	88	114	142	165	197	268
	NOM. PIPE SIZE	1/2	3/4		11/4	11/2	2	21/2	3	31/2	4	5	9	8	01	12	14	91	18	20	24

		ENGLISH	HSIT					METRIC	RIC		
NOM. PIPE SIZE	300# WNFLG. WR WT. LBS.	300# SO-FLG. WT. LBS.	300# Thrd-FLG. WT. LBS.	300# Lap-FLG. WT. LBS.	300# Blind-FLG. WT. LBS.	NOM. PIPE SIZE MM	300# WNFLG. WT. KG	300# SO-FLG. WT. KG	300# Thrd-FLG. WT. KG	300# Lap-FLG. WT. KG	300# Blind-FLG. WT. KG
1/2	2	1.5	1.5	1.5	2	12.70	6.0	0.7	0.7	0.7	6.0
3/4	က	2.5	2.5	2.5	е	19.05	1.4	1.1	1.1	1.1	1.4
1	4	3	3	3	4	25.40	1.8	1.4	1.4	1.4	1.8
11/4	5	4.5	4.5	4.5	9	31.75	2.3	2.0	2.0	2.0	2.7
11/2	7	6.5	6.5	6.5	7	38.10	3.2	2.9	2.9	2.9	3.2
2	80	7	7	7	œ	63.50	3.6	3.2	3.2	3.2	3.6
21/2	12	10	10	10	12	63.50	5.4	4.5	4.5	4.5	5.4
3	18	13	14	14.5	16	76.20	8.2	5.9	6.4	9.9	7.3
31/2	20	16	16	91	21	88.90	9.1	7.3	2.3	7.3	9.5
4	26.5	23.5	24	24	28	101.60	12.0	10.7	6.01	10.9	12.7
5	36	29	31	26	37	152.40	16.3	13.2	14.1	11.8	16.8
9	45	36	36	38	48	152.40	20.4	16.3	16.3	17.2	21.8
8	69	26	26	55	79	203.20	31.3	25.4	25.4	24.9	35.8
10	100	77	80	88	122	254.00	45.4	34.9	36.3	39.9	55.3
12	142	113	110	139	183	304.80	64.4	51.3	49.9	63.0	83.0
14	206	159	164	184	241	406.40	93.4	72.1	74.4	83.5	109.3
16	249	210	220	234	315	406.40	112.9	95.3	8.66	106.1	142.9
18	306	253	280	305	414	457.20	138.8	114.8	127.0	138.3	187.8
20	369	307	325	375	515	508.00	167.4	139.3	147.4	170.1	233.6
24	519	490	490	530	800	09.609	235.4	222.3	222.3	240.4	362.9

AMPLES. VI. Turk Fig. 10. WILLISS. VI. List. VII. List. VIII. List. VII	85. Blin 4 WI	NOM. PIESZE PRESZE NOM. 12.70 19.05 25.40 31.75 38.10 63.50	400# KG KG 1.4 1.6 1.8	400# SO-FLG. WT. KG	400# Thrd-FLG.	400# Lap-FLG. WT. KG	400# Blind-FLG.
2 2 2 2 10 - 4 - 0 8		12.70 19.05 25.40 31.75 38.10 63.50	1.4		WT. KG		WT. KG
2 2 2 2 8		19.05 25.40 31.75 38.10 63.50	1.6	6.0	6.0	6.0	6.0
3.5 4.5 6.5 6.5 8 8 8 8 12 12 12 21 21 21 31 31 63		38.10 63.50 63.50	1.8	1.4	1.4	1.4	1.4
4.5 6.5 6.5 8 8 8 8 12 12 21 22 24 24 33 63		31.75 38.10 63.50 63.50	2.5	1.6	1.6	1.6	1.8
6.5 8 8 12 12 21 21 21 24 31 39 63		38.10 63.50 63.50		2.0	2.0	2.0	2.7
8 12 12 21 24 24 39 63		63.50	3.6	2.9	2.9	2.9	3.6
12 15 21 21 24 24 33 63		63.50	4.5	3.6	3.6	3.6	4.5
21 21 31 31 39 63			6.4	5.4	5.4	5.0	6.8
24 39 63		76.20	8.2	6.8	6.8	6.4	9.1
31 39 63		88.90	11.8	9.5	9.5	9.1	13.2
31 39 63	22 33	101.60	13.6	10.9	10.9	10.0	15.0
39	29 44	152.40	17.7	14.1	14.1	13.2	20.0
63	37 61	152.40	22.2	17.7	17.7	16.8	27.7
	001 65	203.20	35.4	28.6	28.6	26.8	45.4
10 16 011	95 155	254.00	49.9	41.3	41.3	43.1	70.3
160 129 129	152 226	304.80	72.6	58.5	58.5	68.9	102.5
191 191 233	210 310	406.40	105.7	9.98	9.98	95.3	140.6
294 253 253	280 398	406.40	133.4	114.8	114.8	127.0	180.5
260 310 310	345 502	457.20	117.9	140.6	140.6	156.5	227.7
445 378 378	420 621	508.00	201.8	171.5	171.5	190.5	281.7
640 539 539	615 936	09.609	290.3	244.5	244.5	279.0	424.6

	. KG WT. KG																			
600# 600# Thrd-FLG. Lap-FLG. WT. KG WT. KG		6.0 6.0	_									. (4								
SO-FLG.WT. Thrd-I	_	0.9																		
WNFLG. WT. SO	1.4		1.6	1.6	1.6	1.6 1.8 2.5 3.6	1.6 1.8 2.5 3.6 4.5	1.6 1.8 2.5 3.6 4.5 6.4	1.6 1.8 2.5 3.6 4.5 6.4 8.2	1.6 1.8 3.6 4.5 6.4 8.2 11.8	1.6 1.8 2.5 3.6 4.5 6.4 8.2 11.8	1.6 1.8 2.5 3.6 4.5 6.4 8.2 11.8 10.8 30.8	1.6 1.8 2.5 3.6 4.5 6.4 6.4 8.2 11.8 16.8 30.8	1.6 1.8 2.5 3.6 4.5 6.4 6.4 8.2 11.8 16.8 30.8	1.6 1.8 2.5 3.6 4.5 6.4 6.4 8.2 11.8 10.8 30.8 33.1 50.8	1.6 1.8 2.5 3.6 4.5 6.4 6.4 8.2 11.8 11.8 30.8 30.8 33.1 50.8	1.6 1.8 2.5 3.6 4.5 6.4 8.2 11.8 11.8 30.8 33.1 50.8 85.7 102.5	1.6 1.8 2.5 3.6 4.5 6.4 8.2 11.8 10.8 30.8 33.1 50.8 85.7 102.5 121.6		
PIPE SIZE W	12.70		19.05	19.05	19.05 25.40 31.75	19.05 25.40 31.75 38.10	19.05 25.40 31.75 38.10 63.50	19.05 25.40 31.75 38.10 63.50	19.05 25.40 31.75 38.10 63.50 63.50 76.20	19.05 25.40 31.75 38.10 63.50 63.50 76.20 88.90	19.05 25.40 31.75 38.10 63.50 63.50 76.20 88.90	19.05 25.40 31.75 38.10 63.50 63.50 76.20 88.90 101.60	19.05 25.40 31.75 38.10 63.50 63.50 76.20 88.90 101.60 152.40	19.05 25.40 31.75 38.10 63.50 63.50 76.20 88.90 101.60 152.40 152.40 203.20	19.05 25.40 31.75 38.10 63.50 63.50 76.20 88.90 101.60 152.40 152.40 253.20	19.05 25.40 31.75 38.10 63.50 63.50 76.20 88.90 101.60 152.40 152.40 203.20 2554.00	19.05 25.40 31.75 38.10 63.50 63.50 76.20 88.90 101.60 1152.40 152.40 203.20 254.00 304.80	19.05 25.40 31.75 38.10 63.50 63.50 76.20 88.90 101.60 1152.40 152.40 203.20 254.00 304.80 406.40	19.05 25.40 31.75 38.10 63.50 63.50 76.20 88.90 101.60 1152.40 152.40 203.20 254.00 304.80 406.40	19.05 25.40 31.75 38.10 63.50 63.50 101.60 1152.40 152.40 152.40 203.20 254.00 304.80 406.40 406.40
600# Blind-FLG. WT. LBS.	,	7	3 8	4 w 4	1 K 4 9	1 W 4 0 8	8 0 0	8 8 10 10 15	20 S 8 8 8 0 20 20 20 20 20 20 20 20 20 20 20 20 2	20 20 59 59 50 50 50 50 50 50 50 50 50 50 50 50 50	20 20 20 29 41	20 20 20 29 68 88	20 20 20 20 88 86	20 20 20 20 29 86 86 86	20 20 20 29 88 86 88 86 139	2 4 4 6 6 8 8 8 6 8 8 8 6 8 8 6 8 8 8 6 8 8 8 6 8 8 8 6 8 8 8 6 8 8 8 6 8 8 8 6 8 8 8 6 8 8 8 6 8 8 8 6 8 8 8 6 8 8 8 6 8 8 8 8 6 8				
600# Lap-FLG. E WT. LBS.	2		е	3.5	3.5	3.5 4.5 6.5	3.5 4.5 6.5	3.5 4.5 6.5 8	3.5 4.5 6.5 8 8 11	3.5 4.5 6.5 8 8 11 11 14	3.5 4.5 6.5 8 8 11 11 14 20	3.5 3.5 6.5 6.5 8 8 8 11 11 14 20 31 63	3.5 4.5 6.5 6.5 8 8 8 11 11 12 20 31 63	3.5 4.5 6.5 6.5 6.5 11 11 12 31 63 78	3.5 4.5 6.5 6.5 8 8 8 8 11 11 12 20 31 63 78 78	3.5 4.5 6.5 6.5 8 8 8 11 11 12 20 31 63 78 112 195	3 3.5 4.5 6.5 6.5 6.5 6.5 6.5 6.5 6.5 6.5 6.5 6	3 3.5 4.5 6.5 6.5 6.5 6.5 6.5 6.5 6.5 6.5 6.5 6	3.5 4.5 6.5 6.5 8 8 8 8 8 11 11 12 20 20 240 240 240 469	3.5 4.5 6.5 6.5 8 8 8 8 8 11 11 11 12 13 13 13 13 13 13 13 13 14 20 20 24 240 240 240 240 240 240 240 2
600# Thrd-FLG. WT. LBS.	\exists			.5	5 5	w 2; 2; 2;	w 1, 1, 1, w	w vi vi vi w v	w 7; 73 73 w 2 79	2 2 3 5 5 15	3 1 2 2 3 2 2 3 3	333333333333333333333333333333333333333	0 3 3 5 6 8 8 6 6 6	7 0 0 3 3 T S 2 8 55 55 7	7 7 0 3 3 1 2 2 3 2 2 2 2 2 2 2 2 2 2 2 2 2 2	3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	2.5.5.5.5.5.5.5.5.5.5.5.5.5.5.5.5.5.5.5	3.5 1.5 1.5 1.5 1.5 1.5 2.1 1.5 2.1 2.1 2.1 2.1 2.1 2.1 2.1 2.1 2.1 3.3 3.3 3.3 3.3 3.3 3.3 3.3 3.3 3.3 3	3.3 5 5 5 5 5 5 5 5 5	
Thre	7		(*)	(') m	(, E 4	(, E 4 0	W 4 9	ε 4 9 σ _	(, 6, 4, 6, 3, - -		(a) (b) (b) (c) (c) (c) (c) (c) (c) (c) (c) (c) (c	8 3 2 1 1 2 8		'						3.5 3.5 4.5 6.5 6.5 8 8 8 8 12 21 15 21 17 177 177 177 177 177 177
600# 60 SO-FLG. Thre WT.LBS. WT				10	2 2	2 2 2														
	3 2 2			3.5	3.5	3.5 4.5 6.5	8 8	3.5 4.5 6.5 8 8	3.5 3.5 4.5 6.5 8 8 12 15	3.5 3.5 4.5 6.5 8 8 12 12	3.5 3.5 4.5 6.5 8 8 8 12 12 12 33	3.5 3.5 4.5 6.5 8 8 8 8 112 12 21 21 21 56	3.5 3.5 4.5 6.5 6.5 12 12 12 21 21 23 33 66	3.5 4.5 6.5 6.5 8 8 8 8 8 12 12 21 21 21 33 66 66	3.5 4.5 4.5 6.5 6.5 8 8 8 8 12 12 12 21 21 33 56 66 66	3.5 4.5 4.5 6.5 6.5 8 8 8 8 12 12 12 21 21 21 56 66 66 97	3.5 4.5 4.5 6.5 6.5 8 8 8 12 12 15 21 21 21 21 21 21 21 21 21 21 25 25 25 25 25 25 25 25 25 25 25 25 25	3 3.5 4.5 6.5 6.5 6.5 8 8 8 8 15 12 12 15 21 21 27 177 177 177 177 259 259 366	3.5 4.5 4.5 6.5 6.5 8 8 8 8 12 12 12 21 21 56 66 97 177 177 177 177 177 177 177 177 177	3.5 4.5 4.5 6.5 6.5 8 8 8 8 12 12 21 21 56 66 97 177 177 215 229 336 476

•						_\	•	•												
	900# Blind-FLG. WT. KG	1.8	2.7	4.1	4.5	6.4	11.3	15.9	14.5	24.5	39.5	51.3	89.4	131.5	187.3	224.1	280.8	399.2	502.1	952.1
	900# Lap-FLG. WT. KG	2.7	2.7	3.4	4.5	6.4	9.5	13.2	11.3	23.1	36.7	47.6	85.3	125.6	168.3	180.1	221.4	303.9	393.7	752.5
SIC	900# Thrd-FLG. WT. KG	2.7	2.7	3.4	4.5	6.4	10.0	16.3	14.1	24.0	37.6	49.9	78.0	1.111	147.9	172.4	208.2	293.5	359.2	671.3
METRIC	900# SO-FLG. WT. KG	2.7	2.7	3.4	4.5	6.4	10.0	16.3	14.1	24.0	37.6	49.9	78.0	1.111	147.9	172.4	208.2	293.5	359.2	671.3
	900# WNFLG. WT. KG	3.2	3.2	3.9	4.5	6.4	10.9	16.3	13.2	23.1	39.0	49.9	84.8	121.6	168.7	254.9	310.7	419.1	528.0	955.7
	NOM. PIPE SIZE MM	12.70	19.05	25.40	31.75	38.10	63.50	63.50	76.20	101.60	152.40	152.40	203.20	254.00	304.80	406.40	406.40	457.20	508.00	09.609
	900# Blind-FLG. WT. LBS.	4	9	6	10	14	25	35	32	54	87	113	197	290	413	494	619	880	1107	2099
	900# Lap-FLG. WT. LBS.	9	9	7.5	10	14	21	59	25	51	18	105	188	277	371	397	488	029	898	1659
ENGLISH	900# Thrd-FLG. WT. LBS.	9	9	7.5	10	14	22	36	31	53	83	108	172	245	326	380	459	647	792	1480
ENG	900# SO-FLG. WT. LBS.	9	9	7.5	10	14	22	36	31	53	83	108	172	245	326	380	459	647	792	1480
	900# WNFLG. WR WT. LBS.	7	7	8.5	10	14	24	36	29	51	98	110	187	268	372	562	685	924	1164	2107
	NOM. PIPE SIZE	1/2	3/4	1	11/4	11/2	2	21/2	3	4	5	9	8	10	12	14	16	18	20	24

	# C .	- 2	5	4	2	3	7	4	0	e,	.2	5.	ω.	6.	=					
	1500# Blind-FLG. WT. KG	3.2	4.	5.4	80	11.3	17.7	25.4	39.0	60.3	101.2	156.5	241.8	464.9	664.1					
	1500# Lap-FLG. WT. KG	2.7	2.7	3.4	4.5	6.4	9.5	13.2	17.2	34.0	62.6	77.1	129.7	220.0	339.7					
SIC	1500# Thrd-FLG. WT. KG	2.7	2.7	3.4	4.5	6.4	10.4	16.3	21.8	33.1	59.9	74.4	117.0	197.8	302.5					
METRIC	1500# SO-FLG. WT. KG	2.7	2.7	3.4	4.5	6.4	10.0	16.3	21.8	33.1	59.9	74.4	117.0	197.8	302.5					
	1500# WNFLG. WT. KG	3.2	3.2	3.9	4.5	6.4	10.9	16.3	21.8	31.3	59.9	74.4	123.8	205.9	313.0					
	NOM. PIPE SIZE MM	12.70	19.05	25.40	31.75	38.10	63.50	63.50	76.20	101.60	152.40	152.40	203.20	254.00	304.80	406.40	406.40	457.20	508.00	00000
	1500# Blind-FLG. WT. LBS.	7	10	12	18	25	39	56	86	133	223	345	533	1025	1464					
	1500# Lap-FLG. WT. LBS.	9	9	7.5	10	14	21	29	38	75	138	170	286	485	749					
											_	_	2	4	7					
HSIT	1500# Thrd-FLG. WT. LBS.	9	9	7.5	01	14	23	36	48	73	132	164	258 2	436 4	2 299					
ENGLISH	1500# 1500# SO-FLG. Thrd-FLG. WT.LBS. WT.LBS.	9 9	9 9	7.5 7.5	01 01	14 14	22 23	36 36	48 48											
ENGLISH	· .									73	132	164	258	436	299					

	Į CELIS					METRIC	Siz		
2500# 2500# 25 SO-FLG. Thrd-FLG. Lap WT.LBS. WT.LBS. WT	Lap VT	2500# Lap-FLG. WT. LBS.	2500# Blind-FLG. WT. LBS.	NOM. PIPE SIZE MM	2500# WNFLG. WT. KG	2500# SO-FLG. WT. KG	2500# Thrd-FLG. WT. KG	2500# Lap-FLG. WT. KG	2500# Blind-FLG. WT. KG
7 7		7	7	12.70	3.6	3.2	3.2	3.2	3.2
8 6 6	8		10	19.05	4.1	4.1	4.1	3.6	4.5
12 12 12	12		12	25.40	5.9	5.4	5.4	5.4	5.4
18 17	17		18	31.75	9.1	8.2	8.2	7.7	8.2
25 25 24	24		25	38.10	12.7	11.3	11.3	10.9	11.3
38 38 37	37		39	63.50	1.61	17.2	17.2	16.8	17.7
55 55 53	53		56	63.50	23.6	24.9	24.9	24.0	25.4
83 83 80	80		86	76.20	42.6	37.6	37.6	36.3	39.0
127 127 122	122		133	101.60	66.2	57.6	57.6	55.3	60.3
210 210 204	204		223	152.40	110.7	95.3	95.3	92.5	101.2
323 323 314	314		345	152.40	171.5	146.5	146.5	142.4	156.5
485 485 471	471		533	203.20	261.3	220.0	220.0	213.6	241.8
925 925 897	897		1025	254.00	484.4	419.6	419.6	406.9	464.9
1300 1300 1262	1262		1464	304.80	729.4	589.7	589.7	572.4	664.1
				406.40					
				406.40					
				457.20					
				508.00					
				09.609					

GASKETS


There are a large variety of gaskets used within our industry. Each type has specific purposes, material types and chemical resistant properties.


There are non-metallic, semi-metallic and metallic types. Often the non-metallic gaskets are referred to as sheet gaskets after being cut from a specific sheet of material to a specific layout pattern. Trade names include Garlock, Flexitallic and Lamons to name a few.

For this manual our photos demonstrate the spiral wound metallic and semi-metallic types. Careful consideration and adherence to the client design specifications must be considered when selecting the proper gasket. Please refer to your piping specifications prior to installing all gaskets and that the bolt torque is established with the gasket data information used for final bolt torque calculations.

Contact your supervisor or QC department if there are any concerns with gasket specification types.

GASKET COLOR CODES Metallic Winding Materials







Incoloy® 800/825 White



Inconel® X750 No Color



Hastelloy® C276 Beige



Hastelloy® B2 Brown

GASKET COLOR CODES Metallic Winding Materials

CONTINUED





Zirconium No Color



Carbon Steel Silver



Orange

Metallic Winding Materials



White Stripe



Grey Stripe



Flexite Super® Pink Stripe



Ceramic Light Green Stripe



Thermiculite[™] 735 Fluorescent Green Stripe



Thermiculite[™] 835 Light Blue Stripe

GASKET ASSEMBLY, BOLTING AND COMPRESSION

Flange Inspection

 Ensure flange faces are clean and fee from imperfections. These could be detrimental to sealing performance.

Surface Finish Recommendations

Sheet Jointing


3.2 to 12.5 micro meter Ra is dependent on gasket thickness (125 to 500 micro inch RMS

Spiral Wound Gaskets

Preferred Finish 3.2 to 6.3 micro meter Ra (125 to 250 micro inch RMS) on all pressure classes and critical applications

Bolting Recommendations

 When utilizing Torque wrenches the use of suitable lubricants on the stud threads and nut bearing faces is recommended, e.g. Molybdenum disulphide or Nickel powder anti-seize compounds.



Carefully remove any solid residue from the flanges using scrapers, wire brush or cloth.

Flexicarb RG & NR

3.2 to 6.3 micro meter Ra (125 to 250 micro inch RMS)

Jacketed Gaskets

2.5 to 125 micro meter Ra (100 to 125 micro inch RMS)

Solid Metal Gaskets

1.6 micro meter max Ra (63 micro inch RMS max

- 2. We recommend a 4 stage tightening method as follows:
 - Tighten the bolts at 30% of the final loading using the diametrical sequence.
 - 60% of final load following diametrical sequence.
 - 100% of final load following diametrical sequence.
 - 100% of final torque on adjacent bolts.

BOLT SEQUENCE FOR PROPER TORQUEING

For easy handling, bolt numbering shall be done clockwise around the flange with the following sequence.

4 bolt Flange	1,3,2,4
8 bolt Flange	1,5,3,7,2,6,4,8
12 bolt Flange	1,7,4,10,2,8,5,11,3,9,6,12
16 bolt Flange	1,9,5,13,3,11,7,15,2,10,6,14,4,12,8,16
20 bolt Flange	1,11,6,16,3,13,8,18,5,15,10,20,2,12,17,4,14,9,19
24 bolt Flange	1,13,7,19,4,16,10,22,2,14,8,20,5,17,11,23,6,18,12,24,3,15,9,21
28 bolt Flange	1,15,8,22,4,18,11,25,6,20,13,27,2,16,9,23,5,19,12,26,3,17,10,24,7,21,14,28
32 bolt Flange	1,17,9,25,5,21,13,29,3,19,11,27,7,23,15,31,2,18,10,26,6,22,14,30,8,24,16,32,4,20,12,28

BOLT TORQUE DATA

Torque Table for Class 150 Flange

Flange Materials : ASTM A105, ASTM A182 grades F50 and F51, ASTM A350 grades LF2 and LF3, ASTM A694 grade F52

Bolting Materials: ASTM A193 grades B7 and B7M, ASTM A320 grades L7, L7M and L43.

Gasket Type: Spiral Wound Gasket

SIZE IN INCH	SIZE IN MM	NO. OF BOLT	BOLT DIA.	THREAD TYPE	BOLT STRESS LB/IN2	TORQUE LBF.FT.	TORQUE NM
1/2	15	4	1/2"	UNC	25,000	22	30
3/4	20	4	1/2"	UNC	30,000	26	36
1	35	4	1/2"	UNC	33,000	29	39
1 ½	40	4	1/2"	UNC	50,000	44	60
2	50	4	5/8"	UNC	50,000	86	117
3	80	4	5/8"	UNC	50,000	86	117
4	100	8	5/8"	UNC	40,000	69	93
6	150	8	3/4"	UNC	45,000	137	185
8	200	8	3/4"	UNC	45,000	137	185
10	250	12	7/8"	UNC	40,000	194	263
12	300	12	7/8"	UNC	40,000	194	263
14	350	12	1"	UN8	41,000	296	401
16	400	16	1"	UN8	40,000	289	392
18	450	16	1 1/8"	UN8	40,000	421	571
20	500	20	11/8"	UN8	40,000	421	571
24	600	20	1 1⁄4″	UN8	40,000	588	797

BOLT TORQUE DATA

Torque Table for Class 300 Flange

Flange Materials : ASTM A105, ASTM A182 grades F50 and F51, ASTM A350 grades LF2 and LF3, ASTM A694 grade F52

Bolting Materials: ASTM A193 grades B7 and B7M, ASTM A320 grades L7, L7M and L43.

Gasket Type: Spiral Wound and Ring Joint

Bolt Lubricant Molykote 1000 ($\mu = 0.11$)

SIZE IN INCH	SIZE IN MM	NO. OF BOLT	BOLT DIA.	THREAD TYPE	BOLT STRESS LB/IN2	TORQUE LBF.FT.	TORQUE NM
1/2	15	4	1/2"	UNC	40,000	35	47
3/4	20	4	1/2"	UNC	40,000	69	93
1	35	4	1/2"	UNC	40,000	69	93
1 1/2	40	4	1/2"	UNC	31,000	94	128
2	50	4	5/8"	UNC	37,000	64	87
3	80	4	5/8"	UNC	42,000	127	173
4	100	8	5/8"	UNC	45,000	137	185
6	150	8	3/4"	UNC	45,000	137	185
8	200	8	3/4"	UNC	45,000	218	296
10	250	12	7/8"	UNC	45,000	325	441
12	300	12	7/8"	UNC	43,000	453	614
14	350	12	1″	UN8	45,000	474	643
16	400	16	1″	UN8	31,000	456	618
18	450	16	1 1/8"	UN8	34,000	500	678
20	500	20	1 1/8"	UN8	40,000	588	797
24	600	20	1 1⁄4″	UN8	31,000	809	1097

VICTOR OXYGEN & ACETYLENE CUTTING PRESSURE & TIP CHART

TIP CLEANING DRILL SIZES	PREHEAT	75	75	73	73	71	71	70	70	70	89	89	62	62	62	09	09	09	09	09	99
TIP CLE DRILL	CUTTING	72	68	62	62	26	56	54	54	54	51	51	45	45	45	41	41	41	32	32	28
KERF	WIDTH	0.035	0.05	0.055	0.055	0.08	0.08	0.095	0.095	0.095	0.100	0.100	0.125	0.125	0.125	0.150	0.150	0.150	0.203	0.230	0.250
CUTTING	SPEED I.P.M.	28	26	22	20	19	17	16	14	13	12	10	6	œ	7	7	9	5.5	5	4.5	4
C.F.H.	FUEL ACETY- LENE	6.5	6.5	7	7	9.5	9.5	10.5	10.5	10.5	12	12	13	13	14	25	25	26	28	28	30
CONSUMPTION C.F.H.	PREHEAT	7	7	7.5	7.5	ΙΙ	11	12	12	12	14	14	15	15	91	29	2	30	32	32	34
CONSI	CUTTING	18	24	40	20	75	85	105	115	135	170	180	240	265	315	420	485	550	750	975	1250
FUEL P.S.I	ACETYLENE @REGULATOR	3	3	4	4	4	4	4	4	4	5	5	5	5	5	9	9	9	6	9	7
A P.S.I. RESSURE	@TORCH	20	20	30	35	35	40	35	40	50	40	45	35	40	20	50	09	70	70	06	82
OXYGEN P.S.I. CUTTING PRESSURE	@ REGULATOR	20	20	30	35	35	40	35	41	51	42	47	38	44	54	56	29	78	83	125	100
	VICIOR IIP#	000	00	0	0	1	1	2	2	2	е	3	4	4	4	2	5	5	9	9	7
METAL	THICKNESS	1/8″	3/16″	1/4"	3/8″	1/2"	2/8″	3/4"	"L	11/4"	11/2"	2″	21/2"	3″	4″	2,,	9	8	10″	12″	14"

ANSI BOLTING CHART 1/2" – 4"

PRES- SURF	BOLTING	FLANGE				١	NORMAL	PIPE SIZE									
RATING	BOLLING	FACING	1/2	3/4	1	11/4	11/2	2	2 1/2	3	3 1/2	4					
	Number		4	4	4	4	4	4	4	4	8	8					
	Diameter		1/2	1/2	1/2	1/2	1/2	5/8	5/8	5/8	5/8	5/8					
150 Pound	Length of Stud Bolts	1 1/16 RF	2 1/2	2 1/2	2 3/4	2 3/4	3	3 1/4	3 1/2	3 3/4	3 3/4	3 3/4					
	Stud Boits	RTJ	-	-	3 1/4	3 1/4	3 1/2	3 3/4	4	41/4	41/4	41/4					
	Ring Size	R	-	-	15	17	19	22	25	29	33	36					
	Number		4	4	4	4	4	8	8	8	8	8					
	Diameter		1/2	5/8	5/8	5/8	3/4	5/8	3/4	3/4	3/4	3/4					
300	Length of	1/16 RF	2 3/4	3	3 1/4	3 1/4	3 3/4	3 1/2	4	41/4	41/2	41/2					
Pound	Stud Bolts	RTJ	3 1/4	3 1/2	3 3/4	3 3/4	41/4	41/4	43/4	5	5 1/4	5 1/4					
	Ring Size	R	11	13	16	18	20	23	26	31	34	37					
		RX	-	-	-	-	20	23	26	31	34	37					
	Number		4	4	4	4	4	8	8	8	8	8					
	Diameter		1/2	5/8	5/8	5/8	3/4	5/8	3/4	3/4	7/8	7/8					
400	Length of Stud Bolts	1/4 RF	3 1/4	3 1/2	3 3/4	4	41/4	41/4	4 3/4	5	51/2	5 1/2					
Pound		RTJ	3 1/4	3 1/2	3 3/4	4	41/4	41/2	5	5 1/4	5 3/4	5 3/4					
	Ring	R	11	13	16	18	20	23	26	31	34	37					
	Size	RX	-	-	-	-	20	23	26	31	34	37					
	Number		4	4	4	4	4	8	8	8	8	8					
	Diameter		1/2	5/8	5/8	5/8	3/4	5/8	3/4	3/4	7/8	7/8					
600	Length of	1/4 RF	3 1/4	3 1/2	3 3/4	4	41/4	41/4	4 3/4	5	51/2	5 3/4					
Pound	Stud Bolts	RTJ	3 1/4	3 1/2	3 3/4	4	41/4	41/2	5	5 1/4	5 3/4	6					
	Ring	R	11	13	16	18	20	23	26	31	34	37					
	Size	RX	-	-	-	-	20	23	26	31	34	37					
	Number		4	4	4	4	4	8	8	8	-	8					
	Diameter		3/4	3/4	7/8	7/8	1	7/8	1	7/8	-	11/8					
900	Length of	1/4 RF	41/4	41/2	5	5	51/2	5 3/4	61/4	5 3/4	-	6 3/4					
Pound	Stud Bolts	RTJ	41/4	41/2	5	5	51/2	6	61/2	6	-	7					
	Ring	R	12	14	16	18	20	24	27	31	-	37					
	Size	RX	-	-	-	-	20	24	27	31	-	37					

ANSI BOLTING CHART 5" - 24"

PRES-		FLANGE				I	NORMAL	PIPE SIZE				
SURE RATING	BOLTING	FACING	5	6	8	10	12	14	16	18	20	24
	Number		8	8	8	12	12	12	16	16	20	20
150	Diameter]	3/4	3/4'	3/4	7/8′	7/8′	1	1	11/8	11/8	11/4
150	Length of	11/16 RF	4	4	41/4	4 3/4	4 3/4	5 1/4	51/2	6	61/4	7
Pound	Stud Bolts	RTJ	41/2	41/2	41/2	5 1/4	5 1/4	5 3/4	6	61/2	6 3/4	71/2
	Ring Size	R	40	43	48	52	56	59	64	68	72	76
	Number		8	12	12	16	16	20	20	24	24	24
	Diameter		3/4	3/4	7/8′	1	11/8	11/8	11/4	11/4	11/4	11/2
300	Length of	1/4 RF	4 3/4	5	51/2	61/4	6 3/4	7	71/2	7 3/4	8 1/4	9 1/4
Pound	Stud Bolts	RTJ	51/2	5 3/4	61/4	7	71/2	7 3/4	8 1/4	8 1/2	9	10 1/4
	D' C'	R	41	45	49	53	57	61	65	69	73	77
	Ring Size	RX	41	45	49	53	57	61	65	69	73	77
	Number		8	12	12	16	16	20	20	24	24	24
400	Diameter	1	7/8	7/8	1	11/8	11/4	11/4	13/8	13/8	11/2	13/4
Pound	Length of	1/4 RF	5 3/4	6	6 3/4	71/2	8	8 1/4	8 3/4	9	9 3/4	10 3/4
	Stud Bolts	RTJ	6	61/4	7	7 3/4	8 1/4	8 1/2	9	9 1/4	10	11 1/4
	Number		8	12	12	16	20	20	20	20	24	24
	Diameter]	1	1	11/8	11/4	11/4	13/8	11/2	15/8	15/8	17/8
600	Length of	1/4 RF	61/2	6 3/4	7 3/4	8 1/2	8 3/4	9 1/4	10	10 3/4	11 1/2	13
Pound	Stud Bolts	RTJ	6 3/4	7	8	8 3/4	9	91/2	101/4	11	11 3/4	13 1/2
	Ring	R	41	45	49	53	57	61	65	69	73	77
	Size	RX	41	45	49	53	57	61	65	69	73	77
	Number		8	12	12	16	20	20	20	20	20	20
	Diameter	1	11/4	11/8	13/8	13/8	13/8	11/2	15/8	17/8	2	21/2
900	Length of	1/4 RF	71/2	7 3/4	8 3/4	9 1/4	10	10 3/4	11 1/4	13	133/4	17 1/4
Pound	Stud Bolts	RTJ	7 3/4	7 3/4	9	91/2	10 1/4	11 1/4	11 3/4	13 1/2	141/4	18
	Ring	R	41	45	49	53	57	62	66	70	74	78
	Size	RX	41	45	49	53	57	62	66	70	74	78
	Number		8	12	12	12	12	16	16	16	16	16
	Diameter]	11/2	13/8	15/8	17/8	2	2 1/4	21/2	2 3/4	3	3 1/2
1500	Length of	1/4 RF	9 3/4	10 1/4	11 1/2	13 1/2	15	16 1/4	17 3/4	191/2	21 1/4	241/4
Pound	Stud Bolts	RTJ	10	101/2	12	133/4	15 1/2	17	183/4	201/2	22 1/2	251/2
	Ring	R	44	46	50	54	58	63	67	71	75	79
	Size	RX	44	46	50	54	58	63	67	71	75	79
	Number		8	12	12	12	12	-	-	-	-	-
	Diameter		13/4	2	2	21/2	2 3/4	-	-	-	-	-
2500	Length of	1/4 RF	11 3/4	13 3/4	15 1/4	19 1/4	21 1/4	-	-	-	-	-
Pound	Stud Bolts	RTJ	121/2	141/4	153/4	201/4	22 1/4	-	-	-	-	-
	Ring	R	42	47	51	55	60	-	-	-	-	-
	Size	RX	42	47	51	55	60	-	-	-	-	-

WELD-O-LETS

				CEN	TER OF RUN	TO FACE FIT	TING		
RUN SIZE	WT. OR				OUTLE	T SIZE			
	SCH.	1/2	3/4	1	11/2	2	21/2	3	4
1/2	STD	13/16	3/4		11/2		21/2		•
1/2	XS	13/16							
	160&XXS	11/2							
2/4	-	,	17/10						
3/4	STD	11/4	1 7/16						
	XS	11/4	1 7/16						
	160&XXS	15/8	13/4						
1	STD	13/8	11/2	1 11/16					
	XS	13/8	11/2	1 11/16					
	160&XXS	13/4	17/8	21/8					
11/2	STD	1 11/16	113/16	2	2 1/4				
	xs	1 11/16	1 13/16	2	2 1/4				
	160&XXS	21/16	2 3/16	2 7/16	2 15/16				
2	STD	1 15/16	2 1/16	21/4	2 1/2	3 5/6			
	xs	1 15/16	2 1/16	21/4	2 1/2	2 11/16			
	160&XXS	2 5/16	2 7/16	2 11/16	3 3/16	3 3/8			
2 1/2	STD	23/16	2 5/16	21/2	2 3/4	2 15/16	3 1/16		
	xs	23/16	2 5/16	21/2	2 3/4	2 15/16	3 1/16		
	160&XXS	29/16	2 11/16	2 15/16	3 7/16	3 5/8	3 7/8		
3	STD	21/2	2 5/8	2 13/16	3 1/16	3 1/4	3 3/8	3 1/2	
	xs	21/2	2 5/8	2 13/16	3 1/16	3 1/4	3 3/8	3 1/2	
	160&XXS	2 7/8	3	3 1/4	3 3/4	3 15/16	4 3/16	4 5/8	
4	STD	3	3 1/8	3 5/16	3 9/16	3 3/4	3 7/8	4	41/4
	xs	3	3 1/8	3 5/16	3 9/16	3 3/4	3 7/8	4	41/4
	160&XXS	3 3/8	3 1/2	3 3/4	4 1/4	4 7/16	4 11/16	5 1/8	5 9/16

WELD-O-LETS

*USE HEAVY WALL WELD-O-LET

		CENTER OF RUN TO FACE FITTING							
RUN	WT. OR				OUTLE	T SIZE			
SIZE	SCH.								
		1/2	3/4	1	11/2	2	2 1/2	3	4
6	STD	4 1/16	4 3/16	4 3/8	4 5/8	4 13/16	4 15/16	5 1/16	5 5/16
	XS	4 1/16	4 3/16	4 3/8	4 5/8	4 13/16	4 15/16	5 1/16	5 5/16
	160&XXS	4 7/16	49/16	4 13/16	5 5/16	5 1/2	5 3/4	6 3/16	6 5/8
8	STD	5 1/16	5 3/16	5 3/8	5 5/8	5 13/16	5 15/16	61/16	6 5/16
	XS	5 1/16	5 3/16	5 3/8	5 5/8	5 13/16	5 15/16	6 1/16	6 5/16
	160&XXS					6 1/2	6 3/4	7 3/16	7 5/8
10	STD	61/8	61/4	6 7/16	6 11/16	6 7/8	7	7 1/8	7 3/8
	XS	6 1/8	61/4	6 7/16	6 11/16	6 7/8	7	7 1/8	7 3/8
	160&XXS					7 9/16	7 13/16	8 1/4	8 11/16
12	STD	7 1/8	7 1/4	7 7/16	7 11/16	7 7/8	8	8 1/8	8 3/8
	XS	7 1/8	7 1/4	7 7/16	7 11/16	7 7/8	8	8 1/8	8 3/8
	160&XXS					8 9/16	8 13/16	9 1/4	9 11/16
14	STD	7 3/4	7 7/8	8 1/16	8 5/16	8 1/2	8 5/8	8 3/4	9
	XS	7 3/4	7 7/8	8 1/16	8 5/16	8 1/2	8 5/8	8 3/4	9
	160&XXS					9 3/16	9 7/16	9 7/8	10 5/16
16	STD	8 3/4	8 7/8	9 1/16	9 5/16	9 1/2	9 5/8	9 3/4	10
	XS	8 3/4	8 7/8	9 1/16	9 5/16	9 1/2	9 5/8	9 3/4	10
	160&XXS					10 3/16	10 7/16	10 7/8	11 5/16
18	STD	9 3/4	9 7/8	10 1/16	10 5/16	10 1/2	10 5/8	10 3/4	11
	XS	9 3/4	9 7/8	10 1/16	10 5/16	10 1/2	10 5/8	10 3/4	11
	160&XXS					11 3/16	11 7/16	11 7/8	12 5/16
20	STD	10 3/4	10 7/8	11 1/16	11 5/16	11 1/2	11 5/8	11 3/4	12
	XS	10 3/4	10 7/8	11 1/16	11 5/16	11 1/2	11 5/8	11 3/4	12
	160&XXS					12 3/16	12 7/16	12 7/8	13 5/16
24	STD	12 3/4	12 7/8	13 1/16	13 5/16	13 1/2	13 5/8	13 3/4	14
	XS	12 3/4	12 7/8	13 1/16	13 5/16	13 1/2	13 5/8	13 3/4	14
	160&XXS					14 3/16	14 7/16	14 7/8	15 5/16

WELD-O-LETS

			CENTER OF RUN TO FACE FITTING							
RUN	WT. OR				(OUTLET SIZ	E			
SIZE	SCH.									
		6	8	10	12	14	16	18	20	24
6	STD	5 11/16								
	xs	6 3/8								
	160&XXS	7 7/16								
8	STD	6 11/16	7 1/16							
	XS	7 3/8	8 3/16							
	160&XXS	8 7/16	*							
10	STD	7 3/4	8 1/8	8 7/16						
	XS	8 7/16	9 1/4	9 1/8						
	160&XXS	91/2	*	*						
12	STD	8 3/4	9 1/8	9 7/16	9 3/4					
	XS	9 7/16	10 1/4	10 1/16	10 5/16					
	160&XXS	10 1/2	*	*	*					
14	STD	9 3/8	9 3/4	10 1/16	10 3/8	10 1/2				
	XS	10 1/16	10 7/8	10 11/16	11 1/16	11 1/8				
	160&XXS	11 1/8	*	*	*	*				
16	STD	10 3/8	10 3/4	11 1/16	11 3/8	11 1/2	11 11/16			
	xs	11 1/16	11 7/8	11 11/16	12 1/16	11 15/16	12 7/16			
	160&XXS	12 1/8	*	*	*	*	*			
18	STD	11 3/8	11 3/4	12 1/16	12 3/8	12 1/2	12 11/16	13 1/16		
	xs	12 1/16	12 7/8	1211/16	131/16	12 15/16	13 3/16	13 11/16		
	160&XXS	13 1/8	*	*	*	*	*	*		
20	STD	12 3/8	12 3/4	13 1/16	13 3/8	13 1/2	13 11/16	13 13/16	14 5/8	
	xs	13 1/16	13 7/8	13 11/16	14 1/16	13 15/16	14 3/16	14 3/8	15	
	160&XXS	14 1/8	*	*	*	*	*	*	*	
24	STD	14 3/8	14 3/4	15 1/16	15 3/8	15 1/2	15 11/16	15 13/16	16	17 3/8
	xs	15 1/16	15 7/8	15 11/16	16 1/16	15 15/16	16 3/16	16 3/8	16 11/16	17 1/2
	160&XXS	16 1/8	*	*	*	*	*	*	*	*

ASTM MATERIAL CODES

Carbon Steel

PIPE	VALVES	FLANGES	WELD FITTINGS	SCREWED & SOCKET FITTINGS
4.50	A105	A105 Grade 2	400414/00	A105 Grade 2
A53	A216 WCB	A181 Grade 2	A234 WPB	A181 Grade 2
A106B	A105	A105 Grade 2		A105 Grade 2
	A216 WCB	A181 Grade 2	A234 WPB	A181 Grade 2

Stainless Steels

PIPE	VALVES	FLANGES	WELD FITTINGS	SCREWED & SOCKET FITTINGS
A312 T304	A182 F-304/A351 CF8	A182 F-304	A403 WP-316L	A182 F-304
A312 304L	A182 F-304L/A296 CF3	A182 F-304L	A403 WP-304L	A182 F-304L
A312 T316	A182 F-316/A351 CF8M	A182 F-316	A403 WP-316	A182 F-316
A312 316L	A182 F-316L/A296 CF3M	A182 F-316L	A403 WP-316L	A182 F-316L
A312 321	A182 F-321/A351 CF8C	A182 F-321	A403 WP-321	A182 F-321
A312 347	A182 F/347/A351 CF8CMO	A182 F-347	A403 WP-347	A182 F-347

Low-Temperature Steels

PIPE	VALVES	FLANGES	WELD FITTINGS	SCREWED & SOCKET FITTINGS
A333 Grade	A350 LF-2/A352 LCB	A350 LF-2	A420 WPL-6	A350 LF-2
A333 Grade	A350 LF-3/A352 LCS	A350 LF-3	A420 WPL-3	A350 LF-3

Chrome-Moly Alloys

PIPE	VALVES	FLANGES	WELD FITTINGS	SCREWED & SOCKET FITTINGS
A335 P-1	A217 WC-6	A182 F-1	A234 WP-1	A182 F-1
A335 P-12	A217 WC-6	A182 F-12	A234 WP-12	A182 F-12
A335 P-11	A182 F11/A217 WC-6	A182 F-11	A234 WP-11	A182 F-11
A335 P-22	A182 F-22/A217 WC-9	A182 F-22	A234 WP-22	A182 F-22
A335 P-5	A182 F-5/A217 WC-5	A182 F-5	A234 WP-5	A182 F-5
A335 P-7	A182 F-7/A217 WC-12	A182 F-7	A234 WP-7	A182 F-7
A335 P-9	A182 F-9/A217 WC-12	A182 F-9	A234 WP-9	A182 F-9
A268 T-410	A182 F-6/A351 CA15	A182 F-6	A234 WP-410	A182 F-6

RIGGING AND CRANE

SECTION 6:

RIGGING SIGNALS



STOP: With arm extended horizontally to the side, palm down, arm is wung back and forth.



EMERGENCY STOP: With both arms extended horizontally to the side, palms down, arms are swung back and forth.



HOIST: With upper arm extended to the side, forearm and index finger pointing straight up, hand and finger make small circles.



RAISE BOOM: With arm extended horizontally to the side, thumb points up with other fingers closed.



SWING: With arm extended horizontally, index finger points in direction that boom is to swing.



RETRACT TELESCOPING BOOM: With hands to the front at waist level, thumbs point at each other with other fingers closed.



RAISETHE BOOM AND LOWER THE LOAD: With arm extended horizontally to the side and thumb pointing up, fingers open and close while load movement is desired.



DOG EVERYTHING Hands held together at waist level.



LOWER

With arm and index finger pointing down, hand and finger make small circles.



LOWER BOOM: With arm extended horizontally to the side, thumb points down with other fingers closed.



EXTEND TELESCOPING BOOM: With hands to the front at waist level, thumbs point outward with other fingers closed.



TRAVEL/TOWER TRAVEL: With all fingers pointing up, arm is extended horizontally out and back to make a pushing motion in the direction of travel.

RIGGING SIGNALS



LOWER THE BOOM AND RAISE THE LOAD: With arm extended horizontally to the side and thumb pointing down, fingers open and close while load movement is desired.



MOVE SLOWLY: A hand is placed in front of the hand that is giving the action signal.



USE AUXILIARY HOIST (WHIPLINE): With arm bent at elbow and forearm vertical, elbow is tapped with other hand. Then regular signal is used to indicate desired action.



CRAWLER CRANE TRAVEL, BOTH TRACKS: Rotate fists around each other in front of body; direction of rotation away from body indicates travel forward; rotation towards body indicates travel backward.



USE MAIN HOIST: A hand taps on top of the head. Then regular signal is given to indicate desired direction.



CRAWLER CRANE TRAVEL, ONE TRACK: Indicate track to be locked by raising fist on that side. Rotate other fist in front of body in direction that other track is to travel.



TROLLEY TRAVEL: With palm up, fingers closed and thumb pointing in direction of motion, hand is jerked horizontally in direction trolley is to travel.

SOURCE FOR HAND SIGNALS: OSHA 29 CFR 1926, SUBPART CC, APPENDIX A

CRANE & RIGGING QUALIFICATIONS

Operator Training, Qualification and Certification

Only employees who are qualified by the possession of a current accredited NCCCO as applicable crane operator testing certification and on-site qualifications may operate a crane.

A state or local license is required if:

- 1. working within a state or locality that has licensing requirements, and
- 2. the licensing program meets the licensing and certification criteria listed in subpart CC.
- 3. A state or local license is valid for the period of time stipulated by the licensing office, but no longer than 5 years. It is portable only within the jurisdiction of the issuing agency.

WRITTEN TESTS MAY BE ADMINISTERED IN A LANGUAGE UNDERSTOOD BY THE OPERATOR CANDIDATE. WHEN AN OPERATOR'S TESTING IS BASED ON A LANGUAGE OTHER THAN ENGLISH, IT MUST BE NOTED ON THE CERTIFICATE.

Rigger Training, Qualification and Certification

All rigging work will be performed by a qualified rigger. A qualified rigger means a person who, by possession of a recognized degree, certificate or professional standing, or who by extensive knowledge, training and experience, successfully demonstrated the ability to solve/resolve problems relating to the subject matter, the work, or the project.

Riggers will be qualified by an accredited organization or assessed by a third Party (DOL, NCCER, NCCCO, etc.).

SECTION 6: RIGGING AND CRANE

RIGGING SIGNAL TIPS Common Safety for Crane Operation

- The preferred method of communication is to have visual signals, however it is not always feasible, in those cases radios must be utilized.
- A crane operator should always move loads according to the established code of signals, and use a signaler. Hand signals are preferred and should be clarified before work begins.
- Only a qualified person should give signals to the crane operator.
- There should be only one designated person at a time giving crane signals.
- A crane operator should move loads only on crane signals from one person. A crane operator must obey a STOP signal regardless of who gives it.
- When feasible the person giving crane signals must be in clear view of the crane operator.

- The person giving crane signals must have a clear view of the load and the equipment.
- The person giving the crane signals must keep people outside the crane's operating area. Any request or question should be addressed to the signaler.
- The person giving crane signals should never direct a load over a person.
- No part of a crane or load should come within 15 feet of any power line. High power transmission lines may require additional clearances.
- Each crane operator is directly responsible for the safe operation of the crane. Whenever there is any doubt as to safety, the crane operator should stop the crane and refuse to handle loads until safety has been assured.
- These safety rules should not be considered complete for all situations of crane operation. Each situations is unique.

FREQUENTLY ASKED QUESTIONS:

When should the crane operator follow hand signals?

A crane operator should always move loads according to the established code of signals, and use a signaler. Hand signals are preferred, but radios are allowed as well.

Who can give hand signals or who can be a signaler?

- · A qualified signaler must be designated,
- A person qualified to give crane signals to the operator,
- There should be only one designated signaler at a time,
- A crane operator should move loads only on signals from one signaler,
- A crane operator must obey STOP signals regardless of who gives it.

What should you do when you are in charge of signaling?

The signaler must:

- When feasible be in clear view of the crane operator or communicate via radio,
- Have a clear view of the load and the equipment,
- Keep persons outside the crane's operating area,
- Never direct a load over a person.

RIGGING INFORMATION Risk Management

Risk Management is a comprehensive set of actions that reduces the risk of a problem, a failure, or an accident.

ASME B30.9 requires that sling users shall be trained in the selection, inspection, cautions to personnel, effects of environment, and rigging practices. Sling identification is required on all types of slings.

ASME B30.26 requires that rigging hardware users shall be trained in the selection, inspection, cautions to personnel, effects of environment, and rigging practices. All rigging hardware is to be identified by manufacturer with name of trademark or manufacturer.

TERMINOLOGY

- Working Load Limit (WLL): The maximum mass or force which the product is authorized to support in a particular service
- Proof Test: A test applied to a product solely to determine injurious material or manufacturing defects
- Ultimate Strength: The average load or force at which the product fails or no longer supports the load
- Design Factor: An industrial term denoting a product's theoretical reserve capability; usually computed by the working load limit and generally expressed a ratio e.g. 5 to 1

Planning And Responsibilities

Plan every lift and include the following questions with the questions your experience provides:

- Who is responsible (competent) for the rigging?
- 2. Has communications been established?
- 3. Is the rigging in acceptable condition?
- 4. Is the rigging appropriate for lifting?
- 5. Does the rigging have proper identification?
- 6. Does all gear have known working load limits?
- 7. What is the weight of the load?
- 8. Where is the loads center of gravity?
- 9. What is the sling angle?
- 10. Will there be any side or angular loading?

- 11. Are the slings padded against sharp corners (softeners)?
- 12. Are the working load limits adequate?
- 13. Is the load rigged to the center of gravity?
- 14. Is the hitch appropriate for the load?
- 15. Is a tag line required to control the load?
- 16. Will personnel be clear of suspended loads?
- 17. Does a load have a clear path?
- 18. Will the load be level and stable?
- 19. Any unusual environmental concerns?
- 20. Any special requirements?

 $The rigging \ must be used within manufacturer's recommendations and industry standards that include OSHA, ASME, ANSI, API and others.\\$

RIGGING INFORMATION

User Responsibility

- Utilize appropriate rigging gear suitable for overhead lifting
- Utilize the rigging gear within industry standards and the manufacturer's recommendations
- Conduct Regular inspection and maintenance of the rigging gear
- Provide employees with training to meet OSHA and ASME (B30.9, B30.26, etc.) requirements

Inspection of Rigging Hardware

Inspection Frequency per ASME B30.26 A visual inspection shall be performed by the user or designated person each day before the rigging hardware is used. A periodic inspection shall be performed by a designated person, at least annually. The rigging hardware shall be examined and a determination made as to whether they constitute a hazard. Written records are not required. Semi-permanent and inaccessible locations where frequent inspections are not feasible shall have periodic inspections performed.

Rejection Criteria per ASME B30.26

- Missing or illegible manufacturer's name or trademark and/or rated load identification (or size and required)
- A 10% or more reduction of the original dimension
- Bent, twisted, distorted, stretched, elongated, cracked or broken load bearing components
- Excessive nicks, gouges, pitting and

corrosion

- Indications of heat damage including weld splatter or arc strikes, evidence of unauthorized welding
- Loose or missing nuts, bolts, cotter pins, snap rings, or other fasteners and retaining devices
- Unauthorized replacement components or other visible conditions that cause doubt as to the continued use of the sling
- Additionally, inspect wedge sockets for:
- Indications of damaged wire rope or wire rope slippage

Improper assembly

Additional Rejection Criteria per ASME B30.10 - Hooks

- Any visibly apparent bend or twist from the plane of the unbent hook
- Any distortion causing an increase in throat opening of 5% not to exceed 1/4"

SECTION 6: RIGGING AND CRANE

RIGGING INFORMATION Inspection of Slings

Inspection Frequency per ASME B30.9

A visual inspection for damage shall be performed by the user or designated person each day or shift the sling is used. A complete inspection for damage shall be performed periodically by a designated person at least annually.

Rejection Criteria per ASME B30.9

- · Missing or illegible sling identification
- · Evidence of heat damage
- · Slings that are knotted

 Fittings that are pitted, corroded, cracked, bent, twisted, gouged or broken

Severe localized abrasion or scraping,

kinking, crushing, bird caging and any

other damage resulting in distortion of

 Other conditions including visible damage that causes doubt as to the continued use of the sling

Wire Rope Slings

 Excessive broken wires, for strand-laid and single part slings, ten (10) randomly distributed broken wires in one (1) rope lay or five (5) broken wires in one (1) strand in one (1) rope lay

Web Slings

- Chemical Damage including Acid or caustic burns
- Melting or charring of any part of the sling surface
- · Holes, tears, cuts or snags

Corrosion of the rope or end attachments Broken or work stitching in load

bearing splices
 Excessive abrasive wear

the rope structure

 Discoloration and brittle or stiff areas on any part of the sling, which may mean chemical or ultraviolet/sunlight damage

Round Slings

- Chemical Damage including Acid or caustic burns
- Extensive abrasive wear
- Holes, tears, cuts, abrasive wear or snags that expose the core yarns
- Broken or damaged core yarns and/or stitching
- Weld splatter that exposes core yarns
- Discoloration and brittle or stiff areas on any part of the slings

RIGGING INFORMATION Wire Rope Sling Connections and Hitches

Connection to Fittings

- Use a thimble eye to protect sling and increase D/d
- Never place eye over a fitting with a smaller diameter or width than the ropes diameter
- Never place a sling eye over a fitting with a diameter or width greater than one half the length of the eye





Choker Capacity

A choker hitch has 75% of the capacity of a single leg sling only if the angle of the choke is 120 degrees or greater. A choke angle less than 120 degrees can result in a capacity as low as 40% of the single leg.



Basket Hitch Capacity

A basket hitch has twice the capacity of a single leg only if D/d ration is 25/1 and the legs are vertical.





Angle	Capacity % of Single Leg
90	200%
60	170%
45	140%
30	100%

Multiple Leg Slings

Triple leg slings have 50% more capacity than double leg slings (at same sling angle) only if the center of gravity is in center of connection points and legs are adjusted properly (they must have an equal share of the load).

Quad (4 leg) slings offer improved stability, but provide increased capacity only if all legs share an equal share of the load.

RIGGING INFORMATION Chain Sling Connections and Hitches

Connection to Fittings

- Use master links to collect slings and to connect to hook
- Use Grade 8 (80) or Grade 10 (100) fitting that match the WLL of chain and offer proper securement



Choker Capacity

- A choker hitch has 80% of the capacity of a single leg sling only if the angle of choke is 120 degrees or greater. Choke angles less than 120 degrees will result in a significantly reduced capacity.
- · No loss in capacity results if a cradle crab hook is used





Basket Hitch Capacity

A true basket hitch has twice the capacity of a single leg only if the legs are vertical. Note: The basket is formed by using a chain sling with two master links at each end connected to the hook.



Angle	Capacity % of Single Leg
90	200%
60	170%
45	140%
30	100%

Multiple Leg Slings

Triple leg slings have 50% more capacity than double leg slings (at same sling angle) only if the center of gravity is in center of connection points and legs are adjusted properly (they must have an equal share of the load).

Quad (4 leg) slings offer improved stability, but do not provide increased capacity. The capacity of a four leg chain sling is considered the same as three leg chain sling.

RIGGING INFORMATION **Synthetic Sling Connections and Hitches**


Web sling identification includes:

Sling Type

TC - Triangle Choker

TT - Triangle Triangle


EE - Eye Eye



Folding, bunching or pinching or synthetic slings, which occurs when used with shackles, hooks or other application, will reduce the rated load.

Round Sling Identification Includes:

- Sling Number: 1-13
- Sling numbers are for reference only. Some round slings have different ratings.
- · Sling Color: purple, green, yellow, tan, red, white, blue, and orange
- · Sling color is not followed by all manufacturers and some colors have more than one rated load



Choker Capacity

A choker hitch has 80% of the capacity of a single leg sling only if the angle of choke is 120 degrees or greater. Choke angles less than 120 degrees will result in a capacity as low as 40% of the single leg.



Basket Hitch Capacity

A true basket hitch has twice the capacity of a single leg only if th legs are vertical.



Angle	Capacity % of Single Leg
90	200%
60	170%
45	140%
30	100%

Multiple Leg Slings

Triple leg slings have 50% more capacity than double leg slings (at same sling angle) only if the center of gravity is in center of connection points and legs are adjusted properly (they must have an equal share of the load).

Quad (4 leg) slings offer improved stability, but provide increased capacity only if all legs share an equal share of the load.

Always select and use web slings and round slings by the rated load shown on the sling identification and not by the width, color or sling number.

RIGGING INFORMATION Center of Gravity, Weights and Measures

When lifting vertically, the load will be shared equally when the center of gravity is placed equally between the pick points.

If the weight of the load is 10,000 lbs. then each sling will have a load of 5,000 lbs. and each shackle and eyebolt will also have a load of 5,000 lbs.



CENTER OF GRAVITY AND SLING LOADING

D1=8 FT

D2=2 F1

SLING 1

SLING 2

Weight and Measurement Data

Center of Gravity and Sling Loading

When the center of gravity is not equally spaced between the pick points, the sling and fittings will not carry an equal share of the load. The sling connected to the pick point closest to the center of gravity will carry the greatest share of the load.

Sling 2 is closest to COG. It will have the greatest share of the load.

Ex. Sling
$$2 = 10,000 \times 8/(8+2) = 8,000 \text{ lbs.}$$

Sling $1 = 10,000 \times 2/(8+2) = 2,000 \text{ lbs.}$

Unit weight steel = 490 lbs./cu ft
Unit weight aluminum = 168 lbs./cu ft
Unit weight concrete = 150 lbs./cu ft
Unit weight wood = 40 lbs./cu ft
Unit weight water = 62 lbs./cu ft
Unit weight sand and gravel = 120 lbs./cu ft
Unit weight copper = 560 lbs./cu ft
Unit weight copper = 58 lbs./cu ft
Unit weight oil = 58 lbs./cu ft


1 cubic ft. = 7.5 gals

½ inch = 12.7 mm

1 inch - 25.4 mm

1 metric ton = 1.1 US tons
1 kilogram = 2.2 lbs.

Volume of Cube = height x width x length



Volume of Sphere = 3.14 x (diameter x diameter x diameter)/6


Volume of Cylinder = 3.14 x (diameter x diameter x length)/4

RIGGING INFORMATION Sling Angle Information

Vertical share of load on slings are equal if center of gravity is in the middle of the pick points.




Horizontal Sling Angle (A) degree 90



Horizontal Sling Angle Load Angle Factor = L/H 1,000 1,155


> 1,305 1,414 2,000



Load on sling calculated

Tension 1 = Load x D2 x S1/(H(D1+D2))

Tension $2 = Load \times D1 \times S2/(H(D1+D2))$



Load on sling calculated

Tension 1 = Load x D2 x S1/(H(D1+D2))

Tension $2 = Load \times D1 \times S2/(H(D1+D2))$

Horizontal sling angles of less than 30 degrees are not recommended. Refer to ANSI B30.9 for full information.

RIGGING INFORMATION ASME B30.9 Operating Practices and Load Control


Whenever any sling is used, the following practices shall be observed.

- Slings that are damaged or defective shall not be used
- 2. Slings shall not be shortened with knots or bolts or other makeshift devices
- 3. Sling legs shall not be kinked
- 4. Slings shall not be loaded in excess of their rated capacities
- Slings used in a basket hitch shall have the loads balance to prevent slippage
- 6. Slings shall be securely attached to their load
- 7. Slings shall be padded or protected from


- the sharp edges of their loads
- 8. Suspended loads shall be kept clear of all obstruction
- All employees shall be kept clear of loads about to be lifted and of all suspended loads
- Hand or fingers shall not be placed between the sling and its load while the sling is being tightened around the load
- 11. Shock loading is prohibited
- 12. A sling shall not be pulled from under a load when the load is resting on the sling.

Inspection: Each day before being used, the sling and all fastenings and attachments shall be inspected for damage or defects by a competent person designated by the employer. Additional inspections shall be performed during sling use where service conditions warrant. Damaged or defective slings shall be immediately removed from service.

Positive Load Control



Reeving through connections to the load increases the load on connection fittings by as much as two times. DO NOT REEVE!



RIGGING INFORMATION Block Concepts

Mechanical Advantage

- Mechanical advantage is the leverage gained by a multiple part block
- The theoretical (ignore friction) advantage is equal to the number of parts of line supporting the traveling block (load)
- Total load on the block is sum of all loads placed on the block end fitting



Ex.

Parts of line = 4
Mechanical advantage = 4
Line pull required = 6,000/4 = 1,500 lbs.
Lower block load = 6,000 lbs.
Required WLL = 6,000 lbs.

Upper block load = 6,000 + line pull + gear

6,000 + 1,500 + gear = 7,500 lbs. plus


Required WLL = 7,500 lbs. plus

Angle Factor Multipliers

A single line snatch block used to change load line direction can be subjected to total loads greatly different from the line pull.

Angle	Factor	Angle	Factor
0°	2.00	100°	1.29
10°	1.99	110°	1.15
20°	1.97	120°	1.00
30°	1.93	130°	.84
40°	1.87	135°	.76
45°	1.84	140°	.68
50°	1.81	150°	.52
60°	1.73	160°	.35
70°	1.64	170°	.17
80°	1.53	180°	.00
90°	1.41		

Total Load = Line Pull x Angle Factor Multiplier




SECTION 6: RIGGING AND CRANE

RIGGING INFORMATION Working With Blocks


Overhaul Weight

To determine the weight of the block or overhaul ball that is required to free fall the block, the following information is needed: size of wire rope, number of line parts, type of sheave bearing, length of crane boom, and drum friction.




Block Reeving

Straight laced reeving is a basic method of placing the rope through a set of blocks. The end of the rope is fed through the outside sheave of the upper block to the outside sheave of the lower (traveling) block. This continues to the last sheave.




Symmetrical Reeving

Reeve blocks symmetrically to distribute load evenly. All sheaves must be reeved to achieve the full working load limit of the block.




RIGGING INFORMATION Rigging with Blocks




Pull (P) required (level ground) = weight (W) x friction factor (f)

Many surfaces have a friction factor <1 (f) for steel on steel is .16 lubricated (f) for steel on steel is .8 clean (f) for wood on steel is .2 to .6 clean (f) for wood on wood is .25 to .5 clean



Winch pull required = weight x friction factor mechanical advantage



RIGGING INFORMATION Block and Sheave Inspection

At a minimum, examine the following inspection points and remove from service or correct before use:

- Excessive wear on pins or axles, rope grooves, side plates, bushings or bearings and end fittings
- Deformation in side plates, pins and axles, lifting attachment points and trunnions
- 3. Misalignment or wobble in sheaves
- Security of nuts, bolts, and other locking methods
- 5. Missing or loose snap rings on pins

- Excessive end play of sheave bearings on shaft, more than .031 clearance per sheave with bushing or straight roller bearings
- 7. Excessive swivel case clearance (more than .12" .18")
- Hook with deformation, corrosion of cook or nut threads, missing or defective latch
- Welding side plates with weld cracking or corrosion

Sheave Groove



"No daylight" between groove and gauge shows groove acceptable



"Daylight" between groove and gauge shows wear



Corrugated grooves accelerate wear of wire rope

Fleet Angle

Fleet Angle is the entrance and exit angles of the wire rope relative to the sheave.

Fleet Angle should be no more than 1-1/2 degrees to 2 degrees.



RIGGING INFORMATION Block Hook Inspection

Crosby Recommends as a Minimum:


- A visual inspection for cracks, nicks, wear, gouges and deformation as part of a comprehensive documented inspection program, should be conducted by trained personnel in compliance with the schedule in ANSI B30.10.
- For hooks used in frequent load cycles or pulsating load, or exposed to corrosive conditions (road salt, etc.) the hook and thread should be periodically inspected by Magnetic Particle or Dye Penetrant.

SCREW PIN SHACKLES

G-209 & S209 Style Screw Pin Anchor Shackles

	WORK-													TOLER	TOLERANCE
NOM. SIZE	ING	WEIGHT					DIM	DIMENSIONS (IN.)	Ç Z					f	-/+
(N)	LIMIT (T)*	(IBS.)	∢	8	U	۵	ш	ш	ŋ	I	-	٤	۵	v	∢
3/16	1/3	90.0	0.38	0.25	0.88	0.19	9.0	0.56	96.0	1.47	0.16	1.14	0.19	90.0	90.0
 1/4	1/2	0.1	0.47	0.31	1.13	0.25	0.78	0.61	1.28	1.84	0.19	1.43	0.25	90.0	90.0
5/16	3/4	0.19	0.53	0.38	1.22	0.31	0.84	0.75	1.47	2.09	0.22	1.71	0.31	0.06	90.0
3/8	-	0.31	99.0	0.44	1.44	0.38	1.03	16:0	1.78	2.49	0.25	2.02	0.38	0.13	90.0
91//	1-1/2	0.38	0.75	0.5	1.69	0.44	1.16	1.06	2.03	2.91	0.31	2.37	0.44	0.13	90.0
1/2	2	0.72	0.81	0.63	1.88	0.5	1.31	1.19	2.31	3.28	0.38	2.69	0.5	0.13	90.0
2/8	3-1/4	1.37	1.06	0.75	2.38	69.0	1.69	1.5	2.94	4.19	0.44	3.34	69.0	0.13	90.0
3/4	4-3/4	2.35	1.25	0.88	2.81	0.75	2	1.81	3.5	4.97	0.5	3.97	0.81	0.25	90.0
2/8	6-1/2	3.62	1.44	1	3.31	0.88	2.28	2.09	4.03	5.83	0.5	4.5	0.97	0.25	90.0
-	8-1/2	5.03	1.69	1.13	3.75	l	2.69	2.38	4.69	6.56	0.56	5.13	1.06	0.25	90.0
1-1/8	9-1/2	7.41	1.81	1.25	4.25	1.16	2.91	2.69	5.16	7.47	0.63	5.71	1.25	0.25	90.0
1-1/4	12	9.5	2.03	1.38	4.69	1.29	3.25	3	5.75	8.25	69.0	6.25	1.38	0.25	90.0
1-3/8	13-1/2	13.53	2.25	1.5	5.25	1.42	3.63	3.31	6.38	9.16	0.75	6.83	1.5	0.25	0.13
1-1/2	17	17.2	2.38	1.63	5.75	1.54	3.88	3.63	6.88	10	0.81	7.33	1.62	0.25	0.13
1-3/4	25	27.78	2.88	2	7	1.84	5	4.19	8.86	12.34	٦	9.06	2.25	0.25	0.13
2	35	45	3.25	2.25	7.75	2.08	5.75	4.81	9.97	13.68	1.22	10.35	2.4	0.25	0.13
2-1/2	55	85.75	4.13	2.75	2.75	2.71	7.25	5.69	12.87	17.84	1.38	13	3.13	0.25	0.25

NOTE: MAXIMUM PROOF LOAD IS 2.0 TIMES THE WORKING LOAD LIMIT. MINIMUM ULTIMATE STRENGTH IS 6 TIMES THE WORKING LOAD LIMIT.




SCREW PIN SHACKLES

G-210 & S210 Style Screw Pin Chain Shackles

IOM. SIZE	WORKING	WEIGHT					OIMENSI	OIMENSIONS (IN.)	~ _				TOLER	rolerance +/-
(; <u>Z</u>	LIMIT (T)*	(LBS.)	∢	В	υ	۵	ш	ш	v	×	-	٤	υ	∢
1/4	1/2	11.0	0.47	0.31	0.25	0.25	0.97	0.62	0.97	1.59	0.19	1.43	90.0	90.0
91/9	3/4	0.17	0.53	0.38	0.31	0.31	1.15	0.75	1.07	1.91	0.22	1.71	90.0	90.0
3/8	-	0.28	99.0	0.44	0.38	0.38	1.42	0.92	1.28	2.31	0.25	2.02	0.13	90.0
91//	1-1/2	0.43	0.75	0.5	0.44	0.44	1.63	1.06	1.48	2.67	0.31	2.37	0.13	90.0
1/2	2	0.59	0.81	0.63	0.5	0.5	1.81	1.18	1.66	3.03	0.38	2.69	0.13	90.0
2/8	3-1/4	1.25	1.06	0.75	0.63	0.63	2.32	1.5	2.04	3.76	0.44	3.34	0.13	90.0
3/4	4-3/4	2.63	1.25	0.88	18'0	0.75	2.75	1.81	2.4	4.53	0.5	3.97	0.25	90.0
8//	6-1/2	3.16	1.44	١	0.97	0.88	3.2	2.1	2.86	5.33	0.5	4.5	0.25	90.0
_	8-1/2	4.75	1.69	1.13	_	-	3.69	2.38	3.24	5.94	0.56	5.13	0.25	90.0
1-1/8	9-1/2	9.75	1.81	1.25	1.25	1.13	4.07	2.69	3.61	6.78	0.63	5.71	0.25	90.0
1-1/4	12	90'6	2.03	1.38	1.38	1.25	4.53	е	3.97	7.5	69.0	6.25	0.25	0.13
1-3/8	13-1/2	11.63	2.25	1.5	1.5	1.38	5.01	3.31	4.43	8.28	0.75	6.83	0.25	0.13
1-1/2	17	15.95	2.38	1.63	1.62	1.5	5.38	3.62	4.84	9.05	0.81	7.33	0.25	0.13
1-3/4	25	26.75	2.88	2	2.12	1.75	6.38	4.19	5.78	10.97	١	90.6	0.25	0.13
2	35	42.31	3.25	2.25	2.36	2.1	7.25	5	6.77	12.74	1.13	10.35	0.13	0.25
2-1/2	55	71.75	4.12	2.75	2.63	2.63	9.38	5.68	8.07	14.85	1.38	13	0.25	0.25
TE. BAA VII	FIRST CAN CONTRACT TO CONTRACT	0000	LIE STANIE	Ya Ow	0	1								

NOTE: MAXIMUM PROOF LOAD IS 2.0 TIMES THE WORKING LOAD LIMIT. MINIMUM ULTIMATE STRENGTH IS 6 TIMES THE WORKING LOAD LIMIT.



SECTION 6: RIGGING AND CRANE

NOTES

ANSI BOLTING CHART 1/2" – 4"

PRES- SURE	BOLTING	FLANGE				ا	NORMAL	PIPE SIZE	Ē			
RATING		FACING	1/2	3/4	1	11/4	11/2	2	21/2	3	31/2	4
	Number		4	4	4	4	4	4	4	4	8	8
	Diameter		1/2	1/2	1/2	1/2	1/2	5/8	5/8	5/8	5/8	5/8
150 Pound	Length of	1 1/16 RF	2 1/2	2 1/2	2 3/4	2 3/4	3	3 1/4	3 1/2	3 3/4	3 3/4	3 3/4
	Stud Bolts	RTJ	-	-	3 1/4	3 1/4	31/2	3 3/4	4	41/4	41/4	41/4
	Ring Size	R	-	-	15	17	19	22	25	29	33	36
	Number		4	4	4	4	4	8	8	8	8	8
300 Pound 400 Pound	Diameter		1/2	5/8	5/8	5/8	3/4	5/8	3/4	3/4	3/4	3/4
	Length of	1/16 RF	2 3/4	3	3 1/4	3 1/4	3 3/4	31/2	4	41/4	41/2	41/2
	Stud Bolts	RTJ	3 1/4	31/2	3 3/4	3 3/4	41/4	41/4	4 3/4	5	5 1/4	5 1/4
	Rina Size	R	11	13	16	18	20	23	26	31	34	37
	King Size	RX	-	-	-	-	20	23	26	31	34	37
	Number		4	4	4	4	4	8	8	8	8	8
	Diameter		1/2	5/8	5/8	5/8	3/4	5/8	3/4	3/4	7/8	7/8
	Length of	1/4 RF	3 1/4	3 1/2	3 3/4	4	41/4	41/4	4 3/4	5	51/2	51/2
	Stud Bolts	RTJ	3 1/4	31/2	3 3/4	4	41/4	41/2	5	5 1/4	5 3/4	5 3/4
	Ring	R	11	13	16	18	20	23	26	31	34	37
	Size	RX	-	-	-	-	20	23	26	31	34	37
	Number		4	4	4	4	4	8	8	8	8	8
	Diameter		1/2	5/8	5/8	5/8	3/4	5/8	3/4	3/4	7/8	7/8
600	Length of	1/4 RF	3 1/4	31/2	3 3/4	4	41/4	41/4	43/4	5	51/2	5 3/4
Pound	Stud Bolts	RTJ	3 1/4	31/2	3 3/4	4	41/4	41/2	5	5 1/4	5 3/4	6
	Ring	R	11	13	16	18	20	23	26	31	34	37
	Size	RX	-	-	-	-	20	23	26	31	34	37

ANSI BOLTING CHART 5" - 24"

PRES-		FLANGE				ı	NORMAL	PIPE SIZE				
SURE RATING	BOLTING	FACING	5	6	8	10	12	14	16	18	20	24
	Number		8	8	8	12	12	12	16	16	20	20
	Diameter]	3/4	3/4'	3/4	7/8′	7/8'	1	1	11/8	11/8	11/4
150 Pound	Length of	11/16 RF	4	4	4 1/4	43/4	43/4	5 1/4	51/2	6	61/4	7
Tourid	Stud Bolts	RTJ	41/2	41/2	41/2	5 1/4	51/4	5 3/4	6	61/2	63/4	71/2
	Ring Size	R	40	43	48	52	56	59	64	68	72	76
	Number		8	12	12	16	16	20	20	24	24	24
	Diameter		3/4	3/4	7/8'	1	11/8	11/8	11/4	11/4	11/4	11/2
300	Length of	1/4 RF	43/4	5	51/2	61/4	6 3/4	7	71/2	7 3/4	8 1/4	9 1/4
Pound	Stud Bolts	RTJ	51/2	5 3/4	61/4	7	71/2	7 3/4	8 1/4	8 1/2	9	101/4
	Ring Size	R	41	45	49	53	57	61	65	69	73	77
	King Size	RX	41	45	49	53	57	61	65	69	73	77
	Number		8	12	12	16	16	20	20	24	24	24
400	Diameter		7/8	7/8	1	11/8	11/4	11/4	13/8	13/8	11/2	13/4
Pound	Length of	1/4 RF	53/4	6	6 3/4	71/2	8	8 1/4	8 3/4	9	93/4	103/4
	Stud Bolts	RTJ	6	61/4	7	73/4	81/4	8 1/2	9	91/4	10	11 1/4
600 Pound 900 Pound	Number		8	12	12	16	20	20	20	20	24	24
	Diameter		1	1	11/8	11/4	11/4	13/8	11/2	15/8	15/8	17/8
	Length of	1/4 RF	61/2	6 3/4	7 3/4	8 1/2	8 3/4	9 1/4	10	103/4	11 1/2	13
	Stud Bolts	RTJ	63/4	7	8	83/4	9	91/2	10 1/4	11	11 3/4	131/2
	Ring	R	41	45	49	53	57	61	65	69	73	77
	Size	RX	41	45	49	53	57	61	65	69	73	77
	Number		8	12	12	16	20	20	20	20	20	20
	Diameter		11/4	11/8	13/8	13/8	13/8	11/2	15/8	17/8	2	21/2
	Length of	1/4 RF	71/2	7 3/4	8 3/4	9 1/4	10	10 3/4	11 1/4	13	13 3/4	17 1/4
	Stud Bolts	RTJ	73/4	7 3/4	9	91/2	10 1/4	11 1/4	11 3/4	13 1/2	14 1/4	18
	Ring	R	41	45	49	53	57	62	66	70	74	78
	Size	RX	41	45	49	53	57	62	66	70	74	78
	Number		8	12	12	12	12	16	16	16	16	16
	Diameter		11/2	13/8	15/8	1 7/8	2	2 1/4	21/2	2 3/4	3	31/2
1500	Length of	1/4 RF	93/4	10 1/4	11 1/2	131/2	15	16 1/4	17 3/4	191/2	21 1/4	241/4
Pound	Stud Bolts	RTJ	10	101/2	12	13 3/4	15 1/2	17	18 3/4	201/2	221/2	251/2
	Ring	R	44	46	50	54	58	63	67	71	75	79
	Size	RX	44	46	50	54	58	63	67	71	75	79
	Number		8	12	12	12	12	-	-	-	-	-
	Diameter		13/4	2	2	21/2	2 3/4	-	-	-	-	-
2500	Length of	1/4 RF	11 3/4	13 3/4	15 1/4	19 1/4	21 1/4	-	-	-	-	-
Pound	Stud Bolts	RTJ	121/2	14 1/4	153/4	201/4	221/4	-	-	-	-	-
	Ring	R	42	47	51	55	60	-	-	-	-	-
	Size	RX	42	47	51	55	60	-	-	-	-	-

UPS Industrial Services

806 Seaco Court Deer Park, Texas 77536 281-479-6000 info@universalplant.com

